

BIDDING DATA

(This section should be filled in by the Engineer / Procuring Agency before issuance of the Bidding Documents)

- a) Name of Procuring Agency:-DIGP West Zone Karachi.
- b) Brief Description of Work: Repair / Renovation Conversion of Barrack into at of HQtr West at Naval Colony
- c) Procuring Agency 's Address : DIGP West Zone Karachi(Gulberg Karachi) .
- d) Estimate Cost :-Rs.76,00000/-
- e) Amount of Bid Security: Rs.1,52,000/-.
- f) Period of Bid Validity (days) :60 days.
- g) Security Deposit including bid security:3,80000/- (in % age of bid amount / estimated cost equal to 5%).
- h) Percentage , if any , to be deducted from bills: According to Rule
- i) Deadline for Submission of Bids along with time:10-11-2014 AT 1400 hours
- j) Venue , Time ,and Date of Bid Opening: Conference Room of DIGP West Zone at 1400 hours dated 10-11-2014.
- k) Time for completion from written order of commence: 60 Days.
- l) Liquidity damages:2 % (o.5 of Estimated Cost or Bid cost per day of delay , but total not exceeding 10%).
- m) Deposit Receipt No: Date :Amount (in word and figures)Receipt No.
Dated: Rs. 3,80000/- (Three Lac Eighty Thousand Only.

(Executive Engineer /Authority issuing bidding documents)

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

S.#	DESCRIPTION	QTY	RATE	UNIT	AMOUNT
1	Dismantling of R.C.C Chajja	704	30	P.SFT.	21120
2	Dismantling of Block masonry Wall	1386	20	P.SFt	27720
3	Removing of Doors	11	500	Each	5500
4	Removing of windows	55	200	Each	11000
5	Providing and laying 1:2½ cement concrete solid block masonry set in 1:2½ cement sand mortar in raking our joints and curing etc. complete. (Ground to 2 nd floor)	11295	110	P.Cft	1242450
6	Providing and Fixing RCC Lanter (Fix on Doors) 5-0 long	77	950	Each	73150
7	Cement Plaster 1:2½ (Ground floor to 2 nd floor)	23528	25	P.SFT	588200
8	P/F in position, doors windows and ventilators of first class GI frames, and 1 1/2" thick commercial, ply shatter of first class skeleton solid and commercial ply wood (3 ply) on both side, including hole pass hinges iron tower bolts, handles and cleats with cord and one mortise lock and hooks.	1300	550	P.SFT	715000

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

9	P / L Marble tiles 12" X 12" 1/2" on floor facing in required colour and pattern of joint in white cement and pigment over a base of 1:2 grey Cement mortar 3/8" thick including washing and filling of joints with slurry of white cement and pigment in desired shape with finishing cleaning and grinding & polishing etc. complete including cutting tiles to proper profile.	8708	125	P.SFT	1088500
10	P / L Bathroom Glaze tiles 13" X 10" 1/4" on floor facing in required colour and pattern of joint in white cement and pigment over a base of 1:2 grey Cement mortar 3/8" thick including washing and filling of joints with slurry of white cement and pigment in desired shape with finishing cleaning etc. complete including cutting tiles to proper profile.	3700	150	P.SFT	555000
11	Providing & Fixing Kitchen Cabinet Lasani Sheet including Hanges & Tower Bolt Wooden Frame & Labour Charges	330	650		214500
12	Providing & Fixing Kitchen Marble Top & Labour Charges (1" Thick)	69	550	P.SFT	37950

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

13	A) Preparing the surface and painting with Distemper including rubbing the surface with Bathy (Silicon carbide rubbing brick) filling the voices with Zink / Chalk / Plaster of Paris mixture, Appling 03 coats with Distemper of approved make etc.	75874	13	P.SFT	986362
14	Painting Doors & Windows	2749	20	P.SFT	54980
15	P/F WC Pan complete with including the cost of white black plastic seat and lid with C.P. brass binges & buffers. 3 Gallons white glassed earthen were low level flushing cistern with siphon fitting 1 1/2 “ dia with porcelain enameled flush ben 3/4” dia and making requisite num ber of holes in walls. plinth and floor for pipe connections and making good in cement concrete 1:2:4 (foreign quality)	22	3500	each	77000
16	P/F 22” X 16 “ labortry basin in white glazed earthen were complete with and i/c the cost of IW or C.I cantilever brackets 6” built into walls, painted white in two coats after a primary cost of red lead paint a pair of 1/2” dia chrome platter pillar taps.	22	2200	each	48400

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

17	P/F 6" v /2" or 6" X 3" UPVC floor trap o f the approved self cleaning design with a screwed down gritting with or without a vent arm complete with and including making requisite number of holes in walls plnth and floor for pipe connections and making good in CC1:2:4.	22	1100	each	24200
18	P / F CP stop cock ½" dia approved quality.	44	750	each	33000
19	Providing and fixing bib Cock ½ dia approved quality etc. Complete	22	850	each	18700
20	Construction of Main hole inspection chamber 1.5 X 1.5 X 18 up to required depth including excavation C.C 1:4:8 Sq.ft. bare then 1:3:6 block masonry inside and outside plaster 1:4 ¾ thick CC including Main hole cover.	16	3500	Each	56000
21	Construction of chamber 1.50 X 1.50 X 1.50 4 Nos required depth including excavation C.C 1:4:8 Sq.ft. bare then 1:2½ block masonry including inside and outside plaster 1:4 ¾ thick CC topping 2" thick and making channel including chamber cover..	14	2500	Each	35000
22	P/Fixing Shower approved quality	22	950	Each	20900
23	P/Fixing Steel Sink approved quality	11	3500	Each	38500

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

24	P / F U-PVC piper approved duality including fitting 4' dia and labour charges etc complete.	165	390	P.RFT	64350
25	P / F U-PVC piper approved duality including fitting 3' dia and labour charges etc complete.	184	370	P.RFT	68080
26	P / F U-PVC piper approved duality including fitting 6' dia and labour charges etc complete.	300	550	P.RFT	165000
27	P / F U-PVC Pipe approved quality including fitting 1' dia and labour charges etc complete.	859	250	P.RFT	214750
28	P / F U-PVC pipe approved quality including fitting 3'/4' dia and labour charges etc complete.	435	180	P.RFT	78300
29	Wiring for light of fan point with 1/1 12(3/29) PVC insulated wire including PVC Fitting Under Ground fancy switch 15 AMP including holder, complete. approved quality.	200	720	each	144000
30	P / F energy sever including fixing on existing holder etc, complete. approved quality	115	350	each	40250
31	Wiring for Main with 2-3-29 including concold fitting & Labour Charges	227	90	P.RFT.	20430
32	Wiring for Main with 2-7-44 including channel concold fitting & Labour Charges	500	200	P.RFT.	100000

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
ROUGH COST ESTIMATE**

33	Wiring for Main with 2-7-36 including channel concold fitting & Labour Charges	390	120	P.RFT.	46800
34	P/Fixing Circuit Braker 10 AMP approved quality including electric connection	22	1200	Each	26400
35	P/Fixing Circuit Braker 30 AMP approved quality including electric connection	3	6000	Each	18000
36	P/Fixing Iron Panel Board fix on wall including electric connection	44	1100	P.SFT.	48400
37	Providing and fixing Almunium window of approved quality with 5 m.m thick liminated Glass complete with fly proof shutter etc complete	734	550	P.SFT	403700
38	Providing and layiing R.C.C 1:2:4 slab 4" thick including form work and including cost of reinforcement	396	250	P.SFT	99000
39	Providing and fixing of Square bar Grill 3/8"X3/8" 4" c/o fixing with screw drilling complete as per requirement only for Ground floor windows / ventilators	298	300	P.SFT	89400
GRAND TOTAL					7599992

Sub Engeneer

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SHEDULE BOOK DOCUMENT**

S.#	DESCRIPTION	QTY	RATE	UNIT	AMOUNT
1	Dismantling of R.C.C Chajja	704		P.SFT.	
2	Dismantling of Block masonry Wall	1386		P.SFt	
3	Removing of Doors	11		Each	
4	Removing of windows	55		Each	
5	Providing and laying 1:2½ cement concrete solid block masonry set in 1:2½ cement sand mortar in raking our joints and curing etc. complete. (Ground to 2 nd floor)	11295		P.Cft	
6	Providing and Fixing RCC Lanter (Fix on Doors) 5-0 long	77		Each	
7	Cement Plaster 1:2½ (Ground floor to 2 nd floor)	23528		P.SFT	
8	P/F in position, doors windows and ventilators of first class GI frames, and 1 1/2” thick commercial, ply shatter of first class skeleton solid and commercial ply wood (3 ply) on both side, including hole pass hinges iron tower bolts, handles and cleats with cord and one mortise lock and hooks.	1300		P.SFT	

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SHEDULE BOOK DOCUMENT**

9	P / L Marble tiles 12" X 12" 1/2" on floor facing in required colour and pattern of joint in white cement and pigment over a base of 1:2 grey Cement mortar 3/8" thick including washing and filling of joints with slurry of white cement and pigment in desired shape with finishing cleaning and grinding & polishing etc. complete including cutting tiles to proper profile.	8708		P.SFT	
10	P / L Bathroom Glaze tiles 13" X 10" 1/4" on floor facing in required colour and pattern of joint in white cement and pigment over a base of 1:2 grey Cement mortar 3/8" thick including washing and filling of joints with slurry of white cement and pigment in desired shape with finishing cleaning etc. complete including cutting tiles to proper profile.	3700		P.SFT	
11	Providing & Fixing Kitchen Cabinet Lasani Sheet including Hanges & Tower Bolt Wooden Frame & Labour Charges	330			
12	Providing & Fixing Kitchen Marble Top & Labour Charges (1" Thick)	69		P.SFT	

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SHEDULE BOOK DOCUMENT**

13	A) Preparing the surface and painting with Distemper including rubbing the surface with Bathy (Silicon carbide rubbing brick) filling the voices with Zink / Chalk / Plaster of Paris mixture, Appling 03 coats with Distemper of approved make etc.	75874		P.SFT	
14	Painting Doors & Windows	2749		P.SFT	
15	P/F WC Pan complete with including the cost of white black plastic seat and lid with C.P. brass binges & buffers. 3 Gallons white glassed earthen were low level flushing cistern with siphon fitting 1 1/2 “ dia with porcelain enameled flush ben 3/4” dia and making requisite num ber of holes in walls. plinth and floor for pipe connections and making good in cement concrete 1:2:4 (foreign quality)	22		each	
16	P/F 22” X 16 “ labortry basin in white glazed earthen were complete with and i/c the cost of IW or C.I cantilever brackets 6” built into walls, painted white in two coats after a primary cost of red lead paint a pair of 1/2” dia chrome platter pillar taps.	22		each	

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SHEDULE BOOK DOCUMENT**

17	P/F 6" v /2" or 6" X 3" UPVC floor trap o f the approved self cleaning design with a screwed down gritting with or without a vent arm complete with and including making requisite number of holes in walls plnth and floor for pipe connections and making good in CC1:2:4.	22		each	
18	P / F CP stop cock ½" dia approved quality.	44		each	
19	Providing and fixing bib Cock ½ dia approved quality etc. Complete	22		each	
20	Construction of Main hole inspection chamber 1.5 X 1.5 X 18 up to required depth including excavation C.C 1:4:8 Sq.ft. bare then 1:3:6 block masonry inside and outside plaster 1:4 ¾ thick CC including Main hole cover.	16		Each	
21	Construction of chamber 1.50 X 1.50 X 1.50 4 Nos required depth including excavation C.C 1:4:8 Sq.ft. bare then 1:2½ block masonry including inside and outside plaster 1:4 ¾ thick CC topping 2" thick and making channel including chamber cover..	14		Each	
22	P/Fixing Shower approved quality	22		Each	
23	P/Fixing Steel Sink approved quality	11		Each	
24	P / F U-PVC piper approved duality including fitting 4' dia and labour charges etc complete.	165		P.RFT	

**NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SHEDULE BOOK DOCUMENT**

25	P / F U-PVC piper approved duality including fitting 3' dia and labour charges etc complete.	184		P.RFT	
26	P / F U-PVC piper approved duality including fitting 6' dia and labour charges etc complete.	300		P.RFT	
27	P / F U-PVC Pipe approved quality including fitting 1' dia and labour charges etc complete.	859		P.RFT	
28	P / F U-PVC pipe approved quality including fitting 3'7/4' dia and labour charges etc complete.	435		P.RFT	
29	Wiring for light of fan point with 1/1 12(3/29) PVC insulated wire including PVC Fitting Under Ground fancy switch 15 AMP including holder, complete. approved quality.	200		each	
30	P / F energy sever including fixing on existing holder etc, complete. approved quality	115		each	
31	Wiring for Main with 2-3-29 including concold fitting & Labour Charges	227		P.RFT.	
32	Wiring for Main with 2-7-44 including channel concold fitting & Labour Charges	500		P.RFT.	
33	Wiring for Main with 2-7-36 including channel concold fitting & Labour Charges	390		P.RFT.	
34	P/Fixing Circuit Braker 10 AMP approved quality including electric connection	22		Each	
35	P/Fixing Circuit Braker 30 AMP approved quality including electric connection	3		Each	
36	P/Fixing Iron Panel Board fix on wall including electric connection	44		P.SFT.	

NAME OF WORK REPAIR / RENOVATION / OF POLICE FAMILY QUARTER EXISTING BARRACKS IN
POLICE HEADQUARTER NAVAL COLONY WEST ZONE KARACHI.
SCHEDULE BOOK DOCUMENT

37	Providing and fixing Aluminium window of approved quality with 5 m.m thick laminated Glass complete with fly proof shutter etc complete	734		P.SFT	
38	Providing and laying R.C.C 1:2:4 slab 4" thick including form work and including cost of reinforcement	396		P.SFT	
39	Providing and fixing of Square bar Grill 3/8"X3/8" 4" c/o fixing with screw drilling complete as per requirement only for Ground floor windows / ventilators	298		P.SFT	
GRAND TOTAL					

Estimate cost 7.6 million

Sub Engineer