

KARACHI WATER & SEWERAGE BOARD

OFFICE OF THE CHIEF ENGINEER (IP&D)

BID EVALUATION REPORT

1	Name of Procuring Agency	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No	SPPRA Serial No.17502 I.D No. /2013
3	Tender Description/Name of Work/Item	REPAIRING OF 12" DIA PRCC WATER LINE AT OPPOSITE DHOBI GHAT PUMPING STATION FOR THE IMPROVEMENT WATER SUPPLY IN ADJACENT AREA OF LYARI TOWN (WATER).
4	Method of Procurement	Single Stage (One Envelop)
5	Tender Published	Through Web Site
6	Total Bid Documents Sold	2 Nos
7	Total Bid Received	2 Nos
8	Technical Bid Opening Date (if applicable)	N/A .
9	No. of Bid Technically Qualified (if applicable)	N/A.
10	Bid (s) rejected	Nil
	Financial Bid Opening Date	24/10/2013

12 Bid Evaluation Report

S#)IE OF FIRM OR BIDDER	COST OFFERED BY THE BIDDERS	RANKING IN TERMS OF COST	COMPARISON WITH ESTIMATED COST	REASON FOR ACCEPTANCE/ REJECTION	REMARKS
1	M/	s. S.Qayyum & Sons	Rs. 993,076/-	1st Lowest	@ 0.1015% Below	Substantially Responsive	P.O # 7466171 Dt: 23/10/2013 Rs 20,000/- UBL Rashid Minhas Road Br
2	M/	s. H.R Brothers	Rs. 1,003,889/-	2nd Lowest	@ 0.9862% Above	Un-Responsive bid due to 2% P.O are Short	P.O # 8399395 Dt: 20/05/2013 Rs 20,000/- HBL Malir Cant.Br

The all concerned bidder are being informed accordingly.

The E.E. Concerned for compliance of rule 45 of SPPRA 2010 M/s. Qayyum & Sons declared as the lowest responsive bidder by the Committee and recommended for Sanction from Competent Authority.

(Muhammad Nawaz Khan) Accounts Officer (South) Member/Secretary (Saif-ul-Haque) Additional Director Internal Audit - KMC Member (Maqsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

(Muhammad Arif) Chief Engineer (South) Member (Abdul Rahim Khatti) Chief Engineer (IPD), (Convener)

COMPARATIVE STATEMENT

NAME OF WORK: REPAIRING OF 12" DIA PRCC WATER LINE AT OPPOSITE DHOBI GHAT PUMPING STATION FOR THE IMPROVEMENT WATER SUPPLY IN ADJACENT AREA OF LYARI TOWN (WATER).

T	•	ω		N	-		2
15" Dia Net weight 65 26 Kgs	Repairing & Fixing MS tall piece on PRCC pipe fabricated with 3/8 thick MS plate both caulking and reducer ends 9" wide provide with %" thick square bar at caulking end having at total weight as mentioned against each item. It in includes the cost of labour and caulking & sealing material etc complete. 12" Dia Net weight 51.81 Kgs	Full hire charges of pumping set i/c wages of driver and Assistant fuel or electric energy plate form required for placing or at lower depths with suction and delivery pipes for pumping and water found at carious depth form trenches i/c cost of erection and dismantling after completion of the job. (i) Hire charges of pumping set of upto 10 H.P pumping out water for 10 feet deep trench	up to 5' to 8'	Excavation for pipe line in trenches & pits in all kind of soil of muram i/c trimming and dressing sides to the true alignment & shape leveling of beds of trenches to correct level and grade cutting joints holes & disposal of surplus earth with in a one chain as directed by Engineer Incharge providing fence guard light flag, and temporary crossing for non-vehicle traffic where ever required lift up to 5ft (1.52m) and lead up to on chain (30.5m) up to 0" to 5"	Dismantling and removing road mantling		Description of Work
1 No	2 00		2270.7 Cft		1624 Cft	Quantity	
11,591,00	9,438.00		5,200.00	4,650.00	605.00	Rate	Engineer's Estimate
Each	Each	P/Day	% 0 Cft	% 0 Cft	% Cft	Unit	Estimate
11,591.00	18,876.00	21,000.00	11,807.64	38,688.00	9,825.20	Amount	
11,500.00	9,430.00	1,500.00	5,200.00	4,645.00	604.00	Rate	M/s. S.Qay
11,500.00	18,860.00	21,000.00	11,807.64	38,646.40	9,808.96	Amount	M/s. S.Qayyum & Sons
13,000.00	9,435.00	2,000.00	5,250.00	4,650.00	608.00	Rate	M/s. H.R
13,000,00	18,870.00	28.000.00	11,921.18	38,688.00	9,873.92	Amount	M/s. H.R Brothers

110/20/5/ Jahan

NAME OF WORK: REPAIRING OF 12" DIA PRCC WATER LINE AT OPPOSITE DHOBI GHAT PUMPING STATION FOR THE IMPROVEMENT WATER SUPPLY IN ADJACENT AREA OF LYARI TOWN (WATER).

1			7	o	© CO		S.No
18"dia	Repair of I eaking joints (External varia) on PRCC pipe of various diamete it i/c the cost of excavation, labor, sealing materia I gunny bags de-watering and refilling of the excavated stuff etccomplete 12"dia.	18" Dia Net weight 102.88 Kgs	P/F MS split collar on PRCC pipe, 18" wide fabricated with 3/8" thick MS plate 1 Y4" wide 3/8" thick- ring and ce.nter.3/4" thick MS square bar on both ends with a total weight as mentioned _against each item. it includes the cost of 4 Nos- 3/4" thick flanges, nuts,& bolts rubber packing labour and the sealing material 12" Dia Net weight 80.88 Kgs	Manufacturing Supplying and fixing. black Steel MS pipe made out of MS Sheet conforming to APL grade X-42. ERW and externally as phalt coaled with fib ring less 5.6 mm thick internally 8mm thick (AVVVA) Specification I/c with Helical -welding in trenches I/c th.e cost of bends of any degree': 8 testing with water specification pressure for different dia of pipe as below 5:6 mm thick.	Providing Laying and jointing, P.E pipe in trenches i/c fitting, jointing and testing etc complete in all respect HOPE-100) for conforming ISO 4427/DIN 8074/8075 B:S 3580 & PSI 3051 (PN-10). 315MM		Description of Work
2 Nos	1 Nos	3 Nos	1 Nos	25 Rt	340 Rft	Quantity	
13,841.00	9,716.00	19,769.00	15,572.00	2,458.81	1,998.00	Rate	Engineer's Estimate
Each	Each	Each	Each	PIRE	P/Rft	Unit	Estimate
27,682.00	9,716.00	59,307.00	15,572.00	61,470.25	679,320.00	Amount	
13,840.00	9,715.00	19,750.00	15,550.00	2,455.50	1,996.00	Rate	M/s. S.Qay
27,680.00	9,715.00	59,250.00	15,550.00	61,387.50	678,640.00	Amount	M/s. S.Qayyum & Sons
14.000.00	9,725.00	19,770.00	16,000.00	2,460.20	1,989.00	Rate	M/s. H.R
28,000.00	9,725.00	59,310.00	16,000.00	61,505,00	679,660.00	Amount	M/s. H.R Brothers

1 2 /2 /2 / 2 W

NAME OF WORK: REPAIRING OF 12" DIA PRCC WATER LINE AT OPPOSITE DHOBI GHAT PUMPING STATION FOR THE IMPROVEMENT WATER SUPPLY IN ADJACENT AREA OF LYARI TOWN (WATER).

S.No	Description of Work	Orașilio	Enginee	o o	Engineer's Estimate	77.783	Amount	M/s. S.Qayyu	M/s. S.Qayyum & Sons
	6 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Quantity	Rate	Unit	-	Amount		Amount	Amount Rate
9	Refilling the excavated stuff in trenches 6" th i/c layer including watering ramming to full compaction etc. complete	10590.70 Cft	2,760.00 % O Cft	% o cn		29,230.33		29,230.33	29,230.33 2,760.00
	A Cost Cost and Cost and Cost Cost Cost Cost Cost Cost Cost Cost		$\overline{}$		$\overline{}$	994,085.42		9	
	Say					994,085	994,085	994,085 993,076	

Member/Secretary

(Muhammad Nawaz Khan) Accounts Officer (South)

(Muhammad Arif) Chief Engineer (South) Member

(Saif-ul-Haque)
Additional Director Internal
Audit - KMC Member

(Abdul Rahim Khatti) Chief Engineer (IPD), (Convener)

(Magsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member