CIVIL HOSPITAL KARACHI

NIT NO. INF/KRY-2244/17 SPPRA ID @ S. No. 32946

Method and procedure of procurement: (Single Stage - One Envelope)

MINUTES OF BID OPENING MEETING

A meeting of the procurement committee of this department was held on 11-05-2017 for opening the bids received in respect of subject NIT for Maintenance & Repair of Machinery Equipment at Civil Hospital Karachi till the deadlines of submission. The meeting was attended by following members of the procurement committee and the representative of bidders. (Attendance sheet is enclosed).

The following bidders submitted their bids till the deadline of submission:

- 1) M/s. Zam Trading Co.
- 2) M/s. Field Supplies
- 3) M/s. Health Tech Pakistan
- 4) M/s. Comvare
- 5) M/s. Perfect Power & Engineering Solution
- 6) Life One

The bids were opened at 12:00 noon in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee. All the members of the procurement committee signed each and every page of financial proposal / bids. The bids do not contain any over-writing or cutting.

Following is the details of bids announced:

S. No.	Item name	Name of Bidders	Offered Price	Amount of Bid Security	Pay Order No. / Dated
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex	NQ	NQ	NQ	NQ
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit -I	NQ	NQ	NQ	NQ

CIVIL HOSPITAL KARACHI.

W Owe

S. No.	Item name	Name of Bidders	Offered Price	Amount of Bid Security	Pay Order No. / Dated
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit - I	NQ	NQ	NQ	NQ
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit - I	NQ	NQ	NQ	NQ
	Repair of Ultrasound Machine @ Radiology Department	M/s. Zam Trading Co.	Rs. 796,000/-	Rs. 15,920/-	13444376 10-05-2017
5	Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	M/s. Health Tech Pak	Rs. 810,000/-	Rs. 16,200/-	10855137 10-05-2017
6	Repair of Ultrasound Machine @ Radiology Department	M/s. Zam Trading Co.	Rs. 555,100/-	Rs. 11,800/-	13444373 10-05-2017
0	Model: S11 Make: Sono Scape Replacement of 1x DBF PCB	M/s. Life One	Rs. 590,000/-	Rs. 11,102/-	03350901 11-05-2017
	Repair of UPS 50KW @ Radiology Department	M/s. Life One	Rs. 3,599,970/-	Rs. 72,000/-	03350902 11-05-2017
7	Replacement require of batteries Replacement require of Invertors Replacement require of power bank	M/s. Comvare	Rs. 3,975,000/-	Rs. 79,500/-	03350906 11-05-2017
8	Repair of C. Arm Machine @ Ortho O.T	M/s. Zam Trading Co.	Rs. 216,000/-	Rs. 4,320/-	13444374 10-05-2017
0	Make:- Siemens	M/s. Comvare	Rs. 216,220/-	Rs. 4,325/-	03350905 11-05-2017
9	Repair of Syringes Pump @ Surgical ICU	M/s. Life One	Rs. 424,000/-	Rs. 8,400/-	03350903 11-05-2017
		M/s. Health Tech Pak	Rs. 500,000/-	Rs. 10,000/-	10855139 10-05-2017
10	Repair of Defibrillator @ C.C.U	M/s. Health Tech Pak	Rs. 390,000/-	Rs. 7,800/-	10855138 10-05-2017
10		M/s. Zam Trading Co.	Rs. 402,500/-	Rs. 8,050/-	13444375 10-05-2017
11	Repair / Replacement of Ultrasound Probe @ Surgical ICU	M/s. Field Supplies	Rs. 801,000/-	Rs. 16,020/-	10855140 10-05-2017
11		M/s. Life One	Rs. 830,000/-	Rs. 16,600/-	03350904 11-05-2017
12	Repair of 730KVA F.G. Wilson DG Set @ CHK	M/s. Perfect Power	Rs. 1,5000,000/-	Rs. 30,000/-	13444394 11-05-2017
		(*)	121	(w)	-
13	Repair of Rotofix Centrifuge Machine @ Central Lab	NQ	NQ	NQ	NQ

The committee shall examine all the bids as per the Qualification/ eligibility criteria provided in the bidding documents, arithmetical checks and verify the documents and bid security submitted by the bidders.

The meeting ended with the note of thanks to and from the chair.

ACCOUNTS OFFICER

M

Tyrns



CIVIL HOSPITAL KARACHI

Statement showing the Comparative rates for the "Maintenance & Repair of the Machinery Equipments at Civil Hospital Karachi quoted by the various firms vide Tender Enquiry No. AMS (Tech)/-12824/26 Dated 24-04-2017 Published in Daily "Jang" Dated 26th April' 2017 and hoisted on SPPRA website @ Sr. No. 32946

Technical / Financial opened on 11th May' 2017

Item No.	Descriptions of Works	Qty	Name of Firm & & Rate Quoted	Name of Firm & Rate Quoted	Name of Firm & Rate Quoted	Ramarks
Ĭ	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698	01	NQ	NQ	NQ	NQ
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit –I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	NQ	NQ	NQ	NQ
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V	01	NQ	NQ	NQ	NQ
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit - I Model: CF-180AL	01	NQ	NQ	NQ	NQ
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba	01	M/s. Zam Trading Co. Rs. 796,000/-	M/s. Health Tech Pak Rs. 810,000/-	2	On Lowest Basis
6	Repair of Ultrasound Machine @ Radiology Department Model: S11 Make: Sono Scape	01	M/s. Zam Trading Co. Rs. 555,100/-	M/s. Life One Rs. 590,000/-		On Lowest Basis
7	Repair of UPS 50KW @ Radiology Department Replacement require of batteries Replacement require of invertors Replacement require of power bank	03	M/s. Life One Rs. 3,599,970/-	M/s. Comvare Rs 3,975,000/-	Si Si	On Lowest Basis
8	Repair of C. Arm Machine @ Ortho O.T Make:- Siemens	01	M/s. Zam Trading Co. Rs. 216,000/-	M/s. Comvare Rs. 216,220/-	æ	On Lowest Basis
9	Repair of Syringes Pump @ Surgical ICU Make:- B. Braun	02	M/s. Life One Rs. 424,000/-	M/s. Health Tech Pak Rs. 500,000/-	i a .	On Lowest Basis
10	Repair of Defibrillator @ C.C.U Sector Probe Make:- G.E	01	M/s. Health Tech Pak Rs. 390,000/-	M/s. Zam Trading Co. Rs. 402,500/-		On Lowest Basis

ACCOUNTS OFFICER CIVIL HOSPITAL KARACHI. _ //

M D

Sons

Item No.	Descriptions of Works	Qty	Name of Firm & & Rate Quoted	Name of Firm & Rate Quoted	Name of Firm & Rate Quoted	Ramarks
11	Repair / Replacement of Ultrasound Probe @ Surgical ICU Sector Probe Make: G E	01	M/s. Field Supplies Rs. 801,000/-	M/s. Life One Rs. 830,000/-		On Lowest Basis
12	Repair of 730KVA F.G. Wilson DG Set @ CHK	01 Job	M/s. Perfect Power Rs. 1,500,000/-	-	-	May be retendered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	NQ	NQ	NQ	NQ

Zamilar

ADDL: MEDICAL SUPERINTENDENT

(TECHNICAL)

and. Medical Superintendes IVIL HOSPITAL KARACHI

(Technical) Sivil Hospital, Marachie

> ASSTT. PROF: OF SURGERY UNIT - IV DOW UNIVERISTY OF HEALTH SCIENCE KARACHI

> > Dr. Erum Kazim
> > FCPS
> > Assistant Professor
> > Department of Surgery Unit-IV
> > Dow University of Health Sciences &
> > Civil Hospital Karachi

ACCOUNTS OFFICER CIVIL HOSPITAL KARACHI ASSTT. PROF. OF CARDILOGOY DOW UNIVERSTY OF HEALTH SCIENCE KARACHI

> DR. Arshad Ali Shah M.B.B.S FCPS (Cardialogy) Assistant Professor Deptt. of Cardialogy DUHS & CHK

ADDL: MEDICAL SUPERINTENDENT (GENERAL) CIVIL HOSPITAL KARACHI

Addl. Medical Superintendent Givil Hospital narachi

BID EVALUATION REPORT

1. Name of Procuring Agency:

2. Tender Reference No:

3. Tender Description/Name of item:

4. Method of Procurement:

5. Tender Published:

Civil Hospital, Karachi

No. AMS(Tech) /-12824/26 Dated 24-04-2017

Maintenance & Repair of Machinery Equipments @ CHK.

Single Stage One Envelope Procedure Basis

The Daily "Jang" Dated 26-04-2017 and hoisted on SPPRA website

at S.No. 32946

6. Total Bid documents Sold:

7. Total Bids Received:

8. Tender Opening date:-

9. Bid(s) Rejected:

10. Bid Evaluation Report:

Six Six

11-05-2017

Nil

S. No.	Name of Firm or Bidder	Cost offered by the Bidder	Ranking in terms of cost	Comparison with Estimated cost	Reasons for acceptance/ rejection	Remarks
0	1	2	3	4	5	6
1	M/s. Zam Trading Co.					
2	M/s. Field Supplies	Please See the			Please See the	Item wise
3	M/s. Health Tech Pak	Comparative			Comparative	rate(s) have been recorded
4	M/s. Comvare	Statement			Statement	in comparative
5	M/s. Perfect Power					statement
6	M/s. Life One					Statement

The Committee is recommended to award the contract on lowest basis.

Accounts Officer Civil Hospital, Karachi Dr. Qamar-ul-Zaman Memon

Addl. Medical Superintendent (Technical)

Civil Hospital Karachi

(Technical)

Civil Hospital, Massashi.

DR. Arshad Ali Shah

M.B.B. Fops (Cardialogy)

Assistant Professor

Deptt. of Cardialogy

Asstt. Prof. of Cardiology

Dow University of Health Sciences Karachi

Asstt. Prof. of Surgery Unit - IV Dow University of Health Sciences Karachi

Dr. Abdul Qadir Siddiqui

Addl. Medical Superintendent (General)

Addl. Medical Superintendent Civil Hospital Karachi

Dr. Erum Kazim

Assistant Professor Department of Surgery Unit-IV
Dow University of Health Sciences & Civil Hospital Karachi



REPAIR OF MACHINERY EQUIPMENTS CRITERIA FOR EVALUATION OF THE BID

NIT NO. INF/KRY-2244/17 SPPRA ID @ S. No. 32946

			Zam ng Co.	1 TENTON OF THE PARTY OF THE PA	Field plies		alth Tech ak	M/s. C	omvare	Po- Engin	Perfect wer eering ition	M/s. I	Life One
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	Yes	No
1.	Compliance of Terms & Conditions / Instructions mentioned in the Bid Form / NIT.	~	(<u></u>	~	-	~	_	V	-	~	_	~	-
2.	Relevant Experience	V	-	~	-	~	-	~	<u> 4</u>	~	-	~	-
3.	Registration with Income Tax / Sales Tax. (Mandatory) / Sindh Sales Tax (SST) If applicable.	V	-	~	-	~	_	V	3-	~	-	~	_
4.	Copy of Bank Certificate regarding financially soundness and Turn over for the last three years. (5.000 (M) Turn over in each year).	V	-	~	-	~	-	~	-	~	_	~	-

ACCOUNTS OFFICER
CIVIL HOSPITAL KARACHI

A ==

ans

Tender opening meeting held on 11-05-2017 at 12:00 noon in the Committee Room of Civil Hospital Karachi under the Chairmanship of Addl: Medical Superintendent (General), Civil Hospital Karachi for "Repair of Machinery Equipments" at Civil Hospital Karachi.

The following members have attended the meeting:-

S. No.	Name of Officer(s)	Signature
1	Addl: Medical Superintendent (General), Civil Hospital Karachi	Jan
2	Assistant Professor of Cardiology, Dow University of Health Science, Karachi	Ar
3	Assistant Professor of Surgery Unit -IV, Dow University of Health Science, Karachi	<u></u>
4	Addl: Medical Superintendent (Technical), Civil Hospital Karachi	2gg
5	Accounts Officer, Civil Hospital Karachi	J.

Sealed tenders were invited through the publication of Tender Notice published in the Daily "Jang" Dated 26th April' 2017 and hoisted on SPPRA website vide Sr. No. 32946 for the "Repair of Machinery Equipments" at Civil Hospital Karachi.

The **Bids** opened on 11-05-2017 at 12:00 noon in the Committee Room, Civil Hospital Karachi before the Procurement Committee of this Hospital.

The following firms have participated in the competition, the representative who was present at the time of opening tender their signatures were taken as a token of presence.

S. No.	Name of Firms	Signature of Representative
J -	m/S Law Frading Co.	Saxlan
2.		
Z-	M/s Health Tech Pakistan	Arra
	ms Comvare	Que /
5-	,	H.J.
	mys Life One	Sei.
	o and	
	7	80





STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -Date of Opening & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

S. No.	Description of Work	Qty.	Open Rate Amount Offered
	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex	5	1
	Make: Medec Model: Neptune Sr. No. 09/15698		
1	TRX 3 Pressure Sensor	01	1
	TRX 4 Pressure Sensor		
	Service Charges		
	Repair / Replacement Parts of Xenon Light Source @ Medical Unit -I	01	- /
2	Model: CLV-160	Job	/
	Replacement of Xenon Bulb (2 Nos)	JOB	
	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit - I		
	Model: GIF – V		. /
	Replacement of Connection Tube		/
	Replacement of Bending Unit		1
	Replacement of Bending Sleeve		- /
	Replacement of Instrument Channel		
3	Replacement of A/W Channel	01	/
	Replacement of EL-connector		
	Replacement of Wire Stopper x4		/
	Replacement of W-Mount x4		/
	Replacement of Protector		1
	Replacement of O-Rings		/
	Replacement of FPC Strip		1
	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit - I		
6	Model: CF-180AL		1
- 2	Replacement of Connection Tube		
	Replacement of Bending Unit		
	Replacement of Bending Sleeve		X
	Replacement of D-End Unit	-	11-6-
	Replacement of FPC Unit		1
4	Replacement of Light Guide Bundle	01	
n .	Replacement of Big Wheel		
	Replacement of Small Wheel	-	
	Replacement of Wire Stopper x4		\
	Replacement of W-Mount x4		1 29
	Replacement of F-Knob Cover		\ \
	Replacement of C-Cover		
	Replacement of O-Rings		\ .
	Repair of Ultrasound Machine @ Radiology Department		
5	Model: Xerio Make: Toshiba	0.1	\
2	Replacement of Microprocessor PCB	01	
. 2	Replacement of Linear Probe		

S. No.		Description of Work		Qty.	Open Rate Amount Offered
		f Ultrasound Machine @ Radiology Depart	ment		,
6		11 Make: Sono Scape		01	
		nent of 1x DBF PCB			
		f UPS 50KW @ Radiology Department			1
7		nent require of batteries nent require of invertors		03	1
		nent require of invertors	14		
-		f C. Arm Machine @ Ortho O.T			
	Make:- S				
0	The second second	quire of control		0.1	1
8		quire of I.I		01	
		nent require of camera			1
		service require			
		Syringes Pump @ Surgical ICU			/
-	Make:- B.	Braun ent require of main board			
9		ent require of main board ent require of stepper motor		02	
		ent require of power supply			
	Complete s	service require			
		Defibrillator @ C.C.U			
		obe Make:- G.E			
10		ent require of battery pack		01	
minute in		ent require paddles			/
	Complete	ent require of lcd display			
	Complete	service		_	 -
	Donnin /	Donlagement of Hitmasound Ducks @ Curai	and ICII		
11		Replacement of Ultrasound Probe @ Surgi	cal ICU	01	
11	Sector Pro	obe Make: G.E	cal ICU	01	1
11	Sector Pro Replacem	obe Make: G.E ent require of Sector Probe	cal ICU	01	1
11	Sector Pro Replacem Repair of	be Make: G.E eent require of Sector Probe f 730KVA F.G. Wilson DG Set @ CHK	cal ICU	01	1
11	Sector Pro Replacem	be Make: G.E sent require of Sector Probe f 730KVA F.G. Wilson DG Set @ CHK Description		01	1
11	Sector Pro Replacem Repair of Sr. No.	bbe Make: G.E sent require of Sector Probe f 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 1		01	1
11	Sector Pro Replacem Repair of	bbe Make: G.E sent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges		01	1
11	Sector Pro Replacem Repair of Sr. No.	bbe Make: G.E sent require of Sector Probe f 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical		01	1
11	Sector Programmer Replacem Repair of Sr. No.	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side	20,000	01	1
1	Sector Pro Replacem Repair of Sr. No.	be Make: G.E f 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side	20,000 Qty	01	
11	Sector Programmer Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 1 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – I Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295)	20,000	01	
111	Sector Programmer Replacemer Replacemer Sr. No.	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221)	20,000 Qty	01	150000
11	Sector Programmer Replacemer Replacemer Sr. No. Sr. No. Sr. No. Sr. No. 1 2 3 4 Sr. No. 1 2 3 4	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing O Ring (996-490)	20,000 Qty	01	1509000
11	Sector Programmer Replacemer Replacemer Sr. No.	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221)	20,000 Qty	01	1,500,000
111	Sector Programmer Replacemer Replacemer Sr. No. Sr. No. Sr. No. Sr. No. 1 2 3 4 Sr. No. 1 2 3 4	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352)	20,000 Qty		1509000
	Sector Programmer Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110)	20,000 Qty	01	1,500,000
111	Sector Programmer Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (984-024)	20,000 Qty		1,500,000
	Sector Programmer Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519)	20,000 Qty	01	1509000
	Sector Programmer Replacemer Replacemer Replacemer Repair of Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569)	20,000 Qty 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	01	1509000
	Sector Programmer Replacemer Replacemer Replacemer Repair of Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector O Ring (934-569) Injector O Ring (934-570)	20,000 Qty 6 1 1 1 1 1 1 1 6	01	1,509,000
	Sector Programmer Replacem Replacem Repair of Sr. No. 1 2 3 4 5 6 7 8 9 10 11 12	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490)	20,000 Qty 6 1 1 1 1 1 1 1 6 6	01	1,500,000
	Sector Pro Replacem Repair of Replacem Repair of Sr. No. 1 2 3 4 5 6 7 8 9 10 11 12 13	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Water Pump Gas Kit (983-792)	20,000 Qty 6 1 1 1 1 1 1 1 6 6	01	1,500,000
	Sector Pro Replacem Repair of Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Head Water O Ring (986-192)	20,000 Qty 6 1 1 1 1 1 1 1 6 6	01	1,500,000
	Sector Progression Replacement Replacement Replacement Repair of Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030)	20,000 Qty 6 1 1 1 1 1 1 6 6 6 1 4 1	01	1509000
	Sector Programmer Replacemer Replacemer Replacemer of Sr. No. Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)	20,000 Qty 6 1 1 1 1 1 6 6 6 1 1 1 1 1 1 1 1 1 1	01	1509000
	Sector Programmer Replacem Replacem Repair of Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136) Fuel Filter (901-228)	20,000 Qty 6 1 1 1 1 1 1 1 1 4 1 3 1	01	1509000
	Sector Programmer Replacemer Replacemer Replacemer of Sr. No. Sr. No. 1	Description Fuel Injector Servicing & Calibration (2000 X 06) – 1 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)	20,000 Qty 6 1 1 1 1 1 1 6 6 6 1 4 1	01	1500000

No Sint

S. No.	Descripti in of Work	Qty.	Open Rate Amount Offered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	

Terms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- 4. Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- 5. Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- Incomplete and without the required information offer will not be entertained and offer will be rejected.

NOTE:

 Preference will be given to those firms, who are authorized agent of the Equipment which repair work is needed.

Documentary Evidence must be attached if the work / job is being offered / offoted on Authorized agent / Dealer basis which repair is needed.

Pay Order DD/C.D No	_ :	Signature:	10	
Dated:		Name:	Sulen	a Afmed
For Rs.	F	STAMP:		
(Enclosed by the Contractor)		N.T No.	71004	02
	\leq	GST No	Ce	
)	Contract No.		H
Day 111	1			1



STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	/
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit -I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	/
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Big Wheel Replacement of Small Wheel Replacement of W-Mount x4 Replacement of F-Knob Cover Replacement of C-Cover Replacement of O-Rings	01	
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	1

S. No.		Description of Work		Qty.	Open Rate Amount Offered	77
110.		f Ultrasound Machine @ Radiology Departr	nent	1	(4	D
6		11 Make: Sono Scape		01	590000	
		nent of Ix DBF PCB				
		TUPS 50KW @ Radiology Department ent require of batteries			1,99,990 each	X
7		nent require of invertors		03		45
		ent require of power bank			3,599,970	
		f C. Arm Machine @ Ortho O.T	- 4			
	Make:- S	emens			,	
8		quire of control		01		
O		quire of I.I			/	
		ent require of camera			/	
		service require		-		
	Make:- B.	Syringes Pump @ Surgical ICU Braun			212000 Each	1
9		ent require of main board		02	2.200	1
9		ent require of stepper motor		02	424000	12
		nt require of power supply			1-13-	
-		service require f Defibrillator @ C.C.U		-		
		obe Make:- G.E			,	
.		ent require of battery pack		0.1	/	
10		ent require paddles		01		
		ent require of lcd display			,	
				1		1
	Complete					
	Repair /	Replacement of Ultrasound Probe @ Surgio	al ICU		00	0
11	Repair / I Sector Pro	Replacement of Ultrasound Probe @ Surgio obe Make: G.E	cal ICU	01	830,000	2
11	Repair / I Sector Pro Replacem	Replacement of Ultrasound Probe @ Surgio obe Make: G.E ent require of Sector Probe	al ICU	01	830,000	D
11	Repair / I Sector Pro Replacem	Replacement of Ultrasound Probe @ Surgio obe Make: G.E	eal ICU	01	830,000	2
11	Repair / I Sector Pro Replacem Repair of	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Deent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description		01	830,000	9
11	Repair / I Sector Pro Replacem Repair of	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Deent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12		01	830,000	9
11	Repair / I Sector Pro Replacem Repair of	Replacement of Ultrasound Probe @ Surgice Debe Make: G.E Sent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical		01	830,000	9
11	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Deent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12		01	830,000	9
11	Repair / Sector Pro Replacem Repair of	Replacement of Ultrasound Probe @ Surgice Debe Make: G.E Deent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side	20,000	01	830,000	9
11	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgice Debe Make: G.E Bent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description	20,000 Qty	01	830,000	9
11	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Deent require of Sector Probe F 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295)	20,000	01	830,000	9
111	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgion Discount Replacement of Ultrasound Probe @ Surgion Discount Require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221)	20,000 Qty	01	830,000	2
111	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Deent require of Sector Probe F 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295)	20,000 Qty	01	830,000	2
111	Repair / Sector Pro Replacem Repair of Sr. No.	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E. Bent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490)	20,000 Qty	01	830,000	9
111	Repair / Sector Progression Sect	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E Dent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110)	20,000 Qty		830,000	2
111	Repair / Sector Pro Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E. Bent require of Sector Probe (730KVA F.G. Wilson DG Set @ CHK) Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352)	20,000 Qty	01	830,000	A 9
	Repair / Sector Pro Replacem Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7	Replacement of Ultrasound Probe @ Surgion Debe Make: G.E. Bent require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 × 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160)	Qty 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		830,000	2
	Repair / Sector Progression Replacem Repair of Sr. No. Sr. No. Sr. No. Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8 9	Replacement of Ultrasound Probe @ Surgion Cobe Make: G.E. Each require of Sector Probe F730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519)	Qty 6 1 1 1 1 1 1 1 6	01	830,000	2
	Repair / Sector Progression	Replacement of Ultrasound Probe @ Surgion of the Make: G.E. Sent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569)	Qty 6 1 1 1 1 1 1 1 6 6	01	830,000	2
	Repair / Sector Progress Replacem Repair of Sr. No. 1	Replacement of Ultrasound Probe @ Surgion obe Make: G.E lent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570)	Qty 6 1 1 1 1 1 1 1 6	01	830,000	2
	Repair / Sector Progression	Replacement of Ultrasound Probe @ Surgion obe Make: G.E sent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490)	Qty 6 1 1 1 1 1 1 1 6 6	01	830,000	2
	Repair / Sector Progression	Replacement of Ultrasound Probe @ Surgion obe Make: G.E lent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Water Pump Gas Kit (983-792)	Qty 6 1 1 1 1 1 1 6 6 6 1 1 1	01	830,000	\$ 00 P
	Repair / Sector Progression	Replacement of Ultrasound Probe @ Surgion obe Make: G.E. ent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 x 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192)	Qty 6 1 1 1 1 1 1 1 6 6	01	830,000	2
	Repair / Sector Progression Replacem Repair of Sr. No. 1 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15	Replacement of Ultrasound Probe @ Surgic obe Make: G.E ent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 x 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030)	Qty 6 1 1 1 1 1 1 6 6 6 1 1 4 1	01	830,000	2
	Repair / Sector Progression Replacem Repair of Sr. No. 1 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15 16	Replacement of Ultrasound Probe @ Surgic obe Make: G.E ent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)	Qty 6 1 1 1 1 1 1 6 6 6 1 1 1	01	830,000	2
	Repair / Sector Progression Replacem Repair of Sr. No. 1	Replacement of Ultrasound Probe @ Surgicobe Make: G.E lent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Injector O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136) Fuel Filter (901-228)	Qty 6 1 1 1 1 1 1 1 1 4 1 3 1	01	830,000	
*	Repair / Sector Progression Replacem Repair of Sr. No. 1 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15 16	Replacement of Ultrasound Probe @ Surgic obe Make: G.E ent require of Sector Probe for 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)	Qty 6 1 1 1 1 1 1 6 6 6 1 1 4 1	01	830,000	

KARAN (

S. No.	Description of Work	Qty.	Open Rate Amount Offered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	1

Terms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- 9. List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- Incomplete and without the required information offer will not be entertained and offer will be rejected.

NOTE:

work is needed.
Documentary Evidence must be attached if the work / job is being offered / quoted on cartholized agent / Dealer basis which repair is needed.

Preference will be given to those firms, who are authorized agent of the Equipment which repair

Pay Order DD/C.D No	Signature:	* KARAGU
Dated:	Name:	Sami Bant
For Rs.	STAMP:	
(Enclosed by the Contractor)	N.T No.	1426021-2
	GST No	1203999928219
	Contract No.	



S...NDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

 $11^{\rm th}$ May' 2017 @ 11:30 a.m $11^{\rm th}$ May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	1/8
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit -I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	N/A
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	N/A
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Small Wheel Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of C-Cover Replacement of C-Cover Replacement of O-Rings	01	NA
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	ND



0.		Description of Work			Qty.	Open Rate Amount Offered
6	Repair of Ultrasound Machine @ Radiology Department Model: S11 Make: Sono Scape Replacement of 1x DBF PCB			01	NA	
		UPS 50KW @ Radiology Department				Each 21325000/=
7	Replaceme	ent require of batteries			03	3= 3975000/2
ř.		ent require of invertors			05	51100001
		ent require of power bank				
		C. Arm Machine @ Ortho O.T				1
	Make:- Sie					1
8		uire of control			01	216220/=
	Repair req	ent require of camera				1
		service require				. (
		Syringes Pump @ Surgical ICU			_	
	Make:- B. E					
9		nt require of main board			02	l J
-		nt require of stepper motor			-	NIO
		nt require of power supply ervice require				14/4
_		Defibrillator @ C.C.U				
		be Make:- G.E				
		ent require of battery pack			٥,	1
10		ent require paddles			01	11/2
		ent require of lcd display				(V/Q
	Complete	service				('
						,
_	Repair / F	Replacement of Ultrasound Probe @ Su	rgical ICU			, /
11	Repair / F Sector Pro	Replacement of Ultrasound Probe @ Sube Make: G.E	irgical ICU		01	NID
11	Repair / F Sector Pro Replaceme	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe			01	N/Q
11	Repair / F Sector Pro Replaceme	Replacement of Ultrasound Probe @ Sube Make: G.E		-	01	N/Q
11	Repair / F Sector Pro Replaceme Repair of	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK			01	N/R
11	Repair / F Sector Pro Replaceme	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description			01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No.	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical			01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No.	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges) – 120,000		01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No.	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical) – 120,000		01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No.	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description) – 120,000	Qty	01	N/Q
1	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side) – 120,000	Qty 6	01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 2 3 4	Replacement of Ultrasound Probe @ Subbe Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221)) – 120,000	6	01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 3 4	Replacement of Ultrasound Probe @ Subbe Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490)) – 120,000	6 1 1	01	N/Q N/O
11	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110)) – 120,000	6 1 1 1	01	N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5r. No. 1 5r. No.	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing-Cover Gas Kit (973-352)) – 120,000	6 1 1 1 1	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6	Replacement of Ultrasound Probe @ Subbe Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024)) – 120,000	6 1 1 1 1		N/Q
11	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352)) – 120,000	6 1 1 1 1 1 1	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160)) – 120,000	6 1 1 1 1 1 1 1		N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8 9	Replacement of Ultrasound Probe @ Subble Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519)) – 120,000	6 1 1 1 1 1 1 1 1 6	01	N/Q
	Repair / F Sector Pro Replaceme Repair of	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06) Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569)) – 120,000	6 1 1 1 1 1 1 1 1 6 6	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8 9 10 11	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570)) – 120,000	6 1 1 1 1 1 1 1 1 6 6	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490)) – 120,000	6 1 1 1 1 1 1 1 6 6 6	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 4 5 6 7 8 9 10 11 12 13	Replacement of Ultrasound Probe @ Sube Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 1 1	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 4 5 6 7 8 9 10 11 12 13 14	Replacement of Ultrasound Probe @ Subble Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 6 1 1 1	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 4	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 6 1 1 1 4	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15 16	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 1 1 1 4 1 3	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 Sr. No. 1 1 2 1 3 1 4 1 5 1 6 1 7 1 6 1 7 1 6 1 7 1 6 1 7 1 7 1 7	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136) Fuel Filter (901-228)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 6 1 1 1 4 1 3	01	N/Q
	Repair / F Sector Pro Replaceme Repair of Sr. No. 1	Replacement of Ultrasound Probe @ Subb Make: G.E ent require of Sector Probe 730KVA F.G. Wilson DG Set @ CHK Description Fuel Injector Servicing & Calibration (2000 X 06 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136)) – 120,000	6 1 1 1 1 1 1 1 6 6 6 1 1 1 4 1 3	01	N/Q

ייינטו רבוו



S. No.	Description of Work	Qty.	Open Rate Amount Offered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	N/R

Terms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- 5. Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- 9. List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- Incomplete and without the required information offer will not be entertained and offer will be rejected.

NOTE:

 Preference will be given to those firms, who are authorized agent of the Equipment which repair work is needed.

Documentary Evidence must be attached if the work / job is being offered / quoted on humorized agent / Dealer basis which repair is needed.

Pay Order DD/C	.D No	_ :	Signature:	Cores de la constante
Dated:			Name:	wasif Rosa wand.
For Rs.			STAMP:	
(Enclosed by the	Contractor)		N.T No.	3910732-9
			GST No	5
			Contract No.	н



STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit -I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Big Wheel Replacement of Small Wheel Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of F-Knob Cover Replacement of C-Cover Replacement of O-Rings	01	
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	810,000/=



STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit –I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Big Wheel Replacement of Small Wheel Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of F-Knob Cover Replacement of C-Cover Replacement of O-Rings	01	
- 5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	810,000/=

S. No.	Description of Work		Qty.	Open Rate Amount Offered
Repair of 6 Model: S	f Ultrasound Machine @ Radiology Departm 11 Make: Sono Scape tent of 1x DBF PCB	01	1	
Repair of Replacem	f UPS 50KW @ Radiology Department nent require of batteries nent require of invertors nent require of power bank	03		
	f C. Arm Machine @ Ortho O.T		-	
8 Repair re Repair re Replacem	iemens quire of control quire of I.I nent require of camera	×	01	
9 Replaceme Replaceme Replaceme Complete	Complete service require Repair of Syringes Pump @ Surgical ICU Make:- B. Braun Replacement require of main board Replacement require of stepper motor Replacement require of power supply Complete service require			250,000/=
Sector Pr Replacen Replacen Replacen	Repair of Defibrillator @ C.C.U Sector Probe Make:- G.E Replacement require of battery pack Replacement require paddles Replacement require of lcd display Complete service			390,000/=
Repair / 11 Sector Pr	Replacement of Ultrasound Probe @ Surgic obe Make: G.E nent require of Sector Probe	al ICU	01	1
Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	Description Fuel Injector Servicing & Calibration (2000 X 06) – 12 Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160) Injector Washer (973-519) Injector O Ring (934-569) Injector O Ring (934-570) Sump Gas Kit (932-490) Water Pump Gas Kit (983-792) Head Water O Ring (986-192) Spring (906-030) Oil Filter (901-136) Fuel Filter (901-228) Coolant Coolife Total	0,000 Qty 6 1 1 1 1 1 1 1 1 4 1 3 1 123	O1 Job	

JV





S. No.	Description of Work	Qty.	Open Rate Amount Offered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	

Terms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- 9. List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- Incomplete and without the required information offer will not be entertained and offer will be rejected.

NOTE:

- Preference will be given to those firms, who are authorized agent of the Equipment which repair work is needed.
- Documentary Evidence must be attached if the work / job is being offered / quoted on Authoragent / Dealer basis which repair is needed.

	(Karach	121
Pay Order DD/C.D No	Signature:	15
Dated:	Name: Ansar Ullan 16	ion
For Rs.	STAMP:	
(Enclosed by the Contractor)	N.T.No. 4128478-0	
	GST No 1700412847819	
Jan 1997 . State of the state	Contract No.	200

. Dav

STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	
2	Service Charges Repair / Replacement Parts of Xenon Light Source @ Medical Unit –I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Big Wheel Replacement of Small Wheel Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of F-Knob Cover Replacement of C-Cover Replacement of O-Rings	01	
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	X

	Description of Work		Qty.	Open Rate Amount Offered
6 Mod	pair of Ultrasound Machine @ Radiology Depar del: S11 Make: Sono Scape blacement of 1x DBF PCB	tment	01	
7 Rep	pair of UPS 50KW @ Radiology Department placement require of batteries placement require of invertors placement require of power bank		03	
8 Repa Repa Repla Com	pair of C. Arm Machine @ Ortho O.T se:- Siemens air require of control air require of 1.1 lacement require of camera applete service require		01	
9 Make Repla Repla Repla Comp	air of Syringes Pump @ Surgical ICU e:- B. Braun acement require of main board acement require of stepper motor acement require of power supply blete service require	3.	02	
Secto Repla Repla Repla Comp	air of Defibrillator @ C.C.U or Probe Make:- G.E acement require of battery pack acement require paddles acement require of lcd display plete service		01	
11 Secto Repla	nir / Replacement of Ultrasound Probe @ Surgor Probe Make: G.E acement require of Sector Probe nir of 730KVA F.G. Wilson DG Set @ CHK	gical ICU	01	80100/=
Sr. 1 2 3 4 Sr. 1 1 2 3 4 5 6 7 8 9	Fuel Injector Servicing & Calibration (2000 X 06) – Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side No. Description Tappet Cover Gas Kit (908-295) Rocker Housing Gas Kit (996-221) Rocker Housing O Ring (996-490) Front Seal (902-110) Timing Cover Gas Kit (973-352) Oil Cooler Gas Kit (984-024) Oil Cooler Gas Kit (973-352) Oil Cooler O Ring (930-160)	Qty 6 1 1 1 1 1 1 1 6 6 6	OI Job	

X

TARACHIT 8 92

S.	Description of Work	Qty.	Open Rate Amount Offered
	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	

erms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- 9. List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- Incomplete and without the required information offer will not be entertained and offer will be rejected.

NOTE:

 Preference will be given to those firms, who are authorized agent of the Equipment which repair work is needed.

Documentary Evidence must be attached if the work / job is being offered / quoted on Authorized agent / Dealer basis which repair is needed.

Pay Order DD/C.D No	Signature:
Dated:	Name: ASAA Down
For Rs.	STAMP:
(Enclosed by the Contractor)	N.T.No. 4128478-0
	GST No 1700412847819
	Contract No.
M.	2



STANDARD BIDDING DOCUMENTS (SBD) FOR MAINTENANCE & REPAIR OF THE MACHINERY EQUIPMENT AT CIVIL HOSPITAL KARACHI

Date of Submission & Time: -

11th May' 2017 @ 11:30 a.m 11th May' 2017 @ 12:00 noon

Date of Opening & Time: -

S. No.	Description of Work	Qty.	Open Rate Amount Offered
1	Repair of Spare Parts of Anesthesia Ventilator @ O.T Complex Make: Medec Model: Neptune Sr. No. 09/15698 TRX 3 Pressure Sensor TRX 4 Pressure Sensor Service Charges	01	
2	Repair / Replacement Parts of Xenon Light Source @ Medical Unit –I Model: CLV-160 Replacement of Xenon Bulb (2 Nos)	01 Job	
3	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: GIF – V Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of Instrument Channel Replacement of A/W Channel Replacement of EL-connector Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of Protector Replacement of O-Rings Replacement of FPC Strip	01	
4	Repair / Replacement Parts of Gastro Video Scope @ Medical Unit – I Model: CF-180AL Replacement of Connection Tube Replacement of Bending Unit Replacement of Bending Sleeve Replacement of D-End Unit Replacement of FPC Unit Replacement of Light Guide Bundle Replacement of Big Wheel Replacement of Small Wheel Replacement of Wire Stopper x4 Replacement of W-Mount x4 Replacement of F-Knob Cover Replacement of C-Cover Replacement of O-Rings	01	
5	Repair of Ultrasound Machine @ Radiology Department Model: Xerio Make: Toshiba Replacement of Microprocessor PCB Replacement of Linear Probe	01	796,000

).	Description of Work		Qty.	Open Rate Amount Offered
Model: S Replacer	of Ultrasound Machine @ Radiology Department Make: Sono Scape ment of Ix DBF PCB	ent	01	555,100
Replacer Replacer	of UPS 50KW @ Radiology Department ment require of batteries ment require of invertors ment require of power bank		03	
Repair of Make:- S Repair re Repair re Replacer	of C. Arm Machine @ Ortho O.T	<i>15</i> 7	01	216,000
Repair of Make:- B Replacem Replacem Replacem	Syringes Pump @ Surgical ICU		02	
Repair of Sector Pri Replacer Replacer	of Defibrillator @ C.C.U robe Make:- G.E nent require of battery pack nent require paddles nent require of lcd display	·	01	UD2500
Repair / Sector Pr	Replacement of Ultrasound Probe @ Surgica robe Make: G.E nent require of Sector Probe	LICU	01	
Sr. No. 1 2 3 4 Sr. No. 1 2 3 4 5 6 7 8 9 10	Fuel Injector Servicing & Calibration (2000 X 06) – 120. Radiator Wash with Chemical Service Charges Loading & Unloading (Transportation) Both Side	Qty 6 1 1 1 1 1 1 6 6 6 1	O1 Job	

X



2 Am

S. No.	Description of Work	Qty.	Open Rate Amount Offered
13	Repair of Rotofix Centrifuge Machine @ Central Lab Model: Rotofix 32A Make: Hettich – Germany	01	

Terms & Conditions:

- Warranty period for repair work must be given with offer if the repaired equipment is out of order during the warranty period the same will be repaired without charging any cost by the concerned firm.
- 2% Security deposit in shape of pay order in favor of Medical Superintendent Civil Hospital, Karachi, should be attached with offer the same will be refunded after 03 Months. If not received any complain of the repaired equipment.
- The bid shall be opened on the above said date & time in the presence of the Hospital Procurement Committee (For Repair). The offer will be evaluated on best evaluated basis.
- Under taking on Rs.50 Non judicial stamp paper that the firm is not involved in any litigation of Abandoned any work in the department. (One Undertaking is sufficient for this Tender Job)
- Affidavit to the effect that the firm / contractor has not been black listed previously by any procuring / executing agency of the Government.
- (i) All the applicable taxes should be inclusive with offer.
 (ii) The Government Taxes will be deducted from the bills of the Contractors / Suppliers.
- 7. Conditional offer against the SPPRA-2010 (Amended-2013) will not be entertained.
- 8. Address of Bio Medical Work Shop of the Suppliers / Contractors is required.
- 9. List of Bio Medical Engineer / Bio-Medical Technician may be attached.
- List of Technical Staff who will perform this job / work along with Qualification / Experience may also be attached.
- 11. Incomplete and without the required information offer will not be entertained and offer will be rejected.

Preference will be given to those firms, who are authorized agent of the Equipment which repair

NOTE:

work is needed.

 Documentary Evidence must be attached if t agent / Dealer basis which repair is needed. 	ne work / job is being offered / quote and the	orized
Pay Order DD/C.D No	Signature:	
Dated:	Name: Saleen Ston	<u>.</u>
For Rs.	STAMP:	
(Enclosed by the Contractor)	N.T.No. 722399-5	
	GST No 327787612927	7
	Contract No.	-





ٽينڊر نمبر.06 گھرائڻ لاءِ نوٽيس

للول آسپتال كراچي پر هك لغافو پروسيجر جي بنياد تي كلاس (1)46 آف آيس پي پي آر اي 2010 (ترميم 2013) جي ميڊيكل اوزارن جي مرمت لاء انكمر تيكس ۽ سيلز تيكس اختيارين وٽ منظور ٿيل رجسٽرڊ ئيكيدارن/سپلائرن كان مهربند واك گهرائجن ٿا.

- معياري واك دستاويز (SBD) گڏ تفصيل تيكنيكل برانج فرست فلور ائدمن بلاك ايت سول اسپتال كراچي ويب سائت ۽ ايت سول اسپتال كراچي وٽان دستياب آهن. اهي ايس پي پي آر اي جي ويب سائت ۽ سول اسپتال كراچي وٽان پڻ دستياب آهن ۽ هئرهڻ/ميل وسيلي ٽينڊر في 500 رپيا (ناقابل واپسي) پي آر ڊر جي صورت ۾ هيٺ صحيح كندڙ جي حق ۾ جاري ٿيل شامل كري پيش كيا وچن.
- واكسان كذ 20 كل واكرقم بي آرڊر جي صورت ۾ بحق ميڊيكل سپرنٽينڊنٽ سول اسپتال كراچي جي جاري ٿيل شامل كري آفيس آف اي ايم ايس (ٽيكنيكل) فرست فلور، ائڊمن بلاك سول اسپتال كراچي، كراچي كي 11 مئي، 2017 صبح 11:30 وگي تائين پهچڻ گهرجن، جيكي ساڳئي ڏينهن تي كميٽي روم، سيكنڊ فلور، ائڊمن بلاك سول اسپتال كراچي ۾ كوليا ويندا.
- المنافر ۽ بيا شرط ۽ ضابطا مشينري اوزارن جي مرمت ۽ سارسنيال لاءِ هن اشتهار جي اشاعت کان کلڻ واري تاريخ (11 مئي، 2017) تائين 500 رپيا ٽينڊر في (ناقابل واپسي) پي آرڊر جي صورت ۾ ٽيڪنيڪل برانج سول اسپتال ڪراچي وٽ پي آرڊر نيشنل ٽيڪس نيشنل ٽيڪس نيشنل آجهر/ (STR) جي تصديق ٿيل ڪاپي سميت پيش ڪيون وڃن.
- . هيٺ صحيح كندڙ اهو حق محفوظ ركي ٿو ته هو واك لاڳليٽيل ايس بي پي آر اي رولز 2010 (ترميم كيل 2013/2014) موجب رد كري سگهي ٿو . پهر

نوٽ: اوزارن جي انهن مجاز ايجنٽس کي ترجيح ڏني ويندي. جن جي مرهنٽ جو ڪير گهريل آهي.

میدیکل سپرنتیندنت سول اسپتال کراچی

INF/KRY.No:2244/2017






ا سَدَّ ير تعليم جي بهتري لا ي علمي + يتهلجو بيغام لکي 8 9 3 8 تي ايس اينر ايس ڪريو







99215722 Up

نوٹس طلبی ٹینڈر# 06

سول اسپتال کرائی کومیڈیکل ایکو پمنش کی مرمت کیلے کنریکفرز/ سپلائززے جو اکم لیکس اور کیار فیکس افغار فیز کے پاس رجسٹرڈ موں، سے SPPRA روز 2010 (ترمیم شدہ 2013) تا حال کی دفعہ (46 کے مطابق ایک لفاقہ پرومیجر پرمرمبر پیشکشیس مطلوب ہیں۔

- 1) اسٹینڈر ڈیڈ ٹک دستاویزات (SBD) مع تفصیلات سول اسپتال کرا تی کی ٹیکینیل براہ فی مکلی منزل ایڈ من بلاک ہے دستیاب ہیں۔ یہ ایس ٹی ٹی آراے اور سول اسپتال کرا تی کی ویب سائٹ ہے ڈاؤن لوڈ بھی کی جاسکتی ہیں جنہیں ٹیٹیڈر فیس -/500 روپے (نا قابل والہی) بھٹل ہے آرڈ ریکٹن زیر دیکھنی کے ساتھ دی طور پر/ بزریوہ ڈاک پہنچاد یا جائے۔
- 2) پیشکشوں کے ہمراہ پیشکش کی کل لاگرے کی "کی ساوی رقم بیشکل پے آرڈور بھی میڈیکل پروششڈ نے، سول اسپتال کرا ہی، دفتر AMS (میکیٹیل)، ہمپلی منزل، ایڈمن بلاک، سول اسپتال کرا ہی میں 11 مئی 2017 بوقت دن 11:30 بیچ تک تحق کرادی جا میں اور بیابی دن دو پہر 12:00 ہے کیمٹی روم واقع دو مری منزل، ایڈمن بلاک، سول اسپتال کرا ہی میں کھولی جائیگی ۔
- النصيل شيئرروستاويزات بهمراه شرائط وضوابط برائے مرمت بابته شينري ايکو پهنٹ تاريخ اشاعت بندا ہے کو لئے کی تاریخ کینی 2017-15-16 من 10:00 بنتے تک مبلغ -/500 دو بے(ٹا قابل والدی)
 کی شیئر رئیس بشکل ہے آرڈر بخت زیر جھنی بیز ہے آرڈرا این ٹی این اور سکڑ ٹیکس دھسٹریشن کی ہا تا عدہ تصدیق شدیع کی بنتی ترارے بریکینکل برائج سول اسپتال کرائی ہے حاصل کی جائتی ہیں۔
- 4) زیرد تخلی SPPRA رواز 2010 (ترمیم شده 2013/14) کے متعلقہ مندرجات سے مشروط بیشکشوں کے استر داد کا می محفوظ رکھتے ہیں۔

نوف: ایکوچمنش جن کی مرمت کا کام کیاجانا ہے، کے بجازا یجنش کورجے دی جائے گا۔

ومنعظميد يكل سير نشندنث

سول اسپتأل كراچى

(INF-KRY-2244/17) جم وبشت گروی کے خلاف متحد میں

SAV NO TO CORRUPTIO

DARE

· . a control policies .





No. AMS (Tech)/-12824/26

Civil Hospital

Baba-e-Urdu Road, Karachi

Dated: 24 - 4 - 2017.

The Director Information Information Department, Government of Sindh, Karachi.

Subject: -NOTICE INVITING TENDER FOR REPAIR EQUIPMENTS @ CIVIL HOSPITAL KARACHI.

I am enclosing herewith 07 (Seven) N.I.T for Repair of Medical Equipments of this Hospital with the request to publish it 03 No prominent newspaper one Sindhi, one Urdu & one English for one day only and copy of cutting of N.I.T may kindly be sent to this Hospital for record.

Your co-operation will be highly appreciated.

Advertisement Information Department Govt. of Sindh, Karachi

CIVIL HOSPITAL KARACHI

C.c to the:-

· Director (A & F), SPPRA along with copy of N.I.T and bidding documents with the request to hoist it on authority's website.

Incharge I.T Civil Hospital Karachi with the request to hoist it on Civil Hospital Karachi website.



No. MS (CHK)/-Civil Hospital

Baba-e-Urdu Road, Karachi

Assistant Director

Sindh Public Procurement Regulatory Authority Karachi.

Subject:

NIT Ref No: AMS/(Tech)12824/26 dated 24.4.2017 (Sr. No. 32946)

Reference:

No. AD (ASMT) / SPPRA/MS-32946)/2016-17/2559

It is notified for information to all the interested bidders that 2% Performance Security will be obtained from the successful bidder in response of Letter of Intent issued to the bidder at the time of signature of the Contract Agreement of the required works.

CIVIL HOSPITAL KARACHI

Copy to the:-

- M/s. Zam Trading Co.
- M/s. Field Supplies
- M/s. Comvare
- M/s. Life One
- M/s. Health Tech Pakistan
- M/s. Perfect Power Engineering Solutions
- Notice Board.

FOR: MEDICAL SUPERINTENDEN

Nampal Cho