

K-332

**OFFICE OF THE EXECUTIVE ENGINEER (SEWERAGE) SITE TOWN
KARACHI WATER & SEWERAGE BOARD**

Site Town Water Adjacent Rashid Minhas School Near Urdu Bazar Nazimabad No.1
Karachi

No.KW&SB/E/E/SEW/S.T/2015/76

Dated: 1204-15

The Director (CB),
SPPRA
Barrack No.8 Sindh Secretariat No.4-A
Court Road
Karachi.

**SUBJECT: REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC
RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2 AND UC#3
& P/M SUPPLYING & FIXING OF 21" DIA RCC COVER AND RING SLAB
FOR SITE TOWN.**

Reference: SPPRA Website Serial No.23418 I.D. /2015.

Enclosed Please find herewith the following information regarding
above NIT here by forwarded for uploading on SPPRA Website Please.

1. Bidders Qualification Report.
2. Minute of Bid Opening Meeting
3. Bid Evaluation Report.
4. Comparative Statement.
5. Attendance of Participate Contractors.

Executive Engineer (Sewerage)
Site Town, KW&SB

Copy for Information to all concerned.

SPPRA INWARD DIARY
NO: 15494
DATE: 20-4-15

12/4
M/CS
Put up urgently
Arsh
12/4

NIT No. SPPRA Serial No. 23418

Method and procedure of procurement: Open Competitive Bidding (National/ International Competitive Bidding) (Single Stage-One Envelope)

Description of work: REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2 AND UC#3 & P/M SUPPLYING & FIXING OF 21" DIA RCC COVER AND RING SLAB FOR SITE TOWN

Date of Opening: 14-04-2015


BIDDERS' ELIGIBILITY/ QUALIFICATION REPORT


Eligibility/ Qualification Criteria:

S. No.	Eligibility / Qualification Criteria	Bidders' Name	
		M/s. Al-Maqbool Associates	M/s. Haji Abdul Baqi & Bros
1.	Registration with PEC (if applicable)	N/A	N/A
2.	NTN	Yes	No
3.	Sales Tax Registration (FBR)	N/A	N/A
4.	Registration with Sindh Revenue Board (SRB)	Yes	No
	Qualification Criteria:		
5.	Minimum three years' experience of relevant field.	Yes	No
6.	Turnover of at least last three years	Yes	No
7.	Required Bid Security is attached.	Yes	No
8.	Bid is signed, named and stamped by the authorized person of the firm along with Authorization letter.	Yes	No
9.	Any other factor deemed to be relevant by the procuring agency subject to provision of Rule-44	N/A	N/A
10.	Qualified/ disqualified	Qualified	Disqualified


(Muhammad Khalid Khan)
Accounts Officer (Dist. West)
Member Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit - KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member


(Abdul Rahim Khattai)
Chief Engineer (S,C&W)
Members


(Abdul Rahim Khattai)
Chief Engineer (IPD)
Convener

NIT Sr. No. 23418

Method of Procurement: Single Stage Single Envelope.

Name of Work: REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA
RCC RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2
AND UC#3 & P/M SUPPLYING & FIXING OF 21" DIA RCC COVER
AND RING SLAB FOR SITE TOWN

MINUTES OF BID OPENING MEETING.

A meeting of the procurement committee of this department was held on 14-04-2015 for opening the bids received in respect of subject NIT till deadlines of submission. The meeting was attended by all / following members of the procurement committee and the representative of bidders.


(Attendance sheet is enclosed).

2. Two bidders submitted their bids till the deadline of submission.
 - i. M/s. Al-Maqbool Associates
 - ii. M/s. Haji Abdul Baqi & Bros
3. The bids were opened at 2:30 P.M in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee.


S. No	Name of Firm	Quoted Price	Amount of Bid Security	Pay Order No. / Date
01	M/s.Al-Maqbool Associates	Rs.9,56,348/-	Rs.20,000/-	P.O # 12388793 dt:13-04-2015 from HBL North Nazimabad Branch Karachi
02	M/s.Haji Abdul Baqi & Bros.	Not Quoted	-	Pay order not Attached

4. The bids did not contain any over-writing or cutting.
5. The committee shall examine all the bids as per the qualification / eligibility criteria provided in the bidding document and verify the documents and bid security submitted by the bidders (if required).

The meeting ended with the vote of thanks to and from the chair.


(Muhammad Khalid Khan)
Accounts Officer (West)
Member / Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit – KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member


(Abdul Rahim Khattai)
Chief Engineer (S,C&W)
Members


(Abdul Rahim Khattai)
Chief Engineer (IPD)
Convener



KARACHI WATER & SEWERAGE BOARD

OFFICE OF THE CHIEF ENGINEER (IP&D)

BID EVALUATION REPORT

1	Name of Procuring Agency:	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No:	SPPRA Serial No.23418 I.D # _____/2015
3	Tender Description/Name of Work/Item:	REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2 AND UC#3 & P/M SUPPLYING & FIXING OF 21" DIA RCC COVER AND RING SLAB FOR SITE TOWN
4	Method of Procurement:	<u>Single Stage (One Envelop)</u>
5	Tender Published:	<u>Through SPPRA Web Site</u>
6	Total Bid Documents Sold:	<u>2 Nos</u>
7	Total Bid Received:	<u>2 Nos</u>
8	Technical Bid Opening Date (if applicable):	<u>N/A</u>
9	No. of Bid Technically Qualified (if applicable)	<u>N/A</u>
10	Bid (s) Rejected:	<u>01 No.</u>
11	Financial Bid Opening Date:	14-04-2015

12 BID EVALUATION REPORT


S #	Name of Firm / Bidder	COST OFFERED BY THE BIDDER	RANKING IN TERMS OF COST	COMPARISON WITH ESTIMATED COST	REASON FOR ACCEPTANCE/ REJECTION	REMARKS
1	M/s.Al-Maqbool Associates	Rs.9,56,349/-	1 st Lowest	@0.027% Below	Pay order and other documents are attached. P.O # 12388793 dt:13-04-2015 Rs.20,000/- from HBL North Nazimabad Branch Karachi	Substantially Responsive
2	M/s.Haji Abdul Baqi & Bros.	Not Quoted	-	-	Pay order and other documents are not attached.	Un-Responsive

The all concerned bidders are being informed accordingly.


The E.E Concerned for compliance of Rule-45 of SPPRA 2010 **M/s.Al-Maqbool Associates** declared as the lowest responsive bidder by the Committee and recommended for sanction from Competent Authority.


(Muhammad Khalid Khan)
Accounts Officer (Dist. West)
Member / Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit – KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member





(Abdul Rahim Khattai)
Chief Engineer (S,C&W)
Members


(Abdul Rahim Khattai)
Chief Engineer (IPD)
Convener

COMPARATIVE STATEMENT

Name of Work: REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2 AND UC#3 & P/M SUPPLYING & FIXING OF 21" DIA RCC COVER AND RING SLAB FOR SITE TOWN


Item No	Description of Work	Estimated Cost				M/s. Al-Maqbool Associates		
		Quantity	Rate	Per	Amount	Rate	Amount	
1	Dismantling and removal road metaling	1780.00	Cft	605.00	%Cft	10,769.00	605	10,769.00
2	Excavation for pipe line in trenches and pits in all kind of soils of murum i/c trimming and dressing sides to true alignment and shape leveling of beds of trenches to correct level and grade cutting joints holes and disposal of surplus earth within one chain as directed by Engineer Incharge providing fence guards, lights, flags sand temporary crossing for non-vehicular traffic wherever required lift upto 5 ft (1.52 m) and lead upto one chain (30.5m). 0' - 05'ft Depth	8260.00	Cft	4650.00	%0Cft	38,409.00	4650	38,409.00
	5' - 08' Depth	1140.00	Cft	5200.00	%0Cft	5,928.00	5200	5,928.00
3	Providing, & Laying of RCC Pipes with Rubber Ring Joint and fitting in trench including cutting, fitting, jointing with rubber ring i/c testing with water to specified pressure.	380	Rft	367.00	P/Rft	139,460.00	367	139,460.00
	12" Dia	256	Rft	206.00	P/Rft	52,736.00	205	52,480.00
4	Providing manhole 4' feet (inside) and 5 feet clear depth with C.I Frame (15 Kg) cast in situ with 1:2:4 CC in 9" thick wall, 1:4:8: C.C in 6ft dia and 6" inch thick in foundation 1:2:4 C.C in benching 12" thick cement plastering with 1:3 C.M on all inside wall surfaces, channel and benching i/c making required nos of main and branch channels, 3/4" dia m.s foot rest @12" c/c i/c cost of excavation in all kinds of soil, backfilling and disposal of excavated stuff etc complete as per design and instruction of Engineer Incharge.	26	Nos	14529.29	Each	377,761.54	14529	377,761.54
5	Add for extra depth add or deduc.	13.00	(+)Rft	2538.62	P/Rft	33,002.06	2539	33,002.06
6	Making connection with the existing manhole including the cost of cutting hole in wall, making them good in C.C 1:2:4 and making the required channel etc. complete	20.00	Nos	180.00	Each	3,600.00	180	3,600.00
7	Refilling the excavated stuff in trenches 6" thick layer i/c watering ramming to full compaction etc complete.	8795.00	Cft	2760.00	%0Cft	24,274.20	2760	24,274.20
8	Manufacturing and supplying of 21" dia RCC Manhole covers cast in situ 1:2:4 concrete ratio 3" deep at centre, reinforced with 1/2" dia tor steel bars at 4" C/C welded to a 3/16" thick 2" wide M.S plate two hook of 3/8" dia tor bar including compacting i/c cutting and transportation with in 10 miles. 21" dia cover	80.00	Nos	913.63	Each	73,090.40	914	73,090.40






Name of Work: REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC RUBBER RING SEWER IN DIFFERENT LOCATION OF UC#2 AND UC#3 & P/M SUPPLYING & FIXING OF 21" DIA RCC COVER AND RING SLAB FOR SITE TOWN

Item No	Description of Work	Estimated Cost			M/s. Al-Maqbool Associates			
		Quantity	Rate	Per	Amount	Rate	Amount	
9	Manufacturing and supplying of RCC Ring Slab of 21" dia (inside) and 36" dia outside 7.5" width and 6" thick i/c 3/8" dia tor steel bars two concentric rings with 3/8" dia 8 Nos cross linked bars welded and two sunk type hooks, casted in 1:1 1/2" 3 concrete with embedded 15 Kg C.I Frame in perfect position i/c transportation charges for an average lead of 20 Km per trip from casting yard to town office. (A minimum of 25 slabs per trip will be transported.	80.00	Nos	1906.60	Each	152,528.00	1907	152,528.00
10	Shifting to the site and Fixing of 36" dia Ring Slab in perfect position on damaged manholes i/c cutting of the position of damaged manhole in layer of cement motor in 2" thickness and disposal of debris.	80.00	Nos	563.09	Each	45,047.20	563	45,047.20
	TOTAL QUOTED / CORRECTED COST					956,605		956,349


 (Muhammad Khalid Khan)
 Accounts Officer (West)
 Member / Secretary


 (Saif-ul-Haque)
 Addl. Director Internal Audit
 KMC - Member


 (Maqsood Ahmed Shakh)
 Superintending Engineer (K.M.C)
 Member


 (Abdul Rauf Khattar)
 Chief Engineer (SC&W)
 Member


 (Abdul Rahim Kkaffi)
 Chief Engineer (IPD)
 Convener

Name of Work : REHABILITATION OF DEFECTIVE / OUTLET 12" DIA & 8" DIA RCC RUBBER RING SEWER IN DIFFERENT LOCATION UC-02 & UC-03 & P/M SUPPLYING AND FIXING OF 21" DIA RCC COVERS AND RING SLAB FOR SITE TOWN.

Date of Opening & Time : 14-04-2015 2:30 PM

Estimated Cost : 9,56,605/-

SPPRA Serial No: 23418/-

S.NO	NAME OF FIRM	NAME OF PERSON & DESIGNATION	SIGNATURE
1	M/s.		
2	M/s.		
3	M/s.		
4			
5			
6			
7			
8			
9			
10			