Employment through Skill



1

51

Sindh Technical Education & Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk



## **BILL OF QUANTITIES**

### MAINTENANCE & REPAIR OF COMPOUND WALL OF GOVERNMENT POLYTECHNIC INSTITUTE MEHAR DIST. DADU



Sindh Technical Education & Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: <u>http://www.stevta.gos.pk</u>



### MAINTENANCE & REPAIR OF COMPOUND WALL OF GOVERNMENT POLYTECHNIC INSTITUTE MEHAR, DISTRICT DADU.

#### **BILL OF QUANTITY**

S. #	NAME OF ITEM	QUANTITY	UNIT	RATE	AMOUNT
01.	<b>EXCAVATION:</b> Excavation in foundation of building bridges and other structures including dabelling dressing, refilling around the structure with excavated earth watering and ramming	9488.00	%0Cft		
02.	lead upto 5 ft. <u><b>DISMANTLING</b></u> Dismantling Cement Block Masonry 1:4	3000.00	%Cft		
03.	<b><u>C.C 1:4:8:</u></b> Cement Concrete Plain including placing compacting finishing and curing complete (including screening and washing of stone aggregate ration 1:4:8	2332.00	%Cft		
04.	<b><u>FABRICATION</u></b> OF <u>STEEL:</u> Fabrication of mild steel reinforcement for cement concrete including cutting, banding, laying in position, making joints and fastening including cost of binding wire and also removal of rust from bars.	246.348	P.Cwt		



1 :

•\_

2

Website: http://www.stevta.gos.pk



		nup.//www.stevt	a.gos.pk		
05.	RCC WORK				
	R.C.C Work in roof slab beams columns rafts lintels and other structural members laid in situ of precast lain in position complete in all respect. Ratio	6000.00	P.Cft		
	1:2:4.				· · · ·
06.	BRICK WORK IN FOUNDATION: Pacca brick work in foundation and plinth in cement sand mortar ratio 1:4	7350.00	%Cft		
07	BRICK WORK IN	-			
	GROUND FLOOR: Pacca brick work in ground floor in cement sand mortar ratio 1:4	6209	%Cft		
08	<b>EARTH FILLING:</b> Filling watering and ramming earth under floor with new excavated earth from out side lead upto one chain lift upto 5' ft	50000.00	%0Cft		
09	<b>STEEL GRILL:</b> S/F in position iron steel grill of 13/6" thick size flate i/c approved design and paiting 3 coats etc complete.	1915.00	P.Rft		
10.	Plaster 1/2" thick:			_	
	Cement Plaster 1:4 upto 12ft height ½"" thick.	36000.00	%Sft		
1	L				



i

# Sindh Technical Education &

Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk



	vvebsite;	nttp://www.stevt	a.gos.pk	
11.	Plaster 3/8" thick: Cement Plaster 1:4 upto 12ft	36000.00	%Sft	
12.	height 3/8" thick.			
	MAIN GATE: Providing and fixing iron steel gate of approved design.	2.00	Each	
13.	<u>CHALK:</u>			
	Primary coat of chalk under distemper	32000	%Sft	
14.	DISTEMPERING:			
:	Distempering 3 Coats	16000	%Sft	
15.	WEATHER SHIELD : Preparing the surface and painting with weather shield of approved make including rubbing the surface etc complete.	12000	%Sft	
16.	PAINTING GUARD			
	BARS: Preparing the surface and	İ		
	painting with guard bars of grating iron rails 2 coats.			
			TOTAL AMOU	NT
		······		

Signature of Contractor

Employment through Skill



Ť

ź

2

Sindh Technical Education & Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk



## **BILL OF QUANTITIES**

### REPAIR AND RENOVATION OF GOVERNMENT VOCATIONAL SCHOOL (GIRLS) SEHWAN SHARIF, DIST. JAMSHORO.



Sindh Technical Education & Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: <u>http://www.stevta.gos.pk</u>



### REPAIR & RENOVATION WORK OF GOVERNMENT VOCATIONAL SCHOOL (GIRLS) SEHWAN SHARIF DIST. JAMSHORO.

#### BILL OF QUANTITY

<b>S.</b> #	NAME OF ITEM	QUANTITY	UNIT	RATE	AMOUNT
01.	REMOVAL OF PLASTER:				
	Removing cement or lime plaster. (page No.13, Item No.33)	14303.00	%Sft		
02.	FLOATING COAT Applying floating coat of cement (Page No52,Item No.14)	14303.00	%Sft		
03.	Plaster 3/8" thick: Cement plaster 3/8" thick ratio 1:4 (S.No.11-a, page 51)	14303.00	%Sft	<u> </u>	
04.	Plaster ½" thick: Cement Plaster 1:4 ½" thick.	14303.00	%Sft		
05.	Marble tile flooring: Laying 1" thick white marble flooring fine dressed on the surface without winding set in mortar 1:2 including rubbing and polishing of the joints (S.No.28-a, page 42).	10270.00	P.Sft		
06.	Dismantling C.C:DismantlingCementConcretePlain1:2:4(S.No.19-c, page.10)	1150.00	%Cft		
07	<b>Stone ballast:</b> Cement Concrete brick or stone ballast 1 ½" to 2" gauge ratio 1:4:8.	5135.00	%Cft		




# Sindh Technical Education &

Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-lqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk




		nttp://www.stevt	a.gos.pk	
08	Rece Work: Reinforced cement concrete work including all labour and material except the cost of steel reinforcement and its labour for bending and binding which wil be paid separately. This rate also includes all kind of forms moulds etc. RCC work in roof slab beams columns rafts lintels and other structural members laid in situ or precast lain in position complete in all respect ration 1:2:4	390	P.Cft	
09	STEEL Reinforcement: Fabrication of mild steel rainforcement for cement concrete including cutting bending laying in position making joints and fastenings including cost of binding wire also removal of rust from bars (Item No.8-b, page No.16)	20	P.Cwt	
10.	Scraping ordinary distemper oil bound distemper or paint on walls( S.No.54-b, Page No.13)	20407.00	%Sft	
11	<b><u>CHALK:</u></b> Primary coat of chalk under distemper (S.No.22 Page.53)	20407.00	%Sft	



Vocational Training Authority (STEVTA) ST-19, block-6 Guishan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk



F	website.	nttp://www.stev	la.gos.pk	
12.	Distemper Prepairing the surface and			
	painting with distemper (S.No.24-c, page No.53)	2100.00	%Sft	
13.	Internal wall			
	<b>painting:</b> Freparing the surface and painting with matt finish including rubbing the surface with bathy (slicon carbide rubbing brick) filling the voids with zink / chalk / plaster of paris mixture, applying first coat premix making surface smooth and then painting 3 coats with matt finish of	5067.00	%Sft	
	approved make etc complete (S.No.36-b, page 54)			
14.	<u>Weather coat:</u> Preparing the surface and			
	painting with weather coat i/c rubbing the surface with rubbing brick/ sand paper filling the voids with chalk / plaster of parid and then	13240.00	%Sft	
	painting with weather coat of approved make (S.No.38A&B,Page.55)			
15.	<b><u>C.C Topping:</u></b> Providing and laying 2" thick topping cement concrete 1:2:4 including surface finishing and diiding into panels	13240.00	%Sft	



e



•

Vocational Training Authority (STEVTA) ST-19, block-6 Gulshan-e-Iqbal, Near NIPA, Karachi. Phone No. 99244112-7 Fax No. 99244118 Website: http://www.stevta.gos.pk



<b>Steel Doors:</b> Making and fising steel grated door with 1/16" tick			
heeting including angle iron rame 2"x2"x3/8" and ¾" quare bars 4" center to enter with locking mrangement (S.No.24, page.91)	112.00	P.Sft	
<b>illing earth:</b> illing watering and ramming arth under floor with new arth excavated from outside ead upto one chain and lift pto 5ft (S.No.4, page.4)	24500.00	%0Cft	
<b>Iectrification:</b> omplete electrical work of uilding as board sheets witches lighting overhauling f fan etc wiring distribution oard etc with all accessories omplete in all respect as per astructions of the Engineer.	1.00	L/S	
<b>Iumbing Work:</b> omplete Plumbing work of uilding as piping bathroom epairing washbasin we flush ink etc complete in all espect as per instruction of he Engineer	1.00	L/S	
	·····	TOTAL AN	IOUNT
	rame 2"x2"x3/8" and ¾" quare bars 4" center to enter with locking rrangement (S.No.24, age.91) illing earth: illing watering and ramming arth under floor with new arth excavated from outside ead upto one chain and lift pto 5ft (S.No.4, page.4) lectrification: omplete electrical work of uilding as board sheets witches lighting overhauling f fan etc wiring distribution bard etc with all accessories omplete in all respect as per structions of the Engineer. lumbing Work: omplete Plumbing work of uilding as piping bathroom pairing washbasin we flush nk etc complete in all spect as per instruction of	rame 2"x2"x3/8" and ¾" quare bars 4" center to enter with locking rrangement (S.No.24, age.91) <u>illing earth:</u> illing watering and ramming arth under floor with new arth excavated from outside ead upto one chain and lift pto 5ft (S.No.4, page.4) <u>lectrification:</u> omplete electrical work of uilding as board sheets witches lighting overhauling f fan etc wiring distribution oard etc with all accessories omplete in all respect as per structions of the Engineer. <u>lumbing Work:</u> omplete Plumbing work of uilding as piping bathroom pairing washbasin we flush nk etc complete in all spect as per instruction of	rame2"x2"x3/8"and%"quarebars4"centertoenterwithlockingrrangement(S.No.24,age.91)illing earth:illing watering and ramming arth under floor with new arth excavated from outside read upto one chain and lift pto 5ft (S.No.4, page.4)24500.00lectrification: omplete electrical work of uilding as board sheets witches lighting overhauling f fan etc wiring distribution pard etc with all accessories omplete in all respect as per structions of the Engineer.1.00L/Slumbing Work: omplete Plumbing work of uilding as piping bathroom pairing washbasin we flush nk etc complete in all spect as per instruction of he Engineer1.00L/S

Signature of Contractor