



KARACHI WATER & SEWERAGE BOARD

OFFICE OF THE DIRECTOR (DESIGN & ESTIMATE)

BID EVALUATION REPORT


1	Name of Procuring Agency:	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No:	SPPRA Serial No.37095 I.D No. _____
3	Tender Description/Name of Work/Item:	REPAIR OF LEAKAGES ON 15" DIA, 18" DIA PRCC PIPE LINE & P/L AND JOINTING OF 90MM P.E PIPE TO REPAIR OLD DAMAGED LINE IN SECTOR 48-C KORANGI DIVISION
4	Method of Procurement:	<u>Single Stage (One Envelop)</u>
5	Tender Published:	<u>Through SPPRA Web Site</u>
6	Total Bid Documents Sold:	<u>2 Nos</u>
7	Total Bid Received:	<u>2 Nos</u>
8	Technical Bid Opening Date (if applicable):	<u>N/A</u>
9	No. of Bid Technically Qualified (if applicable)	<u>N/A</u>
10	Bid (s) Rejected:	<u>NIL</u>
11	Financial Bid Opening Date:	20-03-2019

12 BID EVALUATION REPORT


S#	Name of Firm / Bidder	COST OFFERED BY THE BIDDER	RANKING IN TERMS OF COST	COMPARISON WITH ESTIMATED COST	REASON FOR ACCEPTANCE / REJECTION	REMARKS
1	M/s.Salamat Khan & Sons	Rs.9,88,545/-	1 st Lowest	@0.020% Below	Pay Order and required documents are attached. P.O # 01014312 dt:17-01-2018 Rs.20,000/-from Bank of Khyber IBB Metroville Branch Karachi	Substantially Responsive
2	M/s.Raheem Dad & Sons	Rs.9,90,542/-	2 nd Lowest	@0.182% Above	Pay Order and required documents are attached. P.O # 01014314 dt:17-01-2018 Rs.20,000/-from Bank of Khyber IBB Metroville Branch Karachi	Substantially Responsive


The all concerned bidders are being informed accordingly.


The E.E Concerned for compliance of Rule-45 of SPPRA 2010 **M/s.Salamat Khan & Sons** declared as the lowest responsive bidder by the Committee and recommended for sanction from Competent Authority.


(Nadeem Ahmed Khan)
D.A.O (Dist. Korangi)
Member / Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit – KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member


(Wajid Iqbal Siddiqui)
S.E (Dist. Korangi)
Member


(Munir Ahmed Bhatti)
Director (Design & Estimate)
Convener

COMPARATIVE STATEMENT

**Name of Work: REPAIR OF LEAKAGES ON 15" DIA, 18" DIA PRCC PIPE LINE & P/L AND JOINTING
OF 90MM P.E PIPE TO REPAIR OLD DAMAGED LINE IN SECTOR 48-C KORANGI DIVISION**

Item No	Description of Work	Estimated Cost				M/s.Salamat Khah & Sons		M/s.Raheem Dad & Sons		
		Quantity	Rate	Per	Amount	Rate	Amount	Rate	Amount	
1	Excavation for pipe line in trenches and pits in all kind of soil of murum i/c trimming and dressing sides to true alignment and shape leveling of beds of trenches to correct level and grade cutting joints holes and disposal of surplus earth within one chain as directed by Engineer Incharge providing fence guards, lights, flags sand temporary crossing for non-vehicular traffic wherever required lift upto 5 ft (1.52 m) and lead upto one chain (30.5m). 0'-5'ft	6000.00	Cft	4650.00	%0Cft	27,900.00	4649.00	27,894.00	4650.00	27,900.00
	5' to 8'	1200.00	Cft	5200.00	%0Cft	6,240.00	5190.00	6,228.00	5195.00	6,234.00
2	Providing Laying & Fixing in trenches i/c fitting jointing and testing etc. complete in all respect the high density Polyethylene P.E pipes (HDPE-100) for W/S conforming ISO 4427 DIN-8074-8075 B.S 3580 & PSI 3051 (PN-10) 90 MM	600.00	Rft	178.00	P/Rft	106,800.00	178.00	106,800.00	180.00	108,000.00
3	P/F Split Collar 9" wide on AC pipe fabricated with 1/4" thick M.S plate etc. it i/c the cost of nuts, bolts, rubber packing etc. Net Weight 12.3 Kg 8" dia	2.00	Nos	2510.00	Each	5,020.00	2508.00	5,016.00	2514.00	5,028.00
4	Providing & Fixing 0-9" long 3/8" thick M.S "Neck" to existing M.S pipe or to a split collar tee. It included the cost of fabrication and welding to the split collar tee. Net Weight 4.77 Kgs 3" Dia	2.00	Nos	895.00	Each	1,790.00	890.00	1,780.00	898.00	1,796.00
5	C.I Sluice Valve heavy pattern (Test Pressure 21.0 Kg/sq.com or 300 lb/sq.inch) (Imported). 8 Dia	1.00	No	17940.00	Each	17,940.00	17936.00	17,936.00	17944.00	17,944.00
	3" Dia	2.00	Nos	4290.00	Each	8,580.00	4286.00	8,572.00	4294.00	8,588.00
6	Fixing of sluice valve with 2 cast iron tail pieces one end flanged & other with socket i/c the cost of nut, bolts & rubber packing, labour etc complete. 8 Dia	1.00	No	2790.00	Each	2,790.00	2788.00	2,788.00	2796.00	2,796.00
	3" Dia	2.00	Nos	1254.00	Each	2,508.00	1250.00	2,500.00	1259.00	2,518.00







**Name of Work: REPAIR OF LEAKAGES ON 15" DIA, 18" DIA PRCC PIPE LINE & P/L AND JOINTING
OF 90MM P.E PIPE TO REPAIR OLD DAMAGED LINE IN SECTOR 48-C KORANGI DIVISION**

Item No	Description of Work	Estimated Cost			M/s.Salamat Khah & Sons		M/s.Raheem Dad & Sons		
		Quantity	Rate	Per	Amount	Rate	Amount	Rate	Amount
7	Full hire charges of pumping set per day i/c of wages of driver and assistant fuel or electric energy platform for placing the pump etc at lower depth with suction and delivery pipes for pumping out water found at various depth from trenches including the cost of erection and dismantling after completion of the job. Hire charges of pumping set upto 10 HP pumping out water from 10 ft deep trench	10.00	Days	1500.00	P/Day	1495.00	15,000.00	1500.00	15,000.00
8	Construction of Block Masonry chamber with 24"x24" C.I Cover and frame weight 65 Kg fix in RCC 1:2:4 slab 6" thick with steel 1/2" dia tor main bars @6" C/C bentup 1/4" dia 8" C.C distribution bars B/M wall set 1:6 cm 6" thick C.C 1:4:8 in foundation 2" thick CC 1:2:4 flooring 1/2" thick 1-0 to al in side wall surfaced top & bottom slab outer side wall surface 1-0 deep upto roof slab i/c M.S footrest 5/8" dia bars at every 2-0 deep i/c curing de-watering excavation refilling & disposal of surplus of earth etc complete. Chamber size 4'x4'x4'	3.00	Nos	28357.00	Each	28353.00	85,071.00	28365.00	85,095.00
9	Repairing of leaking joints (External Vatta) on PRCC pipe of various diameter it i/c the cost of Excavation, labour, sealing material, gunny bags, de-watering & refilling of the excated stuff etc. 15" dia	32.00	Nos	10729.00	Each	10728.00	343,328.00	10734.00	343,488.00
	18" Dia	25.00	Nos	13841.00	Each	13840.00	346,025.00	13856.00	346,400.00
10	Refilling the excavated stuff in trenches 6" thick layer i/c watering rramming to full compaction etc complete.	7157.61	Cft	2760.00	%0Cft	2756.00	19,755.00	2760.00	19,755.00
	TOTAL QUOTED / CORRECTED COST						988,747		990,542

(Nadeem Ahmed Khan)
D.A.O (Dist.Korangi)
Member / Secretary

(Saif-ul-Haque)
Addl. Director Internal
Audit KMC - Member

(Magsood/Ahmed Shaikh)
Superintending Engineer (K.M.C)
Member

(Wajid Iqbal Siddiqui)
S.E (Dist. Korangi)
Member

(Munir Ahmed Bhatti)
Director (Design & Estimate)
Convener

Method of Procurement: Single Stage Single Envelope.

Name of Work: REPAIR OF LEAKAGES ON 15" DIA, 18" DIA PRCC PIPE LINE & P/L AND JOINTING OF 90MM P.E PIPE TO REPAIR OLD DAMAGED LINE IN SECTOR 48-C KORANGI DIVISION

MINUTES OF BID OPENING MEETING.


A meeting of the procurement committee of this department was held on 20-03-2018 for opening the bids received in respect of subject NIT till deadlines of submission. The meeting was attended by all / following members of the procurement committee and the representative of bidders. (Attendance sheet is enclosed).

2. Two bidders submitted their bids till the deadline of submission.
 - i. M/s.Salamat Khan & Sons
 - ii. M/s.Raheem Dad & Sons
3. The bids were opened at 2:30 P.M in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee.


S. No	Name of Firm	Quoted Price	Amount of Bid Security	Pay Order No. / Date
01	M/s.Salamat Khan & Sons	Rs.9,88,545/-	Rs.20,000/-	P.O # 01014312 dt:17-01-2018 from Bank of Khyber IBB Metroville Branch Karachi
02	M/s.Raheem Dad & Sons	Rs.9,90,542/-	Rs.20,000/-	P.O # 01014314 dt:17-01-2018 from Bank of Khyber IBB Metroville Branch Karachi


4. The bids do not contain any cutting or over-writing.
5. The committee shall examine all the bids as per the qualification / eligibility criteria provided in the bidding document and verify the documents and bid security submitted by the bidders (if required).


The meeting ended with the vote of thanks to and from the chair.


(Nadeem Ahmed Khan)
D.A.O (Dist. Korangi)
Member / Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit – KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member


(Wajid Iqbal Siddiqui)
S.E (Dist. Korangi)
Member


(Munir Ahmed Bhatti)
Director (Design & Estimate)
Convener

Method and procedure of procurement: Open Competitive Bidding (National/ International Competitive Bidding) (Single Stage-One Envelope)


Description of work: **REPAIR OF LEAKAGES ON 15" DIA, 18" DIA PRCC PIPE LINE & P/L AND JOINTING OF 90MM P.E PIPE TO REPAIR OLD DAMAGED LINE IN SECTOR 48-C KORANGI DIVISION**

Date of Opening: 20-03-2018


BIDDERS' ELIGIBILITY/ QUALIFICATION REPORT


Eligibility/ Qualification Criteria:

S. No.	Eligibility / Qualification Criteria	Bidders' Name	
		M/s.Salamat Khan & Sons	M/s.Raheem Dad & Sons
1.	Registration with PEC (if applicable)	N/A	N/A
2.	NTN	Yes	Yes
3.	Sales Tax Registration (FBR)	N/A	N/A
4.	Registration with Sindh Revenue Board (SRB)	Yes	Yes
	Qualification Criteria:		
5.	Minimum three years' experience of relevant field.	Yes	Yes
6.	Turnover of at least last three years	Yes	Yes
7.	Required Bid Security is attached.	Yes	Yes
8.	Bid is signed, named and stamped by the authorized person of the firm along with Authorization letter.	Yes	Yes
9.	Any other factor deemed to be relevant by the procuring agency subject to provision of Rule-44	N/A	N/A
10.	Qualified/ disqualified	Qualified	Qualified


(Nadeem Ahmed Khan)
D.A.O (Dist. Korangi)
Member / Secretary


(Saif-ul-Haque)
Additional Director Internal
Audit – KMC Member


(Maqsood Ahmed Shaikh)
Superintending Engineer (KMC)
Member


(Wajid Iqbal Siddiqui)
S.E (Dist. Korangi)
Member


(Munir Ahmed Bhatti)
Director (Design & Estimate)
Convener

