KARACHI WATER AND SEWERAGE BOARD

OFFICE OF THE EXECUTIVE ENGINEER CIVIL E&M-SEWAGE/SPD Behind Block "A" 9th mile Karsaz Shahra-e-Faisal,KARACHI.

No: EE/CIVIL/E&M-SEW/STP-II/NIT/2017/ 77

Dated:18.05.2017

The Assistant Director (Assessment), SPPRA, Block-8, 4-A Sindh secretariat, Karachi.

SUBJECT: NIT: EE/CIVIL/E&M-SEW/STP-II/NIT/2017/25 DATED- 12.04.2017


REHABILITION / REPLACDEMENT OF DEFECTED SEWERAGE SYSTEM 12",8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD.

In response of the above referred the matter under subject, I am enclosing herewith the documents, as under for your kind perusal. under Rule 45 & 50 of SPPRA website Sr.No.32727.

EXECUTIVE ENGINEER CIVIL E&M-SEW/STP-II K.W& S.B

Encl:-

- 1- BID EVALUATION REPORT IN ORIGINAL
- 2- MINUTES OF BID OPENING MEETING
- 3- COMPARATIVE STATEMENT
- 4- BIDDER'S ELIGIBILITY/ QUALIFIACATION REPORT
- 5- ATTENDANCE SHEET ORIGINAL
- 6- ESTIMATE FORM





KARACHI WATER & SEWERAGE BOARD OFFICE OF THE DIRECTOR (DESIGN & ESTIMATE)

BID EVALUATION REPORT

	To a second seco	
1	Name of Procuring Agency:	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No:	SPPRA Serial No.32727 I.D No
3	Tender Description/Name of Work/Item:	REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD
4	Method of Procurement:	Single Stage (One Envelop)
5	Tender Published:	Through SPPRA Web Site
6	Total Bid Documents Sold:	<u>3 Nos</u>
7	Total Bid Received:	<u>3 Nos</u>
8	Technical Bid Opening Date (if applicable):	N/A
9	No. of Bid Technically Qualified (if applicable)	<u>N/A</u>
10	Bid (s) Rejected:	<u>01 No</u>
11	Financial Bid Opening Date:	04-05-2017

12 **BID EVALUATION REPORT**

S#	Name of Firm / Bidder	COST OFFERED BY THE BIDDER	RANKING IN TERMS OF COST	COMPARIS ON WITH ESTIMATED COST	REASON FOR ACCEPTANCE / REJECTION	REMARKS
1.	M/s.Orange Star Executors	Rs.9,77,038/-	1 st Lowest	@0.136% Below	Pay order and other required documents are available. P.O # 03377351 dt: 27-04- 2017 Rs.20,000/- from Meezan Bank Gulberg Branch Karachi	Substantially Responsive
2	M/s.Aqeel Enterprises	Rs.9,84,037/-	2 nd Lowest	@0.579% Above	Pay order and other required documents are available. P.O # 03377350 dt: 27-04- 2017 Rs.20,000/- from Meezan Bank Gulberg Branch Karachi	Substantially Responsive
3	M/s.Serena Enterprises	Not Quoted	-	-	Pay order not attached, required documents are available.	Un Responsive

The all concerned bidders are being informed accordingly.

The E.E Concerned for compliance of Rule-45 of SPPRA 2010 M/s.Orange Star Executors declared as the lowest responsive bidder by the Committee and recommended for sanction from Competent Authority.

(Khuwaja Muhammad Ahmed) Accounts Officer (E&M-Sew)

Member / Secretary

Additional Director Internal Audit - KMC Member

(Magsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

(Manzoor Ali Khatri) S.E (TPs Circle) Members

Director (Design & Estimate) Convener

NIT No. SPPRA Serial No. 32727

Method and procedure of procurement: Open Competitive Bidding (National/ International Competitive Bidding) (Single Stage-One Envelope)

REHABILITATION / REPLACEMENT OF DEFECTED Description of work:

SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA **SEWERAGE** TP-II BADLY SILTED LINE

MEHMOODABAD

Date of Opening:

04-05-2017

BIDDERS' ELIGIBILITY/ QUALIFICATION REPORT

Eligibility/ Qualification Criteria:

S.		E	Bidders' Name	
No.	Eligibility / Qualification Criteria	M/s.Orange Star Executors	M/s.Aqeel Enterprises	M/s.Serena Enterprises
1.	Registration with PEC (if applicable)	N/A	N/A	N/A
2.	NTN	Yes	Yes	Yes
3.	Sales Tax Registration	N/A	N/A	N/A
4.	Registration with Sindh Revenue Board (SRB)	Yes	Yes	Yes
	Qualification Criteria:			
5.	Minimum three years' experience of relevant field.	Yes	Yes	Yes
6.	Turnover of at least last three years	Yes	Yes	Yes
7.	Required Bid Security is attached.	Yes	Yes	No
8.	Bid is signed, named and stamped by the authorized person of the firm along with Authorization letter.	Yes	Yes	Yes
9.	Any other factor deemed to be relevant by the procuring agency subject to provision of Rule-44	N/A	N/A	N/A
10.	Qualified/ disqualified	Qualified	Qualified	Disqualified

(Khuwaja Muhammad Ahmed) Accounts Officer (E&M-Sew)

Member / Secretary

(Saif-ul-Haque) Additional Director Internal Audit - KMC Member

(Maqsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

(Manzoor Ali Khatri) S.E (TPs Circle) Members

(Saleem Ahmed) Director (Design & Estimate)

Convener

NIT Sr. No. SPPRA Serial No.32727

Method of Procurement:

Single Stage Single Envelope.

Name of Work: REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD

MINUTES OF BID OPENING MEETING.

A meeting of the procurement committee of this department was held on 04-05-2017 for opening the bids received in respect of subject NIT till deadlines of submission. The meeting was attended by all / following members of the procurement committee and the representative of bidders.

(Attendance sheet is enclosed).

- Three bidders submitted their bids till the deadline of submission. 2.
 - M/s. Orange Star Executors
 - M/s. Ageel Enterprises ii.
 - M/s.Serena Enterprises iii.
- 3. The bids were opened at 2:30 P.M in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee.

S. No	Name of Firm	Quoted Price	Amount of Bid Security	Pay Order No. / Date
1.	M/s.Orange Star Executors	Rs.9,77,038.35	Rs.20,000/-	P.O # 03377351 dt: 27-04-2017 from Meezan Bank Gulberg Branch Karachi
2.	M/s.Aqeel Enterprises	Rs.9,83,520.44	Rs.20,000/-	P.O # 03377350 dt: 27-04-2017 from Meezan Bank Gulberg Branch Karachi
3	M/s.Serena Enterprises	Not Quoted	-	Pay Order not attached

- The bids do not contain any cutting or overwriting. 4.
- 5. The committee shall examine all the bids as per the qualification / eligibility criteria provided in the bidding document and verify the documents and bid security submitted by the bidders (if required).

The meeting ended with the vote of thanks to and from the chair.

(Khuwaja Muhammad Ahmed) Accounts Officer (E&M-Sew)

Member / Secretary

(Saif-ul-Haque) Additional Director Internal Audit - KMC Member

(Magsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

(Manzoor Ali Khatri) S.E (TPs Circle)

Members

Director (Design & Estimate)

Convener

COMPARATIVE STATEMENT

Name of Work: REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD

Item No	Description of Work			Estimated	Cost			ange Star cutor		.Aqeel rprises
140		Quanti	ty	Rate	Per	Amount	Rate	Amount	Rate	Amount
1	Scarifying the existing road surface	2580.00	Sft	116.16	%Sft	2,996.93	116.00	2,992.80	120.00	3,096.00
2	Dismantling and removing road metalling etc.	2580.00	Cft	605.00	%Cft	15,609.00	605.00	15,609.00	608.00	15,686.40
3	Excavation for pipe line in trenches and pits in all kind of soils									
	of murum i/c trimming and dressing sides to true alignment and									
	shape leveling of beds of trenches to correct level and grade									
	cutting joints holes and disposal of surplus earth within one									
	chain as directed by Engineer Incharge providing fence guards,									
	lights, flags sand temporary crossing for non-vehicular traffic									
	wherever required lift upto 5 ft (1.52 m) and lead upto one chain									
	(30.5m). Lift 0' - 5'ft	5160.00	Cft	4650.00	%0Cft	23,994.00	4645.00	23,968.20	4650.00	23,994.00
4	Excavation for pipe line in trenches and pits in Wet Soils, clay or									
	mud i/c trimming and dressing sides to true alignment and shape									
	leveling of beds of trenches to correct level and grade cutting									
	joints holes and disposal of surplus earth within one chain as									
	directed by Engineer Incharge providing fence guards, lights,									
	flags sand temporary crossing for non-vehicular traffic wherever									
	required lift upto 5 ft (1.52 m) and lead upto one chain (30.5m).									
	Lift upto 0' to 5'	5160.00	Cft	5400.00	%0Cft	27,864.00	5400.00	27,864.00	5410.00	27,915.60
5	Providing & Laying of RCC Pipes with Rubber Ring Joint and									
	fitting in trench including cutting, fitting, jointing with rubber					₹'	4			
	ring i/c testing with water to specified pressure. 12" Dia Pipe	520.00	Rft	367.00	P/Rft	190,840.00	366.00	190,320.00	368.00	191,360.00
	08" Dia Pipe	408.00	Rft		P/Rft	84,048.00	206.00	84,048.00	208.00	84,864.00

A.O. (E&M) SEW (Member/secretary)

Addl. Dir. Internal Audit-KMC (Member).

S.E. (KMC) (Member) Director D/E
Convener/Chirman

S.E.(E&M) SEW

(Member)

Name of Work: REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD

Item No	Description of Work			Estimated			Exe	cutor Entery		.Aqeel rprises
6	Providing manhole 4' feet (inside) and 5 feet clear depth with C.I Frame (15 Kg) cast in situ with 1:2:4 CC in 9" thick wall, 1:4:8: C.C in 6ft dia and 6" inch thick in foundation 1:2:4 C.C in benching 12" thick cement plastering with 1:3 C.M on all inside wall surfaces, channel and benching i/c making required nos of main and branch channels, 3/4" dia m.s foot rest @12" c/c i/c cost of excavation in all kinds of soil, backfilling and disposal of	Quan	tity	Rate	Per	Amount	Rate	Amount	Rate	Amount
	excavated stuff etc complete as per design and instruction of engineer incharge.	16.00	Nos	14529.29	Each	232,468.64	14529.00	232,464.00	14530.00	232,480.00
7	Full hire charges of pumping set per day i/c of wages of driver and assistant fuel or electric energy platform for placing the pump etc at lower depth with suction and delivery pipes for pumping out water found at various depth from trenches including the cost of erection and dismantling after completion of the job. Hire charges of pumping set upto 10 HP pumping out water from 10 ft deep trench		Day s	1500.00	P/Day	24,000.00	1500.00	24,000.00	1550.00	24,800.00
8	Making connection with the existing manhole including the cost of cutting hole in wall, making them good in C.C 1:2:4 and making the required channel etc. complete		Nos	180.00	Each	3,600.00	178.00	3,560.00	180.00	3,600.00
9	Manufacturing and supplying of RCC Ring Slab of 21" dia (inside) and 36" dia outside 7.5" width and 6" thick i/c 3/8" dia tor steel bars two concentric rings with 3/8" dia 8 Nos cross linked bars welded and two sunk type hooks, casted in 1:1 1/2"3 concrete with embedded 15 Kg C.I Frame in perfect position i/c transportation charges for an average lead of 20 Km per trip from casting yard to town office. (A minimum of 25 slabs per trip will be transported.		Nos	1906.60	Each	38,132.00	1906.00	38,120.00	1910.00	38,200.00

A.O. (E&M) SEW (Member/Secretary) S.E. (KMC) (Member) Addl. Dir. Internal Audit-KMC (Member). Director D/E

Director D/E Convener/Chirman S.E.(E&M) SEW (Member)

Name of Work: REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD

Item No	Description of Work			Estimated	Cost			ange Star ecutor		Aqeel rprises
140		Quant	tity	Rate	Per	Amount	Rate	Amount	Rate	Amount
10	Shifting to the site and Fixing of 36" dia Ring Slab in									
	perfect position on damaged manholes i/c cutting of the									
	position of damaged manhole in layer of C.M in 2"									
	thickness and disposal of debris.	20.00	Nos	563.09	Each	11,261.80	563.00	11,260.00	565.00	11,300.00
11	Manufacturing and supplying of 21" dia RCC Manhole covers						il.			
	cast in situ 1:2:4 concrete ratio 3" deep at centre, reinforced						1			
	with 1/2" dia tor steel bars at 4" C/C welded to a 3/16" thick 2"									
	wide M.S plate two hook of 3/8" dia tor bar including									
	compacting i/c cutting and transportation with in 10 miles. 21"									
	dia cover.	36.00	Nos	913.63	Each	32,890.68	913.00	32,868.00	915.00	32,940.00
12	Sand Haro or any other source sand of same modules of the									
	fineness (Hill Sand)	4692.00	Cft	2425.00	%Cft	113,781.00	2424.00	113,734.08	2450.00	114,954.00
13	Refilling the excavated stuff in trenches 6" thick layer i/c									
	watering ramming to full compaction etc complete.	8208.00	Cft	2760.00	%0Cft	22,654.08	2760.00	22,654.08	2760.00	22,654.08
14	Carriage of 100 Cft / 5 Tons of all matrials like stonne aggregate,									
	spawl, coal, lime, surkhi etc B.G Rail fastening points and									
	crossing bridges, Girders, pipes sheet Rail, M.S Bars etc. or									
	1000 Nos bricks, 10"x 5"x3" or 1000 Nos: tiles, 12" x6"x2" or	ı								
	150 Cft of timber or 100 Maunds of fuel wood by trucks or any									
	other means owned by the Contractors.									
	Carriage for 05 Miles and subsequent mile	7257.17	Cft	714.29	%Cft	51,837.24	714.00	51,816.19	715.00	51,888.77

A.O. (E. W. SEW (Member/Gecretary)

S.E. (KMC) (Member) Add. Dir. Internal Audit-KMC (Member).

> Director D/E Convener/Chirman

S.E.(E&M) SEW (Member)

Name of Work: REHABILITATION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12", 8" DIA RCC PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" DIA BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD

Item No	Description of Work		Estimate	imated Cost			M/s.Orange Star Executor		M/s.Aqeel Enterprises	
140		Quantity	Rate	Per	Amount	Rate	Amount	Rate	Amount	
15	Cleaning inside Sewerage line completely restoring original silt									
	free space / diameter of pipe lines by labour and equipment									
	(Mechanically / Electrically driven). Including accessories like					A I				
	pulley's steel rope, buckets and draggers sizing from 6" to 18"					15				
	dia their "to and fro" pulling action (No of passes shall be as		1							
	many as required) would be undertaken in two phases (First					(-)				
	phase entire length from down stream to up stream) bringing		1							
	down peak hours sewage to flow inside pipe line (as free flow)		1							
	and in 2nd phase from up stream to down stream of entire length					/				
	using no silt to observed in bucket (6" dia to 18" dia) except only		1							
	sewage water finally passing a ball of 12" lesser then the									
	diameter of pipe but no exceeding 48" dia ball even for larger dia					1				
	pipe to ensure perfect cleaning. The job including all the hire /									
	cost of equipment and accessories of above wincing machine /									
	devises alongwith / Engine with winching drum set having, steel					1				
	rope pulley mounted over it, steel bucket 6" to 18" dia hocks and					1				
	other protection like safety barriers, traffic signs, traffic cones					1 4				
	ensuring no damages to pipe line alongwith ensuring safety to									
	labourand other public property / lives and removla of silts /								7	
	solid during desilting and clearance of site etc complete as per					3				
	full satisfaction of site Engineer. 12" dia	1272.00 R	ft 80.50	P/Rft	102,396.00	80.00	101,760.00	82.00	104,304.00	
	TOTAL QUOTED / CORRECTED COST				978,373		977,038		984,037	

(Khuwaja Muhammad Ahmed) Accounts Officer (E&M-Sew) Member / Secretary (Saif-ul-Haque) Additional Director Internal Audit – KMC Member (Maqsood Ahmed Shaikh) Superintending Engineer (KMC) Member (Manzoor Ali Khatri) S.E (TP's Circle) Member

(Saleem Ahmed)//P Durectir (Design & Estimate)

Convener

ATTENDANCE SHEET

Seli) VENUE:-	Rehabilition Affla Man 12 Solve Ace for This of 12 oct is said DIRECTOR DESIGN & ESTIMATE AT N CONTRACTOR CONTRACTOR	EAR COD HILL FILTER PLA	ANT KW&SB. Melines Solo
SR.NO	NAME OF FIRM/BIDDER	CONTACT NO	SIGNATURE / 0
01	Agreel Enterprise.	03008999606	Asser After
	SERENA ENTER DRISES		
03	orange Star	Exceedors 33332192143	864.

KARACHI WATER AND SWERAGE BOARD OFFICE OF THE EXECUTIVE ENGINEER CIVIL E&M-SEW/STP-II **BILL OF QUANTITY**

NAME OF WORK: REHABILITION / REPLACEMENT OF DEFECTED SEWERAGE SYSTEM 12" DIA & 8" DIA R.C.C PIPE AT TP-II MEHMOODABAD INCLUDING DE-SILTING OF 12" BADLY SILTED SEWERAGE LINE AT TP-II MEHMOODABAD.

	SIETED SEWERAGE EINE AT T				
3	Description of Work	Qty	Rate Rs	Per	Total (Rs)
1	Scarifying the existing road surface	2580sft	116/	% sft	2992,80
2	Dismantling and removal road matling	2580cft	(605)	⁰/o cft	15609-0
3	Excavation for pipe line in trenches and pits in all kinds of soils of murmur including trimming and dressing sides to true alignment and shape leveling of beds of trenches to correct level and grade, cutting joints holes and disposal of surplus earth within a one chain as directed, providing fence guards, lights, flags, temporary crossing for non-vehicular traffic where ever required lift upto 5' and lead upto one chain. 0' to 5'	5160 ft (46457	%0 cft	239681
1	Excavation for pipe line in trenches and pits in wet soils, clay or mud including trimming and dressing sides to true alignment and shape leveling of beds of trenches to correct level and grade, cutting joints holes and disposal of surplus earth within a one chain as directed, providing fence guards, lights, flags, temporary crossing for non-vehicular traffic where ever required lift upto 5' and lead upto one chain. 0' to 5'	5160 ft	5400		27864-
5	Providing & laying of RCC pipe with rubber ring joints and fitting in trenches including cutting, fitting and jointing with rubber ring i/c. testing with water to specified pressure. 12 " dia pipe 8 " dia pipe	520 Rft 408 Rft	366/	P/Rft	190320.
5	Providing manhole 4 ft dia (inside) and 5ft clear depth with C.I frame (15 kg) cast in situ with 1:2:4 C.C in 9" thick wall, 1:4:8 C.C in 6ft dia and 6" inch thick in foundation 1:2:4 C.C in benching, ½" thick cement plastering with 1:3 C.M on all inside wall surfaces, channel and benching i/c making required Nos of main and branch channels, ¾" dia M.S footrest @ 12" c/c i/c cost of excavation in all kinds of soil, back filling and disposal of excavated stuff etc complete.	16Nos.	14529/		232464,

S.	Description of Work	Qty	Rate Rs	Per	Total (Rs)
7	Full hire charges of pumping set per day inclusive of wages of driver and assistant fuel electric energy plates etc at lower depth with suction and delivery pipes for pumping out water found at various depth from trenches i/c. the cost of errection and dismantling after completion of job of above set of 10 HP pumping				
	out of water from 10' deep trenches.	16days(1500/	p/day	24000-
S	Making connection with the existing manhole i.c the cost of cutting holes in wall, making them good in C.C 1:2:4 and making required channel etc	20Nos.	178]	each	3560-
9	Manufacturing & supplying of RCC Ring slabs of 21" dia (inside) 36" dia out sides), 7.5 width and 6" thick i/c. 3/8" dia tor steel bars two concentric rings with 3/8" dia 8 Nos cross linked bars welded and two sunk type hooks casted in 1:1 ½" 3 concrete with embedded 15 kg C.I frame in perfect position i/c. transportation charges for an average lead of 20 km per trip from casting yard to town office (A minimum of 25 slabs per trip will be transported).	20Nos.	19061	each	38120-
10	Shifting to the site and fixing of 36" dia (outer) Ring slab in perfect position on damaged manholes i/c. cutting of damaged portion of manhole in proper shape and laying of cement mortar of 2" thickness and disposal of the dbris.	20Nos.	563/-	each	11260.
11	Manufacturing & supplying of RCC manhole covers cast in 1:2:4 cement concrete ratios 3" deep at center reinforced with ½" dia tor steel bars @4" c/c welded to a 3/16" thick 2" wide M.S plate and two hook of 3/8" dia tor bars including compacting, curring and transportation within 10 miles. 21" dia	36Nos.	913/	each	32868
12	Sand Haro or any other source sand of same modulus of the fineness (hill sand).	4692cft	2424/	% cft	11373
1.3	Refilling the excavated stuff in trenches 6" thick layer i.c watering ramming to full compaction etc.	8208cft	2760)	%0 cft	22654
14	Carriage of 100 cft 5 ton of all materials like stone aggregate, spawl coal, lime, surkhi etc. B.G rail fastening points and crossing bridges, girders, pipe sheet rail, M.S bars etc. or 1000 Nos tiles 12 x 6"x2" or 150 cft of timber or 100 maunds of fuel wood by trucks or any other means owned by the contractors. Carriage for 5 th mile.	7257.17 cft	714) % cft	51816

Description of Work	Qty	Rate Rs	Per	Total (Rs)
Cleaning inside sewerage line con restoring original silt free space / diam pipe line by labor and equipment (mechan electrically driven) i.c accessories like steel ropes, buckets and dredgers sizing for to 18" dia their to and from "pulling action passes shell be as many as required) who under taken in two faces(1st phase entire downstream to upstream) bringing down hours sewerage to flow inside pipe line flow) and in 2nd face from upstream observed in buckets (6" dia to 18" dia excessewerage water and finally passing a stee dia 12" less than the diameter of pipe. exceeding 48" dia ball even for larger dia to insure perfect cleaning. The job i/c all / cost of equipment and accessories of winching machine / devises along with / with winchig drum sets having steel rope mounted over it, steel bucket from 6" did dia hocks and other protection like barriers, traffic signs, ensuring no dampipe line along with ensuring safety to and other public property / lives and rem silt / solid during desalting and clearance etc complete.12" dia Pipe	neter of nically / pulleys, rom 6 " n(No of pulley ball of as free ann to posit is ept only ball of But no of pipe the hire above engine pulley a to 18" safety nage to labour toval of of site	80/	P/Rft	101,760
The state of the s	10	tal amount R	s. 97	70787

Executive Engineer Civil/ STP-II KW&SB

977 638, 3 for execution of I/we hereby quoted Is: above mentioned work and bind to comply the rules f KW&SB

1-Termin/Questaria ... Lived in sealed Cover : and open by refore obaning Committee.

2-No cutting as averaging found/cutting averwriting found.

ator has enclosed Earnest money

ator has enclosed Earnest money

amount pay order Rs: 30 Milling

At 1332235)

Dt: 22 Milling

sctor M/s: 1 10 m/se Tax (secundar)

acted Rs: 127.138.255

es: 121.1 / 4c Sazaty. June themse g /g Shirts five

Signature of Contractor

With name of the firm

s. Orange Star Scecutors

LO. (E&M) SEW

S.E. (E&M) Seut (Member)

Internal Audit-KMC