


## COMPARATIVE STATEMENT


**Name of Work: REPAIRING & MAINTENANCE OF 36" DIA BROKEN / BURST MANIFOLD AT JAMILA PUMPING STATION (SPD-I)  
KW&SB**


Item No	Description of Work	Estimated Cost				M/s.H.R Brothers		M/s.Al-Hannan Builders		
		Quantity	Rate	Per	Amount	Rate	Amount	Rate	Amount	
1	Excavation for pipe line in trenches and pits in Wet Soil clay or mud i/c trimming and dressing sides to true alignment and shape leveling of beds of trenches to correct level and grade cutting joints holes and disposal of surplus earth within one chain as directed by Engineer Incharge providing fence guards, lights, flags sand temporary crossing for non-vehicular traffic wherever required lift upto 5 ft (1.52 m) and lead upto one chain (30.5m). 0' - 5'ft	3250.00	Cft	5400.00	%0Cft	17,550.00	5000.00	16,250.00	5100.00	16,575.00
	5' to 8'	1596.43	Cft	5950.00	%0Cft	9,498.76	6000.00	9,578.58	6120.00	9,770.15
	8' to 11'	1596.43	Cft	6500.00	%0Cft	10,376.80	6750.00	10,775.90	6817.00	10,882.86
2	Full hire charges of pumping set per day i/c of wages of driver and assistant fuel or electric energy platform for placing the pump etc at lower depth with suction and delivery pipes for pumping out water found at various depth from trenches including the cost of erection and dismantling after completion of the job. Hire charges of pumping set upto 10 HP pumping out water from 10 ft deep trench	24.00	Day	1500.00	P/Day	36,000.00	1600.00	38,400.00	1648.00	39,552.00
3	P/F M.S split collar tee on PRCC pipe of different dia sizes having with as mentioned against each item to suit. The size of connection fabricated with 3/8" thick M.S plate excluding the cost of neck, it includes the cost of 3/4" M.S square bard on both ends, 4 Nos 3/4" thick M.S flnages with a total weight as mentioned against each item it includes the cost of nuts & bolt, rubber packing, labour and sealing materials and all the tools and plants. Net Weight 454.55 Kg 36" x 36" dia (Width 4'-6").	4.00	Nos	76857.00	Each	307,428.00	76500.00	306,000.00	80325.00	321,300.00


**Name of Work: REPAIRING & MAINTENANCE OF 36" DIA BROKEN / BURST MANIFOLD AT JAMILA PUMPING STATION (SPD-I)  
KW&SB**


Item No	Description of Work	Estimated Cost				M/s.H.R Brothers		M/s.AI-Hannan Builders	
		Quantity	Rate	Per	Amount	Rate	Amount	Rate	Amount
4	Cement concrete plain including all labour and material except the cost of steel reinforcement and its labour for bedding and binding which will be paid separately. This rate also includes all kind of forms moulds. Lifting shuttering curing rendering and finishing the exposed surface (including screening and washing of shingle). Ratio (1:2:4) 90 Lbs cement 2 Cft Sand 4 Cft Shingle 1/8" to 1/4" gauge.	893.50 Cft	337.00	P/Cft	301,109.50	335.00	299,322.50	340.00	303,790.00
5	Fabrication of mild steel reinforcement for cement concrete including cutting, bedding, laying in position, making joints and fastening including cost of binding wire.	7.17 Cwt	5001.70	P/Cwt	35,862.19	5057.00	36,258.69	5000.00	35,850.00
6	Refilling the excavated stuff in trenches 6" thick layer i/c watering ramming to full compaction etc complete.	4842.86 Cft	2760.00	%0Cft	13,366.29	2770.00	13,414.72	2800.00	13,560.01
<b>TOTAL QUOTED / CORRECTED COST</b>					<b>731,192</b>		<b>730,000</b>		<b>751,280</b>

  
(Sarauallah Aleem Shaikh)  
D.A.O (S.P.D)  
Member / Secretary

  
(Saif-ul-Haque)  
Additional Director Internal  
Audit – KMC Member

  
(Maqsood Ahmed Shaikh)  
Superintending Engineer (KMC)  
Member

  
(Manzoor Ali Khatri)  
S.E (S.P Circle)  
Member

  
(Saleem Ahmed)  
Durectir (Design & Estimate)  
Convener



# KARACHI WATER & SEWERAGE BOARD

## OFFICE OF THE DIRECTOR (DESIGN & ESTIMATE)

### BID EVALUATION REPORT

1	Name of Procuring Agency :	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No:	SPPRA Serial No.34407 I.D No. _____
3	Tender Description/Name of Work/Item:	<b>REPAIRING &amp; MAINTENANCE OF 36" DIA BROKEN / BURST MANIFOLD AT JAMILA PUMPING STATION (SPD-I) KW&amp;SB</b>
4	Method of Procurement:	<u>Single Stage (One Envelop)</u>
5	Tender Published:	<u>Through SPPRA Web Site</u>
6	Total Bid Documents Sold:	<u>2 Nos</u>
7	Total Bid Received:	<u>2 Nos</u>
8	Technical Bid Opening Date (if applicable):	<u>N/A</u>
9	No. of Bid Technically Qualified (if applicable)	<u>N/A</u>
10	Bid (s) Rejected:	<u>NIL</u>
11	Financial Bid Opening Date:	04-10-2017

#### 12 BID EVALUATION REPORT

S #	Name of Firm / Bidder	COST OFFERED BY THE BIDDER	RANKING IN TERMS OF COST	COMPARIS ON WITH ESTIMATED COST	REASON FOR ACCEPTANCE / REJECTION	REMARKS
1.	M/s.H.R Brothers	Rs.7,30,000/-	1 <sup>st</sup> Lowest	@0.163% Below	Pay order and other required documents are available. P.O # 03598995 dt:30-05-2017 Rs.7,210/- & P.O # 03932157 dt:03-10-2017 Rs.7,390/- Total Rs.14,600/- from Bank Al Habib Ltd Malir Cantt Branch Karachi	Substantially Responsive
2	M/s.Al-Hannan Builders	Rs.7,51,280/	2 <sup>nd</sup> Lowest	@2.747% Above	Pay order and other required documents are available. P.O # 18298834 dt:03-10-2017 Rs.15,030/-from HBL Malir Cantt. Branch Karachi	Substantially Responsive

The all concerned bidders are being informed accordingly.

The E.E Concerned for compliance of Rule-45 of SPPRA 2010 **M/s.H.R Brothers** declared as the lowest responsive bidder by the Committee and recommended for sanction from Competent Authority.

(Sanauallah Aleem Sheikh)  
D.A.O (S.P.D)  
Member / Secretary

(Saif-ul-Haque)  
Additional Director Internal  
Audit – KMC Member

(Maqsood Ahmed Shaikh)  
Superintending Engineer (KMC)  
Member

(Manzoor Ali Khatri)  
S.E (S.P Circle)  
Members

(Saleem Ahmed)  
Director (Design & Estimate)  
Convener

NIT Sr. No. SPPRA Serial No.34407

Method of Procurement: Single Stage Single Envelope.

Name of Work: REPAIRING & MAINTENANCE OF 36" DIA BROKEN / BURST  
MANIFOLD AT JAMILA PUMPING STATION (SPD-I) KW&SB

**MINUTES OF BID OPENING MEETING.**

A meeting of the procurement committee of this department was held on 04-10-2017 for opening the bids received in respect of subject NIT till deadlines of submission. The meeting was attended by all / following members of the procurement committee and the representative of bidders.


**(Attendance sheet is enclosed).**


2. Two bidders submitted their bids till the deadline of submission.
  - i. M/s. H.R Brothers
  - ii. M/s. Al-Hannan Builders
3. The bids were opened at 2:30 P.M in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee.


S. No	Name of Firm	Quoted Price	Amount of Bid Security	Pay Order No. / Date
1.	M/s.H.R Brothers	Rs.7,29,997/-	Rs.14,600/-	P.O # 03598995 dt:30-05-2017 Rs.7,210/- & P.O # 03932157 dt:03-10-2017 Rs.7,390/- from Bank Al Habib Ltd Malir Cantt Branch Karachi
2.	M/s.Al-Hannan Builders	Rs.7,51,279/	Rs.15,030/-	P.O # 18298834 dt:03-10-2017 from HBL Malir Cantt. Branch Karachi


4. The bids do not contain any cutting or overwriting.
5. The committee shall examine all the bids as per the qualification / eligibility criteria provided in the bidding document and verify the documents and bid security submitted by the bidders (if required).

The meeting ended with the vote of thanks to and from the chair.

  
(Saiaullah Aleem Sheikh)  
D.A.O (S.P.D)  
Member / Secretary

  
(Saif-ul-Haque)  
Additional Director Internal  
Audit – KMC Member

  
(Maqsood Ahmed Shaikh)  
Superintending Engineer (KMC)  
Member

  
(Manzoor Ali Khatri)  
S.E (S.P Circle)  
Members

  
04/10/17  
(Saleem Ahmed)  
Director (Design & Estimate)  
Convener

Method and procedure of procurement: Open Competitive Bidding (National/ International Competitive Bidding) (Single Stage–One Envelope)


Description of work: REPAIRING & MAINTENANCE OF 36" DIA BROKEN / BURST MANIFOLD AT JAMILA PUMPING STATION (SPD-I) KW&SB


Date of Opening: 04-10-2017


**BIDDERS' ELIGIBILITY/ QUALIFICATION REPORT**


Eligibility/ Qualification Criteria:

S. No.	Eligibility / Qualification Criteria	Bidders' Name	
		M/s.H.R Brothers	M/s.Al-Hannan Builders
1.	Registration with PEC (if applicable)	N/A	N/A
2.	NTN	Yes	Yes
3.	Sales Tax Registration	N/A	N/A
4.	Registration with Sindh Revenue Board (SRB)	Yes	Yes
	<b>Qualification Criteria:</b>		
5.	Minimum three years' experience of relevant field.	Yes	Yes
6.	Turnover of at least last three years	Yes	Yes
7.	Required Bid Security is attached.	Yes	Yes
8.	Bid is signed, named and stamped by the authorized person of the firm along with Authorization letter.	Yes	Yes
9.	Any other factor deemed to be relevant by the procuring agency subject to provision of Rule-44	N/A	N/A
10.	Qualified/ disqualified	Qualified	Qualified

  
(Sanauallah Aleem Sheikh)  
D.A.O (S.P.D)  
Member / Secretary

  
(Saif-ul-Haque)  
Additional Director Internal  
Audit – KMC Member

  
(Maqsood Ahmed Shaikh)  
Superintending Engineer (KMC)  
Member

  
(Manzoor Ali Khatri)  
S.E (S.P Circle)  
Members

  
(Saleem Ahmed)  
Director (Design & Estimate)  
Convener

## ATTENDANCE SHEET


**NAME OF WORK:-**

S.No	NAME OF WORK
1.	Repairing & Maintenance Of 36" Dia Broken / Burst Manifold At Jamila Pumping Station SPD-II

Venue:- The Director (D&E) KW&SB, Situated At COD Filter Plant  
Block-17 Gulshan-e-Iqbal Karachi.

Date: 04-10-2017 at 2:30 PM

### CONTRACTORS/FIRMS/BIDDERS

S.No	Name Of Firms/Bidders	Contact No	Signature
	H. R. Brothers	0321-2878773	
2	Al-HANNAN BUILDERS		