NO: XEN/SDD/AB/SKP/ 605 /2016

SHIKRPUR DATED: 10 / 10 /2016

Method of Procedure of Procurement: - Opening Competitive Bidding (National Competitive Bidding) (Single Stage One Envelope)

Name of Work: -

Procurement of Goods & Services during the Year-2016-17

Name of Procuring Agency:-

Executive Engineer Shikarpur Drainage Division Shikarpur

BIDDERS QUALIFICATION REPORT

Name of Bidders	NTN No:	SRB No:	Company Profile	Responsiveness	Litigation
M/S Safdar Ali Channa.	Available	Available	Available	Available	No
M/S Saleemulah Soomro.	Available	Available	Available	Available	No
M/S Abdul Aziz Abbasi.	Available	Available	Available	Available	No
M/S Dua Enterprises.	Available	Available	Available	Available	No
M/S Aftab Ahmed Awan.	Available	Available	Available	Available	No
M/S Rafique Ahmed Soomro.	Available	Available	Available	Available	No
M/S BMB Construction Co:	Available	Available	Available	Available	No
M/S Bilal Hyder Construction Co:	Available	Available	Available	Available	No
M/S Abdul Sattar Mughal & Co:	Available	Available	Available	Available	No
M/S Zaheer & Brothers.	Available	Available	Available	Available	No

The signature of the members of procurement committee.

(Luffullah Phulpoto)
Executive Engineer

Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero



No: XEN/SDD/AB/SKP/

OFFICE OF THE EXECUTIVE ENGINEER SHIKARPUR DRAINAGE DIVISION SHIKARPUR /2016 SHIKRPUR DATED: / /2016

BID OPENING ATTENDANCE SHEET

List of participates and representative of contractors / firms which are present on the opening of Tender on 31/10/2016, at 03.00 PM for the work Procurement of Goods & Service in Shikarpur Drainage Division Shikarpur.

S No:	Name of Bidders	Signature	
1	2		
01)	M/S Safdar Ali Channa.	App.	
02)	M/S Saleemulah Soomro.	All Services of the services o	,
03)	M/S Abdul Aziz Abbasi.	Dieton	
04)	M/S Dua Enterprises.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
05)	M/S Aftab Ahmed Awan.	Afab Ahmed	
06)	M/S Rafique Ahmed Soomro.	9	
07)	M/S BMB Construction Co:	Jhao)	
08)	M/S Bilal Hyder Construction Co:	Tododi	
09)	M/S Abdul Sattar Mughal & Co:	Som gle	
10)	M/S Zaheer & Brothers.	J. P	

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

COMPARATIVE STATEMENT OF RATES QUOTED BY THE CONTRACTORS FOR THE YEAR-2016-17

Quotation Inviting No: XEN/SDD/SKP/605, Dated: 10/10/2016 Date of Issue of Bidding Documents: 28/10/2016.

Date of Received & Opening: 31/10/2016.

PROCUREMENT OF GOODS & SERVICES FOR THE YEAR-2016-17.

NAME OF WORK: -

						Rat	Rate Quoted By Contractors	Contractors				
S. o	Description	Unit	Safdar Ali Channa	Saleemullah Soomro	Abdul Aziz Abbasi	Dua Enterprises	Aftab Ahmed Awan	Rafique Ahmed Soomro	BMB Construction Company	Bilal Hyder Const:	Abdul Sattar Mughal	M/S Zaheer
-	2	u	4	Un.	6	7	000	9	10	1 0	17	11
	(A) ELECTRICAL & MECHANICAL PARTS / JOB WORK OF PUMPS)B WOI	K OF PI	UMPS	4				10	=	1.4	10
01	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25100	25200	25300	25000	25500	25000	26000	25000	26000	25400
02	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13500	13500	13600	13300	14100	13300	14000	13500	14000	13500
ဒ	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18200	18300	18400	18100	18200	18300	18300	18100	18300	18200
94	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25500	25600	25600	25000	25500	25000	26000	25000	26000	25600
95	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25500	25500	25600	25000	256000	25600	26000	25000	26000	25600
8	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7900	8000	8100	7900	7900	7800	8000	7800	7800	7900
07	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24800	24900	25000	25000	25500	24700	26000	24700	24700	24800
80	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300	2300	2300	2350	2300	2300	2400	2200	2200	2300
09	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16400	16400	16500	16500	16600	16300	16500	16300	16500	16400
10	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1800	1850	1850	1850	1900	1780	1850	1800	1750	1760
=	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7500	7600	7800	7500	7800	7400	7800	7400	7500	7500
12	of housing for Pump of 25 & 30 C/S	P. Job	5200	5300	5400	5400	5500	5200	5400	5100	5100	5200
. 3	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500	14600	14600	14500	14600	14000	14500	14000	14500	14500
4		11										

Right Bank "ubevint" Executive Engineer Division Ratoder

COMMARPOR DRAINAGN DIVISION BRECUTIVE ENGINEER SHIRLARUR

Buildings Division Shikarpur, Executive Engineer

(Page No: 2)

28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	-	S &
Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	2	Description
Each	Each	Each	Each	Each	P. Rft	Each	Each	Each	Each	Each	Each	Each	P. Job	P. Job	3	Unit
2200	2400	2600	8600	8000	14000	8600	7200	4450	5300	28000	4400	11500	14800	12950	4	Safdar Ali Channa
2174	2500	2600	8700	8000	14500	8700	7300	4500	5400	28500	4500	11600	14850	13000	5	Saleemullah Soomro
2200	1990	2700	8900	7200	13491	8600	7500	4600	5400	29000	4500	11700	14900	13500	6	Abdul Aziz Abbasi
2300	2500	2600	8950	7184	14500	8600	2800	3634	3728	24338	4264	11224	14704	12950	7	Dua Enterprises
2300	1990	2600	8950	7200	14600	8600	7184	4600	5400	29000	4400	12000	14800	13000	8	Rate Quoted By Contractors Aftab Rafique Ahmed Ahmed Soomro
2400	2400	2600	8552	7184	13491	5268	2800	4500	3728	28000	4400	11224	14704	12950	9	Contractors Rafique Ahmed Soomro
2300	2500	2700	8650	8500	14500	9800	7500	4700	5600	29000	4500	13000	15000	14000	10	BMB Construction Company
2350	2316	2110	8552	8600	13491	5268	2800	3643	5268	24338	4364	12000	15500	14000	11	Bilal Hyder Const:
2400	2400	2110	8552	7184	13491	5268	2800	3643	5268	25000	4400	11500	14600	14500	12	Abdul Sattar Mughal
2450	2400	2550	8950	5200	1520	8600	7250	3700	5310	25000	4364	11224	14704	15500	13	M/S Zaheer & Brothers

Right Bank Fubewell DIVISION RECORD

CONTARPOR DRAINAGN DIVISION BEECUTIVE ENCINEER SHIKARPUR

> Buildings Division Shikarpur. Arrey Executive Engineer

)	43 R	42 R	41 th		39 R	38 Si	_	36 Si	35 35 35 35	34 Si	33 Ii L	32 L in	31 S	30 S	29 S	-		
	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	2	Description	
	P.Job	P.Job	P. Job	P. Job	P.Job	Each	Each	Each	Each	Each	P.Job	P. Job	Each	Each	Each	3	Unit	
	5200	5300	22000	9000	6000	11000	12000	16000	14000	25000	26000	26000	2800	2400	2600	4	Safdar Ali Channa	
	5300	5300	22100	9600	6500	11500	12500	16500	14500	25500	25500	26500	2800	2316	2522	ካ	Saleemullah Soomro	
	5300	5300	22200	9660	6600	11600	13000	16600	14500	25600	25500	26400	2800	2400	2600	2	Abdul Aziz Abbasi	
	5000	5229	21910	8900	6600	11500	13000	16600	14500	25600	25000	25000	2740	2450	2650	7	Dua Enterprises	Rs
	5300	5300	22000	8900	6000	11600	11502	15476	13167	24350	25600	25600	2800	2400	2600	80	Aftab Ahmed Awan	Rate Quoted By Contractors
	5000	5229	22300	8750	5985	10807	11600	15476	13200	24600	25000	25000	2800	2400	2560	•	Rafique Ahmed Soomro	Contractors
	5200	5500	22300	8900	6000	11200	11600	15600	13400	25000	26000	25500	2800	2400	2600	,,0	BMB Constructio n Company	
	5000	5229	21910	8950	6500	11200	11502	15476	13167	24350	25000	25000	2850	2400	2650	"	Bilal Hyder Const: Co:	
	5500	5600	22000	8750	5985	11200	11600	15500	13600	24600	25000	25000	2800	2316	2522	4	Abdul Sattar Mughal & Co:	
	5500	5800	22000	8800	6000	10900	11560	15500	13500	24500	25500	25000	2810	2400	2530		M/S Zaheer & Brothers	

Executive Engineer Division Ratodero

COMMARPUR DRAINAGN DIVINOR BEECUTIVE PHOINEER SHIKARPUR

> Buildings Division Shikarpur. Executive Engineer

				(1 uge 110. 4)	4)	Ra	Rate Quoted By Contractors	Contractors				
	Description	Unit	Safdar Ali Channa	Saleemullah Soomro	Abdul Aziz Abbasi	Dua Enterprises	Aftab Ahmed Awan	Rafique Ahmed Soomro	BMB Constructio n Company	Bilal Hyder Const:	Abdul Sattar Mughal	M/S Zaheer & Brothers
-	2	w	4	5	7	3	8	9	0	/	2	
4	box 45 mm dia i/c fitting of etc complete for the pumps	P .Job	7900	7950	8000	7860	7960	7860	8000	7860	7900	7900
45	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8400	8450	8500	8400	8500	8350	8500	8329	8400	8500
46	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11900	11950	12000	12000	12200	11838	12500	11838	11838	11900
47	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12547	12600	12800	12900	12950	12547	12500	12547	12547	12600
48	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12547	12600	12800	12900	12900	12547	12850	12547	12547	12600
49	umps of 25 & 30 C/S discharge.	P .Job	9500	9600	9700	9800	9850	9500	9650	9500	9410	9500
50	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	14900	15000	15500	15600	15800	14850	15000	15500	14850	14900
51	piece upper of ent of bearing	P .Job	15200	15300	15400	15400	15500	15200	15300	15210	15120	15200
52	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	16950	17000	17200	17300	17400	16980	17200	17500	16915	16950
53	shaft 30 mm dia i/c welding ghtening etc complete.	P.Job	3500	3441	3500	3550	3550	3500	3500	3500	4000	4000
54	welding	P .Job	4200	4200	4167	4500	4500	4500	4200	4200	4400	4500
55	of 25 &	P.Job	10500	10455	10455	10500	10500	10500	10500	10455	10500	10900
56	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16900	16900	16900	16865	17000	16900	16900	16865	17000	17500
57	Repair & Refitting of High tension (HT) coil of 630 KVA transformers	P. Job	25500	25600	25000	25500	25000	25500	25500	25000	25000	25600

DIVISION NATOCE.

BEESCUTTE HOINEER
COMEARING DRAINAGN DIVISION

Buildings Division Shikarpur. Executive Engineer

.

(Page No: 5)

							Ra	Rate Quoted By Contractors	Contractors				
		Description	Unit	Safdar Ali Channa	Saleemullah Soomro	Abdul Aziz Abbasi	Dua Enterprises	Aftab Ahmed Awan	Rafique Ahmed Soomro	BMB Constructio n Company	Bilal Hyder Const:	Abdul Sattar Mughal	M/S Zaheer & Brothers
-		2	w	4	S	8	2	80	9	/0	*	12	
58		Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25500	25600	25000	25500	25000	25500	25500	25000	25000	25600
59		Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25500	25600	25000	25500	25000	25500	25500	25000	25000	25600
69		Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P.Job	25500	25600	25000	25500	25000	25500	25500	25000	25000	25600
61	_	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P.Job	8500	8500	8550	8600	8500	8432	8500	8600	8650	8650
62		Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10600	10600	10800	10900	10700	10500	10600	11000	11500	11500
63		Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12600	12700	12800	12500	12800	12600	12600	12600	13000	12500
64		Repair & Welding of Transformer with plate form outside including coloring.	P .Job	5000	5500	5600	4498	5000	5000	5500	5500	5700	5900
65	Commence of	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3700	3700	3750	3700	3700	3676	3700	3700	3800	3800
66		Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7000	7500	7500	7510	6941	7000	6950	7900	7500	7500
67		Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14000	14500	13960	13945	14500	14600	14500	14600	14600	14600
68		Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14000	14500	13960	13945	14500	14600	13600	14600	14700	14750
69		Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1900	1950	1848	1920	1848	1900	2000	1900	1900	1950
69		Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2700	2700	2700	2750	2700	2700	2800	2700	2700	2700
70		Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	4800	5000	4900	4800	4900	4800	5000	5000	4800	4800

Executive Engineer
Right Bank Cubewell
Division Ratodero

EMEGUTIVE ENGINEER
SHIKARPUR
SHIKARPUR

Executive Engineer
Buildings Division Shikarpur.

	_	2 -	71	72	73	74	75	77	78	79	80	81	82	83	84	000
Description				Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.		Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.		Supplying of Pressure plate genuine for Toyota Pick- up.	Supplying of Water body Genuine for Toyota Pick-up.	Supplying of Shock observer set Rear genuine for Toyota Pick-up.	100.00	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	Supplying & Fixing of Silencer complete local for Toyota Pick-up.	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Complete denting and painting of body for Toyota Pick-up including labor charges.	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.
		3	Р. Н	Р. Н	P. Dav	Each	Each	Each	Each	P. Set	P. Set	P. Job	Each	Each	P. Job	Each
Safdar	Channa	4	1200	1050	6500	11300	9800	13000	8000	23000	25000	25000	13000	13900	25500	7000
Soleomullah	Soomro	م	1200	1100	6600	1.1500	1000	13300	8200	23000	25500	26000	13000	13900	25500	7500
Abdul	Abbasi	8	1200	1100	6500	11500	1000	13300	8200	22000	25000	25000	12700	13800	25000	6000
,	Enterprises	9	1250	1050	6500	11500	10500	13500	8500	24000	26000	26000	13000	14000	26000	7000
Aftab Rafique	Ahmed	06	1200	1100	6600	12500	11000	14000	9500	22000	25000	25000	13600	13800	25000	6000
Rafique	Ahmed	٥	1200	1050	6600	12600	11000	14500	9500	23000	26000	26000	13000	13900	26000	6700
вмв	n Company	3	1350	1100	6000	12300	9800	13000	7950	24000	26000	25500	12500	13900	25500	8000
Bilal	Const:	- 1	1200	1050	6600	11400	9900	13500	8000	24000	26000	25500	13000	14000	26000	8500
Abdul	Mughal	200.	1200	1050	6600	11400	9900	13600	8500	22000	25000	25000	12600	13000	25000	6000
N/S	Zaheer & Brothers		1300	1050	6000	11300	9800	12600	7900	23000	25500	25500	12700	13900	25600	6500

Executive Engineer
Right Bank Fubewell
Division Ratodero

SOUTH ENGINEER SHEARING SOUTHERN STREET

Executive Engineer Buildings Division Shikarpur,

				1 mgc 110. //	17	Rai	to Ornoted By	Contractors				
						RM	Kate Quoted by Contractors	Contractors		-		
	Description	Unit	Safdar Ali Channa	Saleemullah Soomro	Abdul Aziz Abbasi	Dua Enterprises	Aftab Ahmed Awan	Rafique Ahmed Soomro	BMB Constructio n Company	Bilal Hyder Const: Co:	Abdul Sattar Mughal & Co:	M/S Zaheer & Brothers
-	2	3	9	د	8	2	8	. 9	: /0	"	7	
86	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000	22500	23000	23000	22000	23000	23000	23000	22000	23000
87	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2800	2850	2850	2750	2700	2800	2900	3000	27000	28000
88	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000	22000	22000	22000	22000	22000	2150	25000	2150	22000
89	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500	7600	7000	7500	7000	7500	7500	7500	7000	7600
90	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8900	8900	8500	8900	8500	8600	8500	8900	8500	8600
91	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25500	25500	25500	25600	25000	25600	25000	26000	25000	25500
92	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3600	3700	3600	3500	3500	3600	3500	3600	3500	3900
93	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3900	4000	3900	3800	3800	3900	3800	3900	3800	3900
94	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	26000	27000	25000	25500	25000	25500	25000	25500	25000	26000

(Lutfullan Phulpoto)
Executive Engineer
Buildings Division

Member Shikarpur

(Ishtiaque Ahmed Khan) Executive Engineer

Shikarpur Drainage Division

(Syed Niaz Ahmed Shah) **Executive Engineer**

Right Bank Tubewell Division

Chairman

Shikarpur

Ratodero Member

Method of Procedure of Procurement: - Opening Competitive Bidding (National Competitive Bidding) (Single Stage One Envelope)

Name of Work: -

Procurement of Goods & Services during the Year-2016-17

MINUTES OF BID OPENING MEETING

A meeting of the procurement committee of this Division was held on 31/10/2016, for opening of the bids received in respect of above NIT (Procurement of Goods & Services for the Year-2016-17) till the deadline for the submission of Bidding Documents. The meeting was attended by all/ following members of the procurement committee and the bidders or their representative. (Attendance sheet is enclosed).

The 10 Nos: bidders mentioned in the comparative statement (copy attached) submitted their bids till the dead line of submission of bids which were issued.

The bids were opened at 03.00 PM on 31/10/2016, in the presence of bidders / participants and the rates quoted by the bidders were read aloud and encircled by the chairman of the procurement committee.

S No:	Name of Bidders	Offered Price in Rs:	Amount of Bid Security in Rs:	Pay Order No; & Date
1	2	3	4	5
01)	M/S Safdar Ali Channa.	Comparative statement attached	100000/-	PO No: 00519002 Dated: 27/10/2016
02)	M/S Saleemulah Soomro.	~~ Do ~~	100000/-	CDR No: 102263303 Dated: 28/10/2016
03)	M/S Abdul Aziz Abbasi.	~~ Do ~~	100000/-	PO No: 15067956 Dated: 27/10/2016
04)	M/S Dua Enterprises.	~~ Do ~~	100000/-	CDR No:0531205 Dated: 28/10/2016
05)	M/S Aftab Ahmed Awan.	~~ Do ~~	100000/-	PO No: 15067946 Dated: 24/10/2016
06)	M/S Rafique Ahmed Soomro.	~~ Do ~~~	100000/-	CDR No: 385897 Dated: 25/10/2016
07)	M/S BMB Construction Co:	Do	100000/-	CDR No: 1319 Dated: 26/10/2016
08)	M/S Bilal Hyder Construction Co:	~~ Do ~~	100000/-	CDR No: 102257019 Dated: 26/10/2016
09)	M/S Abdul Sattar Mughal & Co:	Do	100000/-	CDR No: 10613772 Dated: 28/10/2016
10)	M/S Zaheer & Brothers.	Do	100000/-	PO No: 15764272 Dated: 28/10/2016

The committee has examine all the bids as per the qualification / eligibility criteria provided in the bidding documents / arithmetically checked and verify the documents and bids security submitted by the bidders.

In the light of above bid evolution report duly signed by the bidding committee attached and submitted for the approval. The meeting ended with the vote of thanks to and from the chair.

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur Chairman (Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

BID EVALUATION REPORT

01) Name of Procurement Agency

Executive Engineer, Shikarpur Drainage Division Shikarpur

02) Tender Reference No:

XEN/SDD/AB/SKP/605 Dated: 10/10/2016

03) Tender Description:

Procurement of Goods & Services during the Year-2016-17

04) Method of Procurement:

Single Stage, One Envelope.

05) Tender Published:

Daily Dawn Dated: 17/10/2016 and Daily Jung 17/10/2016

SPPRA Sr. No: 30123.

06) Total Bid documents Sold:

10 Nos:

07) Total Bids Received:

10 Nos:

08) Technical Bid Opening

Date: (if applicable)

Nil

09) No: of Bid Technically Qualified

(if applicable):

Nil

10) Bid(s) Rejected:

Nil

11) Financial Bid Opening Date:

31/10/2016.

12) Bid Evaluation Report:

S No	Name of Firm or Bidder	Cost offered by the Bidder	Ranking in terms of cost	Comparison with Estimated cost	Reasons for acceptance/ rejection	Remarks
1	2	3	4	5	6	7
01)	M/S Safdar Ali Channa.	Comparative statement attached	Comparative statement attached	Comparative statement attached	Responsive	Accepted
02)	M/S Saleemulah Soomro.	~ Do ~	~~ Do ~~	~~ Do ~~	~~ Do ~~	~ Do ~
03)	M/S Abdul Aziz Abbasi.	~~ Do ~~	~~ Do ~~	~~ Do ~~	~~ Do ~~	~ Do ~
04)	M/S Dua Enterprises.	~ Do ~	~~ Do ~~	~~ Do ~~	~ Do ~	~~ Do ~~
05)	M/S Aftab Ahmed Awan.	~~ Do ~~	~~ Do ~~	~~ Do ~~	~~ Do ~~	~ Do ~
06)	M/S Rafique Ahmed Soomro.	~ Do ~	~~ Do ~~	~ Do ~	~~ Do ~~	~ Do ~
07)	M/S BMB Construction Co:	~~ Do ~~	~~ Do ~~	~~ Do ~~	~~ Do ~~	~~ Do ~~
08)	M/S Bilal Hyder Construction Co:	~ Do ~	~~ Do ~~	~~ Do ~~	~~ Do ~~	~ Do ~
09)	M/S Abdul Sattar Mughal & Co:	~ Do ~	~~ Do ~~	~~ Do ~~	Do	~ Do ~
10)	M/S Zaheer & Brothers.	~~ Do ~~	~ Do ~	~~ Do ~~	~~ Do ~~	~~ Do ~~

(Lutraliah hulpoto)

Executive Engineer Buildings Division

> Shikarpur **Member**

(Ishtiaque Ahnled Khan)

Executive Engineer Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

to M/s Sallemullah Soomes Contrallo

EXECUTIVE INGINEER EESTARPUR DRAINAGN DIVISIOE SHIKARFUR

SCHEDULE "B"

Name of Work:

SUPPLYING OF GOOD & SERVICES FOR THE MAINTENANCE & REPAIR OF SCARP PUMPING STATIONS DRAINS & GOVERNMENT VEHICLES AS PER RATE QUOTED CONTRACT

S No:	Description	Unit	Rate
) ELECTRICAL & MECHANICAL PARTS / JOB WORK OF I	PUMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25200
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13500.
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18300-
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25500
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	8000 -
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24900-
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300-
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16400-
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1850-
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7600-
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5300-
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14600-
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	13000-
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14850-
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11600-
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4500-
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	28500-
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5400-
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4500-
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7300-
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8700-

	*		
	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	14500-
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	8000-
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8700-
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2600-
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2500-
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2174-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2522
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2316-
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2800-
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	26500-
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25500
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	25500
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	14500
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	16500
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	12500
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11200-
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6500-
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	9600-
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22100
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	2300-
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	5300.
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7950-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8420-
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11950 -
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12600 -
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12600-
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9600-

	Supplying Fixing of stuffing box complete for the pumps of 25 &	Each	15000-
51)	30 C/S Discharge Local. Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15300-
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	17000
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3441-
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4200-
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10455-
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16900-
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25600
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25600-
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25600-
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25600
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	8500-
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10600-
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12700
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	2200.
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3700-
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	-1200-
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500-
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500-
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1950-
) MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2700
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	2000-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of	Р. Н	1200-

72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing	P. H	1100-
EQ.	of cuts & breaches along Branch-Drains & Sub-Drains.	n n	6600-
73)	Hiring of Single Cabin Pick-up with POL	P. D	
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11500-
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	1000-
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	13300-
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	8200-
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	23000-
80)	Supplying of Shock observer set Front genuine for Toyota Pick-up.	P. Set	25300-
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	2600- 13000-
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	13000-
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13900-
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25500
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	-1500-
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	22500
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2850-
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	35000.
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7600-
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8900-
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25760
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3700-
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	4000
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	27000

Contractor

(Lutfullah Phulpote)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3604 Dated: 28710/2016

to M/s Dua Enterprises

RIECUTIVE ENGINEER STAFARPUR DRAINAGN DIVISIOS SHIKARPUR

SCHEDULE "B"

Name of Work:

SUPPLYING OF GOOD & SERVICES FOR THE MAINTENANCE & REPAIR OF SCARP PUMPING STATIONS DRAINS & GOVERNMENT VEHICLES AS PER RATE QUOTED CONTRACT

S No:	Description	Unit	Rate
)ELECTRICAL & MECHANICAL PARTS / JOB WORK OF P	UMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25000
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13300
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18100
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25000
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25000
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7900
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	25000
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2350
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16500
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	185c
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7500
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5400
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	12950
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14704
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11224
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4264
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	24338
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	3728
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	3634
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	2860
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8600

thick Painted with epoxy for Pump of 25 & 30 C/S (Local made). Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made). Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made). Each 30 C/S (Local made). Supplying & Fixing Motor fan of 80 & 100 HP motor Local. Supplying & Fixing Terminal carrier for the motors of 80 & 100 HP. Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made). Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Labour charges for the rewinding of electric vertical induction motor of 80 HP. Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor of 100 HP. Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 HP. Each Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 HP. Electric Motor Supplying & Fixing Imerelay 0 to 20 see: for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of Stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of Stuffing box 55 mm dia i/c fitting of		3		
Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made). Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made). Each Supplying & Fixing Motor fan of 80 & 100 HP motor Local. Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P. Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made). Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S (Local made). Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan cowl for 80 & 100 HP motor Local Each 2 (assembled) Local. Supplying & Fixing fan Each 2 (assembled) Local. Supplying & Fixing fan Breaker Contact set 3TB or N5 for the motor ontrol unit of 80 & 100 HP. Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 Each 1.P Electric Motor Each 1.P Each 2.P Each 2	S	upplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia nick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	14500
25) Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made). 26) Supplying & Fixing Motor fan of 80 & 100 HP motor Local. 27) Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P. 28) Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made). 29) Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. 30) Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 31) Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 32) Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33) Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S dischar	S	upplying & Fixing Flange bearing 20" dia with 6 holes for the	Each	7184
26) Supplying & Fixing Motor fan of 80 & 100 HP motor Local. Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P. 28) Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made). 29) Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. 30) Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 31) Supplying & Fixing fan cowl for 80 & 100 HP motor Local 32) Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33) Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 Each H.P Electric Motor 38) Supplying & Fixing ball bearing 6315 NTN upper for 80 & 100 Each H.P Electric Motor 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 43) Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of Stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discha	S	upplying & Fixing stuffing box buses 45 mm for Pump of 25 &	Each	8950
27) Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P. 28) Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made). 29) Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. 30) Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 31) Supplying & Fixing fan cowl for 80 & 100 H.P motor Local 22) Labour charges for the rewinding of electric vertical induction motor of 80 H.P. 33) Labour charges for the rewinding of electric vertical induction motor of 100 H.P. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 H.P. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 H.P. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 Each 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 H.P. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 H.P. 41) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 H.P. 42) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 H.P. 43) Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of Stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stain			Each	2600
8 30 C/S (Local made). Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump. 30 Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 31 Supplying & Fixing fan cowl for 80 & 100 HP motor (assembled) Local. 32 Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33 Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34 Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35 Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36 Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37 Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38 Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 40 Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. 41 Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42 Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 43 Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44 Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45 Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46 Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47 Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48 Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	S	upplying & Fixing Terminal carrier for the motors of 80 & 100	Each	2500
30 C/S discharge pump. 30 Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local. 31 Supplying & Fixing fan cowl for 80 & 100 HP motor Local 32 Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33 Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34 Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35 Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36 Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37 Supplying & Fixing ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38 Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39 Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. 40 Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. 41 Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42 Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42 Repair & Fixing of Suffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44 Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45 Repair & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47 Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48 Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	8	z 30 C/S (Local made).	Each	2300
(assembled) Local. 31) Supplying & Fixing fan cowl for 80 & 100 H.P motor Local 32) Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33) Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 43) Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. 44) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	3	0 C/S discharge pump.	Each	2650
Labour charges for the rewinding of electric vertical induction motor of 80 HP. 33) Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P. Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P. Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.				2450
motor of 80 HP. 33) Labour charges for the rewinding of electric vertical induction motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P. Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P. Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 43) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 44) Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.			Each	2740
motor of 100 HP. 34) Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP. 35) Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. 36) Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P. Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	n	notor of 80 HP.	P. Job	25000
motor control unit of 80 & 100 HP. Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP. Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	n	notor of 100 HP.		25000
for the motor control unit of 80 & 100 HP. Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	n	notor control unit of 80 & 100 HP.		25600
H.P Electric Motor 37) Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.			Each	14500
H.P Electric Motor 38) Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp.) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm.) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 42) Repair & Fixing of Circuit Breaker 1000 (Apm.) for the motor control of 80 & 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	100000	용면 바로 바로 하다 가게 되었다. 이번 전에 가게 되는데 보고 보고 있다. 그리고 있다면 하다 그리고 있다. 그리고 있다면 그리고 있다면 그리고 있다면 그리고 있다. 그리고 있다. 그리고 있다. 그리고 있다. 그리고 있다면 그리고 있다.	Each	16600
of 80 & 100 HP. 39) Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & P. Job 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	No.		Each	13000
control of 80 & 100 HP. 40) Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local. Each 12	0	f 80 & 100 HP.	Each	11500
control of 80 & 100 HP. 41) Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	C	ontrol of 80 & 100 HP.	P .Job	6600
control of 80 & 100 HP. 42) Repair & Fixing of delta star system of Electric Motor of 80 & P. Job 50 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	C	ontrol of 80 & 100 HP.	P. Job	8900
100 HP. 43) Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 44) Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 45) Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	C	ontrol of 80 & 100 HP.	P. Job	21910
cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Capture (Gun metal) etc complete for the pumps of 25 & 30 C/S. Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	1	00 HP.		5 229
cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Ca	age (Gun metal) etc complete for the pumps of 25 & 30 C/S.		5000
cage (Gun metal) etc complete for the pumps of 25 & 30 C/S. 46) Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local. Each 12	ca	age (Gun metal) etc complete for the pumps of 25 & 30 C/S.		7860
pump shaft of 25 & 30 C/S discharge pumps. 47) Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local. Each 12	ca	age (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8400
pump shaft of 25 & 30 C/S discharge pumps. 48) Threading column shaft with protective sleeve 30 mm (Stainless steel) Local. Each 12	pı	ump shaft of 25 & 30 C/S discharge pumps.	Each	12000
steel) Local.	pı	ump shaft of 25 & 30 C/S discharge pumps.	Each	12900
49) Repair of impeller of pumps of 25 & 30 C/S discharge. P. Job 9	st	eel) Local.		12900
	R	epair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9800

ر0ر)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	15600
5Y)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15400
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	17300
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3550
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4500
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10500
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16865
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25500
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25500
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25500
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25500
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	3600
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10900
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12500
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	4498
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3700
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7510
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	13945
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	13945
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1920
) MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding	P. H	2750
70)	of Branch-Drains & Sub-Drains. Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	4800
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1250

12)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1050
73)	Hiring of Single Cabin Pick-up with POL	P. D	6500
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11500
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	10500
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	13500
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	8500
79)	Supplying of Shock observer set Rear genuine for Toyota Pick-	P. Set	24000
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	26000
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	26000
82)	Supplying & Fixing of Silencer complete local for Toyota Pick-up.	Each	13000
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	14000
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	26000
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	7000
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2750
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8900
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25600
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3500
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3800
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25500

Contractor Ena Enterprises

(Lutfullah Phulpoto)
Executive Engineer

Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory Authority

\$ -- 1 - 1 - 1 - 1 - 2

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- · General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3605 Dated: 28/10/2016.

to Ms Abdul Asis Abbasi Contraction.

EXECUTIVE ENGINEER
EXMEARPUR DRAINAGN DIVISION
SHIKARPUR

SCHEDULE "B"

Name of Work:

SUPPLYING OF GOOD & SERVICES FOR THE MAINTENANCE & REPAIR OF SCARP PUMPING STATIONS DRAINS & GOVERNMENT VEHICLES AS PER RATE QUOTED CONTRACT

S No:	Description	Unit	Rate
) ELECTRICAL & MECHANICAL PARTS / JOB WORK OF I	PUMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25300
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13600/=
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18400/=
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600/
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	8/00f=
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	25004
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300/=
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16500/=
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1850/=
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7800f=
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5400/=
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14604=
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	13500/=
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14900f=
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11700/2
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4500/=
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	29004=
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5461/=
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4600/2
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7500/=
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8600/=

,	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	13491/2
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	720%
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	88007=
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	27007=
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	1899=
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2209:
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2600/2
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	24007:
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	28007=
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	26407
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25500/
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	25607:
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	14500/=
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	16607=
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	130092
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11600/2
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6607=
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	96612
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22207=
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	53007:
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	53027:
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8009:
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	850072
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12000/2
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	1280070
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12800/2
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9700/2

,	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	15509:
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	154007:
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	1720/2
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3500%
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4167/=
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10455/2
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16909=
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25007:
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25000/:
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	2200J=
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25000
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	85507=
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10800/=
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12800/2
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	5600]=
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	375%
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7509:
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	750g= 139607= 139607=
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	13/60/2
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1848/2
(B) MAINTANANCE OF DRAIN		/
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	2 Jul:
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	1200/2 1200/2
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1200/2

1	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	Р. Н	110/2
73)	Hiring of Single Cabin Pick-up with POL	P. D	6500/2
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	115007=
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	1000/2
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	1330072
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	82007=
79)	Supplying of Shock observer set Rear genuine for Toyota Pick-up.	P. Set	22000/
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	25000]
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25mg:
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	12700/3
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13800/
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	2500%
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	6000/=
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	230007
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2857
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	220007
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	70007=
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	85007=
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	2550%
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3toof2
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	380072
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25000/-

Contractor Abdul Asia Alsham

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- · Instructions to Bidders (ITB)
- · General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3606 Dated: 28/10/2016.

to m/s Safdar Ali Channa Contractor.

RXECUTIVE ENGINEER SOMFARPUR DRAINAGN DIVISION SHIBARFUR

SCHEDULE "B"

Name of Work:

SUPPLYING OF GOOD & SERVICES FOR THE MAINTENANCE & REPAIR OF SCARP PUMPING STATIONS DRAINS & GOVERNMENT VEHICLES AS PER RATE QUOTED CONTRACT

S	Description	Unit	Rate
No:) ELECTRICAL & MECHANICAL PARTS / JOB WORK OF P	HMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25100
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13500
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18200
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25500
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	3220c
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7800
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24800
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16400
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1800
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	002F
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5200
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	12950
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14800
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11500
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	huoc
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	28600
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5300
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4450
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7200
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8600

23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	14000
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	8000
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8600
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2600
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2400
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	.2750
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2600
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2400
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2200
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	26000
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	26000
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	25000
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	14000
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	16000
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	12000
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11000
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6000
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8000
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22000
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	2300
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	5200
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7900
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8400
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11900
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12247
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12547
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9500

50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	14900
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	12200
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	02931
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3500
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4200
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10200
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16900
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	52200
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25500
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25500
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25200
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	8200
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10600
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	17600
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	5000
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3710
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7600
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14000
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14100
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1900
	MAINTANANCE OF DRAIN		-
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	2700
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	4200
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1200

72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing	Р. Н	1020
Š.	of cuts & breaches along Branch-Drains & Sub-Drains.		1.0-
73)	Hiring of Single Cabin Pick-up with POL	P. D	P200
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11300
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	9800
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	13000
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	8000
79)	Supplying of Shock observer set Rear genuine for Toyota Pick-up.	P. Set	23000
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	25000
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25000
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	13000
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13900
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25220
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	7000
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2800
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8800
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25500
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3600
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3900
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	26000

Contractor Safelar Ali Chams

(Lutfullah Phulpoto)

Executive Engineer

Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory **Authority**

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur

to Ms Afrab Ahmed Awan Continelor

THEARFUR DRAINAGN DIVISION SHIRARFUR

SCHEDULE "B"

Name of Work:

SUPPLYING OF GOOD & SERVICES FOR THE MAINTENANCE & REPAIR OF SCARP PUMPING STATIONS DRAINS & GOVERNMENT VEHICLES AS PER RATE QUOTED CONTRACT

S No:	Description	Unit	Rate
	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF F	UMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25500
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	14100
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18200.
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	22200-
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	256000
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7800-
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	52200
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300-
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16600
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1800 -
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7800-
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	7200 -
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14600-
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	13000.
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14800.
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	12000 -
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4400 -
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	29000 -
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5400 -
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4600-
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7184 -
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8600-

23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	14600
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	7200.
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	- 0298
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2600 -
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	1990 -
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2300-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2600.
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	5400.
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2800.
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	25600
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25600
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	24350
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13167
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	15476
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11205
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11600-
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6000.
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8966
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22000
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	5300
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	2300 -
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7960-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	- 0028
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12200 -
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12950-
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12900-
	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	

10			
50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	12800
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15500
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	17400 -
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	2520-
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4500.
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10,500 -
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	17000
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25000 -
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25000
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	52,000 -
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25000
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	- 0028
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10700 -
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12800 -
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	2000.
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3760
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	6941
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500.
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1848
	MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	2700
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	4900-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1200-

9	•		
72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	Р. Н	1100
73)	Hiring of Single Cabin Pick-up with POL	P. D	6600
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	12500
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	1/000
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	14000
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	9500
79)	Supplying of Shock observer set Rear genuine for Toyota Pick-up.	P. Set	22000
80)	Supplying of Shock observer set Front genuine for Toyota Pick-up.	P. Set	25000
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25000
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	13600
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13800
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25000
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	6000
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	22000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2700
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7000
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8200
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25000
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3200
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3800
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25000

Atas Ahme

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- · General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3608. Dated: 28/10/2016.

to M/s Kafique

EXECUTIVE ENGINEER

SHIBARINA

Name of Work:

S No:	Description	Unit	Rate
	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF PU	JMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25000-
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13300-
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18300-
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25000-
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600-
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7800-
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24700-
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300-
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16300-
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1780-
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7400-
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5200-
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14000-
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	12950-
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14704
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11224-
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4400-
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	28000-
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	3728
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4500-
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	2800- 5268
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	5268

∠3)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	13491-
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	7/84-
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8552-
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2600-
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2400-
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2400-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2560-
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2400-
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2800-
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	25000-
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25000-
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	24600-
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13200-
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	15476-
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11600-
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	10807-
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	5985-
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8750
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22300-
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	5229-
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	5000-
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7860-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8350-
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11838 -
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12547-
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	2500-12
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	2505- 12 14850- 9500-

J)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	14850-
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15200-
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	16980-
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3500-
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4500-
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10500-
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16900-
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25500-
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25500-
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25500-
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25500-
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	8432-
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10500-
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12600-
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	5000-
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3676-
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7000-
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14600-
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14600-
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1900-
Œ	B) MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2700
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	4800-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.		1200-

72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor		240 1520
	with front blade with POL for the supply of Earth for the closing	P. H	1050-
72)	of cuts & breaches along Branch-Drains & Sub-Drains.	n n	11.50
73)	Hiring of Single Cabin Pick-up with POL	P. D	6600-
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	12600-
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	11000-
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	14500-
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	9500-
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	23000-
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	26000-
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	2600-
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	13000-
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13900-
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	26000-
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	6700-
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000-
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2800-
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000-
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500-
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8600-
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25600-
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3600-
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3900-
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25500

Contractor / Raff sue Almored Se

(Lutfullah Phulpoto)

Executive Engineer

Buildings Division

Shikarpur Member (Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Member

Chairman

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3609. Dated: 28/10/2016.

to M/s B.M.B Cont. Co. Contraction.

RIECUTIVE ENGINEER

COMEARPUR DRAINAGN DIVISION
SHIEARPUR

Name of Work:

(0)	Description	Unit	Rate
(O:	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF P	IMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	26000
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	14000
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	188ac
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	26000
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	26000
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	8000
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	26000
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2400
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16500
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1850
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7800
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5400
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	14000
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	15000
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	13000
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4500
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	29000
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	S600
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	4700
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7500
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	9800

		D D C	
23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	14500
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	880
'5)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8650
)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2700
7	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2500
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2300
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2600
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2400
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2800
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	2550
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	26000
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	25000
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13400
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	15600
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11600
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11200
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6000
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8900
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22300
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	2200
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	5200
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8000
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8500
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12500
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12500
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12850
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9650

)			
50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	15000
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15300
')	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	17200
	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	3500
	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4200
	Dismantling & refitting of all parts of pumps of 25 & 30 C/S lischarge.	P .Job	10500
	upplying & Fixing M.S channel size 3"x7" 14 ft: long for undation of motor	Each	16900
	pair & Refitting of High tension (HT) coil of 630 KVA sformers.	P. Job	25300
	iir & Refitting of High tension (IT) coil of 630 KVA formers.	P .Job	2550
	& Refitting of High tension (HT) coil of 750 KVA mers.	P. Job	25500
	& Refitting of High tension (IT) coil of 750 KVA ners.	P .Job	25500
	2 & Fixing LT insulator including Rod, Nut Bolts etc vr 200, KVA Transformer.	P .Job	8500
	Fixing LT insulator including Rod, Nut Bolts etc 330, KVA Transformer.	P .Job	10600
	Fixing LT insulator including Rod, Nut Bolts etc 50, KVA Transformer.	P .Job	12600
	elding of Transformer with plate form outside ing.	P .Job	5500
	of propeller blade i/c welding, grinding and lete for the pumps of 25 & 30 C/S Discharge	P .Job	3700
	Socket spider for 14" dia pipe for the pumps rge local.	Each	6950
	ket spider for 18" dia for the pumps of 25	Each	14500
	spider for 20" dia for the pumps of 25	Each	14500 13600

9			
72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	Р. Н	1100
73)	Hiring of Single Cabin Pick-up with POL	P. D	6000
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	12300
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	9800
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	13000
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	7950
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	24000
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	Hoco
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25360
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	12500
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13900
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25500
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	8000
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	2900
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	2150
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8500
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25000
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3500
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3800
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25000

Contractor B. M. B. Const. Co.

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Member

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3610

CONTARPUR DRAINAGN DIVISION

SHIKARPUR

*Name of Work:

S No:	Description	Unit	Rate
	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF PU	UMPS	
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25000-
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	13500-
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	181cc-
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25000-
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	250ec-
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7800-
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24700
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2200
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16300
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1800-
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7400
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5/00
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14000
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	14000
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	15500
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	12000-
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4364
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	24330
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5268
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	364E 38ee
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	2800
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	5268

/			
23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	13491-
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	86co-
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8552
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2110-
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2316-
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2350-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2650-
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2400-
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2850-
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	25000-
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25 00 -
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	345Sc-
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13167-
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	15476-
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11502-
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11200-
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	6500-
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8850-
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	21910-
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	5229-
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	5000- 7860-
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7860-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8329-
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11838-
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12547-
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	11838- 12547- 12547- 9540-
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9500-

10			
50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	15500-
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15216-
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	17500-
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	350-
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4200-
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10455-
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	16865-
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25000-
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25500-
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	252 ~ -
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	20500-
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	850-
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	10600-
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	13.600-
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	55 2 0-
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3700-
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	6950-
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500-
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14500-
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	2000-
a	B) MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2800-
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2800-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1200-

,			
72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1050-
73)	Hiring of Single Cabin Pick-up with POL	P. D	6600-
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11400-
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	9900-
77)	Supplying of Pressure plate genuine for Toyota Fick-up.	Each	13500-
78)	Supplying of Vicesdate place genuine for Toyota Pick-up.	Each	8000
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	24000
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	26000-
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	arra.
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	13000-
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	14000-
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	26000-
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	8500-
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	2300€
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	3000
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	25000
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7500-
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8900-
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	26000
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3600-
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	8900-
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25560-

Contractor Contille

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur Chairman (Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Member

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- · Instructions to Bidders (ITB)
- · General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3611 Dated: 28/19/2016.

EXECUTIVE ENGINEER

CONTARPUR DRAINAGN DIVISION

SHIKARPUR

to M/s Abdal Saltar Rughal & Co. Contractor.

Name of Work:

S No:	Description	Unit	Rate	
	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF P	UMPS		
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	26000-	
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	14000-	
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	18300-	
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	26000-	
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	26000-	
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7800-	
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24700.	
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2200-	
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	16500-	
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1756-	
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7500-	
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5100-	
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500.	
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500.	
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14600-	
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11500-	
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4400-	
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	Each 2500-	
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	5268-	
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	3643-	
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	2800-	
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	5268-	

23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	13491-
₹4)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	7/84-
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8552-
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	2110-
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	2400-
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2400-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2522-
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	23/6-
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2800-
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	25000-
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	25000
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	24600-
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13600-
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	15500-
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11600-
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	11200-
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	5985-
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8750-
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22000-
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	5600-
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	2200-
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7900-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8400-
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11838-
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12547-
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12547-
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	01.10-

ų

50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	14850-
51)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15120-
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	16915-
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4000-
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4400-
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	10500-
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	17000-
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	25000-
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	25000-
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	25000-
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25000-
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	8650 -
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	P .Job	11500-
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	13000-
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	5700-
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	3800-
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	1200-
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14600-
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14700-
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	P. KG	1900-
(I	B) MAINTANANCE OF DRAIN	V	
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	2700-
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	P. H	4800-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1200-

and the second s			
72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing	Р. Н	1050-
Ø.	of cuts & breaches along Branch-Drains & Sub-Drains.		
73)	Hiring of Single Cabin Pick-up with POL	P. D	6600-
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11400-
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	9900-
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	Each	13600-
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	8500-
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	22000-
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	25000-
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25000
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	126000
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13000-
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25000
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	6000-
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	22000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	27000.
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	2150-
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7000-
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8500-
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25000
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3500-
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3800-
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	25000

Contractor
Andul salas Mughal sis.

(Lutfullah Phulpoto)

Executive Engineer Buildings Division

Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer

Shikarpur Drainage Division

Shikarpur Chairman (Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Member

Sindh Public Procurement Regulatory Authority

Bidding Documents

For

National Competitive Bidding

Pakistan

Procurement of Goods & Service for the Year-2016-17

PART ONE (FIXED)

- · Instructions to Bidders (ITB)
- General Conditions of Contract (GCC)

Issued by the Executive Engineer Shikarpur Drainage Division Shikarpur vide DR No: 3612 Dated: 28/10/2016.

to M/s Taker & Bros. Contractive.

EXECUTIVE ENGINEER

STAFFUR DRAINAGN DIVISION
SHIKARPUR

Name of Work:

S No:	Description	Unit	Rate	
	ELECTRICAL & MECHANICAL PARTS / JOB WORK OF I	PUMPS		
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	Each	25460-	
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	Each	(3Sæ-	
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	182-00-	
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600	
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	Each	25600	
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	Each	7900-	
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	Each	24800	
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	Each	2300-	
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	Each	الحاره	
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	Each	1760-	
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	P. Job	7500-	
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	P. Job	5200-	
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	P. Job	14500-	
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	P. Job	155cc-	
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	P. Job	14704-	
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	Each	11224-	
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	Each	4364-	
18)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	Each	25000-	
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	Each	2310-	
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	Each	3700-	
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	Each	7250-	
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	Each	8600-	

23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	P. Rft	1520-
24) Y	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	Each	5200-
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	Each	8950-
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	Each	722c-
27)	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	Each	≥4ce
28)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	Each	2450-
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	Each	2536
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	Each	2400-
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	Each	2810-
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	P. Job	25000-
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	P .Job	52200
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	Each	24500.
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	Each	13500-
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	Each	12200-
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	Each	11260-
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	Each	1 c700 -
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	P .Job	Leco-
40)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	P. Job	8800-
41)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	P. Job	22000
42)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	P .Job	2800-
43)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	2200-
44)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	7900-
45)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	P .Job	8200-
46)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	11900-
47)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	Each	12600-
48)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	Each	12600-
49)	Repair of impeller of pumps of 25 & 30 C/S discharge.	P .Job	9500-

50)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	Each	14900 -
5¥)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	15200-
52)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	P .Job	16950-
53)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4000 -
54)	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	P .Job	4500-
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	P .Job	100/00-
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor	Each	17500-
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	P. Job	2.5600.
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	P .Job	15600
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	P. Job	256cc-
60)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	P .Job	25600
61)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	P .Job	8650
62)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.		11500-
63)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	P .Job	12500-
64)	Repair & Welding of Transformer with plate form outside including coloring.	P .Job	Z900-
65)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	P .Job	⇒8ce-
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	Each	7500-
67)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14600-
68)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	Each	14750-
69)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.		1950-
	MAINTANANCE OF DRAIN		
69)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.		2700-
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	Р. Н	4800-
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	P. H	1300-

72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing	P. H	1050-
73)	of cuts & breaches along Branch-Drains & Sub-Drains. Hiring of Single Cabin Pick-up with POL	P. D	600e
74)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	Each	11300-
		Each	9800-
75)	Supplying of clutch plate genuine for Toyota Pick-up.	Each	12600
77)	Supplying of Pressure plate genuine for Toyota Pick-up.		7900-
78)	Supplying of Water body Genuine for Toyota Pick-up.	Each	
79)	Supplying of Shock observer set Rear genuine for Toyota Pick- up.	P. Set	23000
80)	Supplying of Shock observer set Front genuine for Toyota Pick- up.	P. Set	22200
81)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Toyota Pick-up.	P. Job	25500
82)	Supplying & Fixing of Silencer complete local for Toyota Pick- up.	Each	12700
83)	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	Each	13900-
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	P. Job	25600.
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	Each	6500-
86)	Supplying of clutch plate genuine for Suzuki Jeep.	Each	23000
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	Each	28000
88)	Supplying of Water body Genuine for Suzuki Jeep.	Each	22000
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	P. Set	7600-
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	P. Set	8600-
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	P. Job	25500
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	Each	3900
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	Each	3900-
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	P. Job	26000
\$	labor charges.		L

Contractor

(Lutfullah Phulpoto)

Executive Engineer Buildings Division Shikarpur

Member

(Ishtiaque Ahmed Khan)

Executive Engineer Shikarpur Drainage Division

Shikarpur

Chairman

(Syed Niaz Ahmed Shah)

Executive Engineer

Right Bank Tubewell Division

Ratodero

Member



OFFICE OF THE EXECUTIVE ENGINEER SHIKARPUR DRAINAGE DIVISION SHIKARPUR

NO: XEN/SDD/AB/ /2016 SHIKRPUR DATED: 21/11 /2016 Phone No: 0726-920265

To,

Mr. Muhammad Anwar Malik, Assistant Director "Assessment",

SPPRA Karachi

SUBJECT: - NIT REF: XEN/SDD/AB/SKP/605/2016 DATED: 10/10/2016 (SR. #30123)

Reference: -Your good office letter No: Mng (Assest) / SPPRA/30123/16-17/8064 Karachi.

Dated: 14/11/2016.

In compliance of reference letter pertaining to above subject matter the Para wise replay of observation / infirmities are submitted as under: -

S No:	Observation Replay of Executive Engine			
1	2	3		
01)	PA is required to furnish APP of the subject schemes for the Year-2016-17 (longer terms) as per Rule-11.	The APP is attached as per Rule-11.		
02)	PA is required to furnish notification of CRC as per Rule-31.	The notification of CRC as per Rule-31 is attached.		
03)	PA is required to furnish clipping of NIT published in English, Urdu & Sindhi languages as per Rule-17 (1A).	The clipping of newspapers as per Rule-17 is attached.		
04)	PA is required to furnish bid data sheet with relevant information duly signed by PC.	The Bid Data Sheet is attached.		
05)	PA is required to furnish quantities of items BOQ of all subject schemes to be procured.	The BOQ / Schedule is showing tentative quantities of items is attached.		
06)	In case, procurement is exceeding Rs: 10.00 Million, then PA is required to sign Integrity Pact with supplier / contractor as per Rule-89.	N/A		
07)	The contract period shall start from signing of contract instead for period from 01/07/2016 to 30/06/2016, as mentioned in bid data.	The contract period shall be started from the date of issue of work order. The period mentioned 01/07/2016 to 30/06/2016 as per financial Year-2016-17.		

This is for favour of your kind information.

Kot sla plz / 20/1

Shikarpur Drainage Division Shikarpur

ANNEXTURE-II

PROCUREMENT PLAN (NON-DEVELOPMENT) FOR THE YEAR-2015-16

	01)		A	S S
	0423-Land Reclamation, 042302-Water Logging & Salinity Control, A-13503- Drianage, A-135 Embankments & Drainage 06- Drains (433 Acutal miles) M&R.		b	Fund Head & Sub Head
GRAND TOTAL RS:	0423-Land A) Earth Work / Raising & Reclamation, Reclamation, Strengthening Of O42302-Water Logging & Salinity Control, A-13503- Drianage, A-135 Begair of Structures / Repair of Govt: Vehicles / Miscellaneous Works along Embankments & Branch Drains and Sub- Drains (433 Acutal Drains (433 Acutal miles) M&R. A) Earth Work / Raising & Repair of Clearance / Deweeding / Miscellaneous Works along Branch Drains and Sub- Drains of Lakhi, Shikarpur, System.	M&R TO DRAINS	C	Name of Work and Break Up
39848000/-	39848000	39848000	D	Allocated Funds and Break Up for Different Locations / Sites
	Repair & Maintenance		E	Items to be Executed
	Single Stage Envolape / Rate Quote Contract		Ŧ	Method of Procurement
	On availability of funds		3 0	Anticipated / Acutal Date of Advertisement
	On availability of funds		-	Anticipated / Acutal Date of Start
	30/06/2016			Anticipated / Acutal Date of Completion
			J	Remarks

ANNEXTURE-II

PROCUREMENT PLAN (NON-DEVELOPMENT) FOR THE YEAR-2015-16

		18	01	A	No:
	Logging & Salinity Control, A-13470-Others, A-134 Irrigation Works (40) Pumps (57) (3400 H.P) M&R.	Reclamation,	0423-Land	ь	Fund Head & Sub Head
Total Rs:	a) Suppling and Fixing of Electrical parts of motor control unit, repair of pumps of various discharges, rewining of electrical vertal induction motors of various H.P. supply of stores and misecliances of Ruk, Sindh Wah, Qazi Wahan Old & New Garhiyasin Pumping Stations.	ed municipal (v	A) M&D to B	7	Name of Work and Break Up
22339000	22339000	22,33,000	11111111	Locations / Sites	Allocated Funds and Break Up for Different
	Supply of Goods &		(×	1	Items to be Executed
	Single Stage Envolape / Rate Quote Contract		4	Í	Method of Procurement
	On availability of funds		ūd		Anticipated / Acutal Date of Advertisement
	On availability of funds		Ь	Start	Anticipated / Acutal Date of
	30/06/2016			Completion	Anticipated / Acutal Date of
			J		Remarks

ANNEXTURE-II

PROCUREMENT PLAN (NON-DEVELOPMENT) FOR THE YEAR-2015-16

						01)	A	No:
building.	9	Control, A-13301 Office	Togging &	042302-Water	Dad-Land	0423 I and	В	Fund Head & Sub Head
Total Rs:	A- Repair of Residentail Quarters and Mosque and SCARP Colony Shikarpur	B) Repair to Residentail Buildings	Total Rs:	Repair of Main Office Block & Sub-Divisional Office Blocks.	A)Repair to Office Buildings	A)D	C	Name of Work and Break Up
2500000	2,500,000	2,500,000	400000	400000	400000	5		Allocated Funds and Break Up for Different Locations / Sites
	Repair			Repair		e		Items to be Executed
	Contract	Single Stage Envolape /				f		Method of Procurement
	idilds	On availability of			(10		Anticipated / Acutal Date of Advertisement
	or rungs	On availability				-	Start	Anticipated / Acutal Date of
		30/06/2016					Completion	Anticipated / Acutal Date of
					_			Remarks

GOVERNMENT OF SINDH IRRIGATION DEPARTMENT

NOTIFICATION

R&S)8-110/2012-13. With the approval of competent authority, a Complaint Redressal Committee is hereby constituted in terms of Rule 31(1) of Sindh Public Procurement Rule 2010 (Amended 2013) regarding ADP schemes 2015-16 of Irrigation Department, Government of Sindh pertaining to Development-I Region Hyderabad with the following compositions

Director General Chainnah Monitoring & Evaluation Cell Litation Department, Government of Singh Chief Engineer. Member Development-II Region Hyderabad Superintending Engineer Member Development-II, Hyderabart Executive Engineer Secretar (Concerned Division) Irrigation Department District Accountant Officer Sindh Assistant Conserned Division)

T.O.R's of the Committee are as provided under Rule 31 of Sindh Public Produce head 10 and also perform any other function uncillary and indicental to the obove

> SYED ZAHEER HYDER SHAH SECRETARY TO GOVE OF SHADE

Secretar

Karachi dated the 917 October 2015 A copy is inswarded for information & necessary action to

to the Accountant General Sinch, Karachi with the request to nominate your appresentative for the above Complaint Redressal Committee.

The Director General, Monitoring & Evaluation Cell Irrigation Department accerminent of Smart, Karachi,


The KLD Sindh Public Procurement Regulatory Authority Karachi.

A. The Chief Engineer. (All) Irrigation Development, Covt. of Sindh Dev

he Surrenntending Engineer (All) Irrigation Depit Covt of South he Executive Engineer (All), Irrigation Department, Govt of Strang

7 P.S. to Secretary Impation Department, Govt or Curan statache

SECTION OFFICER (RR&\$.) For Secretary to Government of Sindi





OFFICE OF THE EXECUTIVE ENGINEER SHIKARPUR DRAINAGE DIVISION SHIKARPUR

Phone No. 0726-920265

NO. XEN/SDD/AB/SKP/605/2016 SHIKARPUR DATED: 10-10-2016

INVITATION OF BIDS FOR THE PROCUREMENT OF GOODS AND SERVICES

Sealed Bids as per SPPRA Rules-2010 (Amended-2013) are hereby invited from the interested Persons / Suppliers Contractors / Firms for the procurement of Goods and Services on rate quoted basis for the financial year 2016-17.

- 01) Bidding document of SPPRA of Goods and Services along with Lists/Schedule "B" of required Material, Goods. Hiring of Machinery and Engaging Skilled & Unskilled Labour etc. will be issued upto 28-10-2016 at 01:00 P.M. and will be received on 31-10-2016 at 02:00 R.M. and will be opened on same day i.e. 31-10-2016 at 03:00 P.M. by the Procurement Committee in presence of contractors or their authorized representatives.
- The bidding documents should be supported with lump sum Call Deposit / Bid Security of Rs. 100,000/- in favour of Executive Engineer, Shikarpur Drainage Division, Shikarpur.
- 03) The bidding document will be issued on payment of prescribed fee of Rs. 1000/- (non-refundable) paid to Executive Engineer, Shikarpur Drainage Division, Shikarpur.
- 04) No bid documents will be accepted without Earnest Money (Call Deposit).
- The rates quoted shall be remain valid and effective from 01-07-2016 to 30th June, 2017 (365 days) for the Annual Procurement of Materials, Goods, Hiring of Machinery and Engaging Skilled/Unskilled Labour etc. In case of emergency occurred in this Division the required materials etc. will be supplied by the lowest bidder on short notice as specified by the undersigned.
- 06) Conditional bids will not be entertained.
- 07) The Procuring Agency reserves the right to reject any or all the bids as per provision provided in the SPPRA Rules-2010 (Amended-2013).
- The contractor whose rates are found the lowest will be bound to supply the Material, Goods, Hiring of Machinery and engaging Skilled / Unskilled Labour etc: as and when ordered during the Financial Year-2015-16.
- The rates quoted must inclusive of all taxes of prevailing rates in voque.
- The bidders must be registered with relevant Provincial and Federal Tax authorities.
- 11) The rates should be quoted after deduction of cost of old material.

Executive Engineer Shikarpur Drainage Division Shikarpur

INF-KRY No. 3896/16 مروهروى كالفاف حمد إلى - Say No to Corruption



UNIVERSITY OF KARACHI

Tel: (021) 9926-1300-06 Ext 2215 Tel/Fax: 99261350

Ref: P.O./Hire-Fur./2016-586

Dated 13.10.2016

ENDER NOTICE

SUPPLY OF EXAMINATION TABLES. **EXAMINATION CHAIRS, TENTS, QANATS ETC.** ON HIRING BASIS FOR GRADUATE/ POSTGRADUATE DEGREE LEVEL ANNUAL EXAMINATIONS-2016

Sealed Bids are invited from Sales Tax, Services Tax & Income Tax Registered Suppliers/Service Providers for the Supply of Examination Furniture on Hiring Basis. Further detail of the Items and Terms & Conditions are contained in the Tender Documents, which are available from Purchase Department, University of Karachi from 17th OCTOBER 2016 on Payment of Rs 1,000 Each (Non-Refundable) in shape of Pay Order drawn in favour of University of Karachi Tender Documents should be dropped in the Tender Box kept in Purchase Office before 11:30 am on 2nd NOVEMBER 2016. The Bid Security Money of Rs. 1,00,000/-should be attached with the Tender Documents in shape of Pay Order drawn in favour of University of Karachi.

DESCRIPTION			
1. Examination Tables (2'x2')	4. Qanats (15'x7')		
2. Examination Chairs (Foam)	5. Pedestal Fans		
3. Tent (Shamiyana) (18'x36')	6. Water Tanki, Jug & Glass (Tumbler)		

(Note: Complete details are mentioned in the Tender Documents) TERMS & CONDITIONS:

 The Procuring Agency may reject all Bids at any time prior to the acceptance of a Bid under SPP Rules, 2010 (Amended 2013) ● The Bid Security should be attached with the Bidding Documents in shape of Pay Order drawn in favour of University of Karachi . Bids not accompanied by the Bid Security will not be considered ● Copies of the Sindh Revenue Board (SRB) Registration and NTN are to be attached with the Bidding Documents ● The Quoted Prices should be inclusive of all applicable Government Taxes and Charges ● Procurement Committee shall finalize the Bids in the light of SPP-Rules, 2010
■ The Bidders are requested to submit their Bids along with The Bidders are requested to submit their Bids along with the Bid Validity Period ● Samples of Table and Chair are to be provided with the Bids ● Prices shall be quoted in Pak Rupees ● The Method of Procurement is Open Competitive Bidding on Single Stage, One Envelope procedure ● The Bids shall be evaluated on the following: Lowest Evaluated Bid, As Per Specifications mentioned in the Bidding Documents ● The Prices to be quoted shall be filled in the Bidding Documents Prices to be quoted shall be filled in the bloding Documents mandatorily ● The Successful Bidder who refuse to or fall to execute the Contract, shall be liable to forfeiture of their Bid Security as a Penalty ● The Last Date of Issuance of Bidding Documents is 01st November 2016 at 04:00 pm. ● The Last Date of Receipt of Bidding Documents is 02nd November 2016 at 11:30 am. The Bids shall be opened on the same day at 12:00 am in presence of the Bidders who may wish to be present In case of any Holiday or Disturbance the Bids shall be received and opened on the Next Working Day as per schedule . The Tender Notice shall be also available on the Websites www.ppra.org.pk & www.pprasindh.gov.pk as well as on Procuring Agency's website www.uok.edu.pk

Purchase Officer University of Karachi



SINDH EDUCATION FOUNDATION GOVT. OF SINDH (HEAD OFFICE)

SEF (PLOT NO. 21/A, BLOCK No. 7&B, OVERSEAS COOPERATIVE HOUSING SOCIETY AMEER KHUSRO ROAD,) KARACHI, 021-34169182 & 184



TENDER NOTICE FOR HIRING OF FIRM FOR INSTITUTIONAL DOCUMENTARY WITH STILL PHOTOGRAPHY

Tender Ref SEF/NP/16-17/08

Sealed bids, addressed to the Procurement Department, Sindh Education Foundation, are invited under SPPRA rules, 2010 ame bidder must have at least 5 years of experience in same field along with turnover of Rs. 10 million per annum in Documentary Photography. The bidder

opposite nmercial would aximum still ut

son of

11-20

11-2016

11-2016

11-2016

11-2016 lope.

will be

ed from

raccept

PPRA's

tendent iatabad.

Karachi

on as

oned

Rs.)

with

on in

bids

ders

ining

tend.

ill be

with

rves

1

Phone No: 0726-920265

The invitation of bids for the procurement of Goods & Services was called by the undersigned vide No: XEN/SDD/AB/SKP/605 dated 10/10/2016.

The following changes are being made as under-

S. No.	Item	Unit	Rate
01.	Supplying of Quality copper wire of spe- cific gauge for the rewinding of Motors of 80 & 100 H.P.	P.KG	

02) The contractors whose rates are found the lowest will be bound to supply the Material Goods, Hiring of Machinery and Engaging Skilled / Unskilled Labour etc. as and when ordered during the Financial Year-2016-17.

All other terms & conditions are the same.

ہم دہشتروی کےخلاف متحدیں Say No to Corruption

Executive Engineer Shikarpur Drainage Division Shikarpur

2016.

INF-KRY No. 3971/16

confirming meeting the eligibility criteria. Eligibility criteria for applicants to qualify (at

jairiii.aunggomv.com along with a prier

minimum) are:

- a) Registered not-for-profit organization (nonreligious, non-sectarian, non-political, non-racial)
- Have continuous active roles in development sector at least of four years to inception
- Have demonstrated education projects of (more or less) same magnitude.
- Demonstrated partnership with at least two reputable national &/or international donor
- Have demonstrated stakeholders management and have exclusive (good) interaction with Govt. officials (at most of levels / tiers)
- Third party financial audits (updated reports)

Please note that rights are reserved to select or reject NGO or any proposal without assigning any reason(s). Only shortlisted pre-qualified NGOs will be contacted for any future partnership.

The EOI submission deadline is October 30, 2016. For queries please contact +92 51 2089853

SAY NO TO CORRUPTION

Government of Pakistan **Ministry of Communications**

NATIONAL HIGHWAY AUTHORITY

(Balochistan South Region)

INVITATION FOR RE-TENDERS

FOR BLACK SPOTS/HIGHWAY SAFETY IMPROVEMENT WORKS (F.Y. 2014-15) BALOCHISTAN SOUTH REGION

- 1. NHA (Balochistan-South Region @ Khuzdar) invites sealed bids (Technical & Financial) from eligible bidders, who can prove their eligibility and qualification as mentioned in the Bidding Documents for the captioned projects (Works).
- 2. The estimated cost and other briefs of projects/works against each are mentioned as below:

Contract No.	Work Description / Route / Chainage	Engineer's Estimate in Rs (M)	Adinimum DEC	Financial Thresholds Required Rs(M)
BSHS-2014-15-BS- 01 (Lasbella)	Black Spot / Highway Safety Improvement Works Under Maintenance Unit , Lasbella. From Km 122+000 to Km 166+000,(N-25)	19.576	C4	Cash Flow ≥10 Turn Over ≥15
BSHS-2014-15-85- 02 (Khuzdar)	Black Spot / Highway Safety Improvement Works Under Maintenance Unit , Khuzdar.(i) From Km 222+000 to Km 545+000, N-25 (ii) Km 000+000 to Km 035+000 , M-8	108.933	C4	Cash Flow ≥ 45 Turn Over ≥ 75

- 3. Bidding will be carried out by adopting "Single Stage Two Envelope" procedure. Bidders are required to be registered with Pakistan Engineering Council (PEC) with a valid registration Certificate in Category mentioned against each with specialization in CE-01 for the year 2016, must be licensed in a minimum Category as mentioned above. Joint Venture (JV) of maximum Two (02) firm is also admissible; however, both of the firms forming JV must be licensed in a minimum Category as mentioned above.
- 4. Bidders can download bidding documents from NHA's website (www.nha.gov.pk) or the same can be purchased from the office of Director (Maintenance) Balochistan-South, NHA-Khuzdar during working hours and working days before 09th November, 2016 on written request on firms letter head accompanied with pay order/demand draft amounting to Rs.2,000/- in favour of Road Maintenance Accounts (RMA) NHA. The bidders are advised to visit the site thoroughly before submission of bids. The eligibility criteria for pre-qualification of the prospective bidders shall be deemed as per provision of relevant clauses of the bid documents as well as NIT/IFB.
- 5. Bid security/Earnest Money @2% of Engineer's Estimate amount, in the form and validity as mentioned in the bidding documents, must be accompanied with "Technical Bid".
- Bids shall be received in the Office of Director (Maintenance) NHA Khuzdar on 09th November, 2016 at 11:30 hours, Bidders' representatives would be required to present the "Authority to Submit the Bid" while submitting the bids. The envelope containing "Technical Bid" will be opened on the same day at 12:30 hours in the presence of bidder's representatives who choose to attend. Second envelope containing "Financial Bid" of technically qualified bidder(s) will be opened later, the date of which will be communicated to the qualified bidder after evaluation of the Technical Bids.
- All prospective bidders are required to provide a Certificate from the authorized Converter of the original manufacturer of Highway Safety products, in the Technical Bid.
- 8. The firm providing unsubstantiated and / or incorrect information is liable to legal action, disqualification/termination of contract at any stage
- 9. NHA reserves the right to reject any or all bids as per the PPRA Rule no. 33(1).

GENERAL MANAGER (BALOCHISTAN-SOUTH), NHA-Complex, Main RCD Highway, Khuzdar, Tel: 0848-412300, Fax: 0848-412390, Websites: www.nha.gov.pk, www.ppra.org.pk

Bid Data Sheet

The following specific data for the goods to be procured shall complement, supplement, or amend the provisions in the Instructions to Bidders (ITB) Part One. Whenever there is a conflict, the provisions herein shall prevail over those in ITB.

[Instructions for completing the Bid Data Sheet are provided, as needed, in the notes in italics mentioned for the relevant ITB Clauses.]

	Introduction
ITB 1.1	Executive Engineer Shikarpur Drainage Division Shikarpur.
ITB 1.1	Loan or credit or Project allocation number. Loan or credit or Project allocation amount. [when applicable]
ITB 1.1	Procurement of Goods & Services.
ITB 1.1	Name of Contract. Supply of Goods / Consumable Items / Services
ITB 4.1	Executive Engineer Shikarpur Drainage Division Shikarpur.
ITB 6.1	Shikarpur Drainage Division Shikarpur. SCARP Colony College Road Shikarpur xensddshp@gmail.com.
ITB 8.1	Language of the bid. English.
	Bid Price and Currency
	The price quoted shall be delivered duty paid of all taxes applicable and after deduction of cost of old material recovered from the goods.
ITB 11.5	The price shall be fixed.
	Preparation and Submission of Bids
ITB 13.3 (d)	Not applicable
ITB 14.3 (b)	Spare parts required for Financial Years-2016-17.
ITB 15.1	Amount of bid security. Lump sum
ITB 16.1	Bid validity period. [The period should be sufficient to permit completion of the evaluation, review of the recommended selection by the Procuring agency (if so required), the obtainment of approvals, and notification of award. Normally, the validity should be ninety (90) days, however the rates will be remain effective / valid w.e.f 01/07/2016 to 30/06/2017. A realistic period should be specified in order to avoid the need for extension.]

ITB 17.1	N 1 6 :
	Number of copies. 01
ITB 18.2 (a)	Address for bid submission. Shikarpur Drainage Division Shikarpur. SCARP Colony College Road Shikarpur. xensddshp@gmail.com.
ITB 18.2 (b)	IFB title and number. Already mention in invitation of Bid.
ITB 19.1	Deadline for bid submission. Already mention in invitation of Bid.
ITB 22.1	Time, date, and place for bid opening. Already mention in invitation of Bid.
	Bid Evaluation
ITB 25.3	Criteria for bid evaluation. [Select as appropriate from criteria listed in ITB Clause 25.3 (e.g., 25.3 (b) and (c)), and in the reference under ITB 25.4 below. Retain only the evaluation method to apply and the relevant parameters corresponding to the retained criteria (e.g., 25.4 (b) (i) and (c) (ii)).]
ITB 25.4 (a) ITB 25.4 (b)	One option only. Delivery schedule. Relevant parameters in accordance with option selected:
Option (i) Option (ii) Option (iii)	adjustment expressed as a percentage, or adjustment expressed in an amount in the currency of bid evaluation, or adjustment expressed as a percentage [A rate of one-half (0.5) percent per week is a reasonable figure. The percentage of liquidated damages specified in SCC should be higher.]
ITB 25.4 (c) (ii)	Deviation in payment schedule. Annual interest rate.
ITB 25.4 (d)	Cost of spare parts.
	As per schedule B attached
ITB 25.4 (e)	Spare parts and after sales service facilities in the Procuring agency's country. [Minimum service facilities and parts inventories or reference to the Technical Specifications.]
ITB 25.4 (f)	Operating and maintenance costs.

ITB 25.4 (g)	Performance and productivity of equipment. [Specify the applicable procedure and the adjustment factor (in the currency used for bid evaluation, as applicable), as required. The adjustment factor should		
the value con	orm that shall be used and that shall either be specified in the Technical Specifications or shall be inmitted in the responsive bid with the best guaranteed performance or productivity; the uidated damages specified in the SCC shall be higher than the evaluation advantage.]		
	Details on the evaluation method or reference to the Technical Specifications.		
ITB 25.4 Alternative	Specify the evaluation factors. [The method shall be used only when a more elaborate quantification is either impractical or unjustified due to the small value of the procurement.]		
	Contract Award		
Percentage for quantity increase or decrease. [Optional clause to be used only where appropriate. Normally should not exceed fifteen (percent.]			

EXECUTIVE ENGINEER
Shikarpur Drainage Division
Shikarpur

Name of Work:

S No:	Description	Tentative Qtty:	Unit	Rate
(A) ELECTRICAL & MECHANICAL PARTS / JOB WORK OF PUMP	S		
01)	Supplying & Fixing ball Bearing 7322 B NTN for 80 & 100 HP Motor	45 Nos:	Each	
02)	Supplying & Fixing ball Bearing MU 315 NTN for 80 & 100 HP Motor	45 Nos:	Each	
03)	Supplying & Fixing top shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	45 Nos:	Each	
04)	Supplying & Fixing column shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	45 Nos:	Each	
05)	Supplying & Fixing Pump shaft (S.S) 45 mm 25 & 30 C/S Pump (Local made).	45 Nos:	Each	
06)	Supplying & Fixing Rubber lined bearing bush 25 & 30 C/S 50.2 mm dia (Local made).	45 Nos:	Each	
07)	Supplying & Fixing Spider for Pump of 25 & 30 C/S (Local made).	45 Nos:	Each	
08)	Supplying & Fixing Threaded coupling for Pump of 25 & 30 C/S (Local made).	45 Nos:	Each	
09)	Supplying & Fixing Local Impeller for Pump of 25 & 30 C/S (Local made).	45 Nos:	Each	
10)	Supplying & Fixing Top Nuts for 45 mm Shaft for Pump of 25 & 30 C/S (Local made).	45 Nos:	Each	
11)	Repair & Fixing of Stiffen Box for Pump of 25 & 30 C/S (Local made).	45 Job:	P. Job	
12)	Repair & Welding of housing for Pump of 25 & 30 C/S (Local made).	20 Job:	P. Job	
13)	Repair & Fixing of Bowel assembly upper piece for Pump of 25 & 30 C/S (Local made).	25 Job:	P. Job	
14)	Repair of Bowel assembly Intermediate piece for Pump of 25 & 30 C/S (Local made).	20 Job:	P. Job	
15)	Repair of Bowel assembly lower piece for Pump of 25 & 30 C/S (Local made).	20 Job:	P. Job	
16)	Supplying & Fixing Bio Metal relay 85 to 100 Amp.	45 Nos:	Each	
17)	Supplying & Fixing Panel switch 80 & 100 HP motor Local	45 Nos:	Each	
(8)	Supplying & Fixing Main contact set 80 & 100 HP motor Local.	45 Nos:	Each	
19)	Supplying & Fixing starter switch 80 & 100 H.P motor local.	45 Nos:	Each	
20)	Supplying & Fixing shaft protecting sleeve 45 mm dia for Pump of 25 & 30 C/S (Local made).	40 Nos:	Each	
21)	Supplying & Fixing Shaft protecting sleeve 30 mm dia for Pump of 25 & 30 C/S (Local made).	40 Nos:	Each	
22)	Supplying & Fixing Shaft protecting sleeve 55 mm dia for Pump of 25 & 30 C/S (Local made).	40 Nos:	Each	
23)	Supplying & Fixing Column Pipe 18" dia, 10' Length 8 mm dia thick Painted with epoxy for Pump of 25 & 30 C/S (Local made).	22 Rft	P. Rft	
24)	Supplying & Fixing Flange bearing 20" dia with 6 holes for the pipes of Pump of 25 & 30 C/S (Local made).	50 Nos:	Each	
25)	Supplying & Fixing stuffing box buses 45 mm for Pump of 25 & 30 C/S (Local made).	45 Nos:	Each	

* 47

	. 17		
26)	Supplying & Fixing Motor fan of 80 & 100 HP motor Local.	15 Nos:	Each
27	Supplying & Fixing Terminal carrier for the motors of 80 & 100 H.P.	20 Nos:	Each
38)	Supplying & Fixing Column pipe bushes 45 mm for Pump of 25 & 30 C/S (Local made).	30 Nos:	Each
29)	Supplying & Fixing Rubber sleeve for bowel assembly of 25 & 30 C/S discharge pump.	35 Nos:	Each
30)	Supplying & Fixing Terminal Box for 80 & 100 HP motor (assembled) Local.	25 Nos:	Each
31)	Supplying & Fixing fan cowl for 80 & 100 H.P motor Local	20 Nos:	Each
32)	Labour charges for the rewinding of electric vertical induction motor of 80 HP.	35 Job:	P. Job
33)	Labour charges for the rewinding of electric vertical induction motor of 100 HP.	35 Job:	P .Job
34)	Supplying & Fixing Air Breaker Contact set 3TB or N5 for the motor control unit of 80 & 100 HP.	60 Nos:	Each
35)	Supplying & Fixing Air Breaker magnetic Contact set 3TB or N4 for the motor control unit of 80 & 100 HP.	60 Nos:	Each
36)	Supplying & Fixing Ball bearing 6319 NTN upper for 80 & 100 H.P Electric Motor	20 Nos:	Each
37)	Supplying & Fixing Ball bearing 6315 NTN upper for 80 & 100 H.P Electric Motor	20 Nos:	Each
38)	Supplying & Fixing time relay 0 to 20 sec: for the motor control of 80 & 100 HP.	20 Nos:	Each
39)	Repair & Fixing of Circuit Breaker 200 (Amp:) for the motor control of 80 & 100 HP.	30 Jobs	P .Job
(0)	Repair & Fixing of Circuit Breaker 600 (Apm:) for the motor control of 80 & 100 HP.	25 Jobs	P. Job
11)	Repair & Fixing of Circuit Breaker 1000 (Apm:) for the motor control of 80 & 100 HP.	20 Jobs	P. Job
(2)	Repair & Fixing of delta star system of Electric Motor of 80 & 100 HP.	20 Jobs	P .Job
3)	Repair & Fixing of stuffing box 30 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	20 Jobs	P .Job
4)	Repair & Fixing of stuffing box 45 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	20 Jobs	P .Job
5)	Repair & Fixing of stuffing box 55 mm dia i/c fitting of cum seal cage (Gun metal) etc complete for the pumps of 25 & 30 C/S.	20 Jobs	P .Job
-6)	Supplying & Fixing rubber line bearing bush 70.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	30 Nos:	Each
7)	Supplying & Fixing rubber line bearing bush 75.2 mm dia for pump shaft of 25 & 30 C/S discharge pumps.	25 Nos:	Each
8)	Threading column shaft with protective sleeve 30 mm (Stainless steel) Local.	25 Nos:	Each
	Repair of impeller of pumps of 25 & 30 C/S discharge.	20 Jobs:	P .Job
0)	Supplying Fixing of stuffing box complete for the pumps of 25 & 30 C/S Discharge Local.	20 Nos:	Each
1)	Repairing & Fixing of bowl assembly piece upper of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	30 Jobs:	P .Job
2)	Repairing & Fixing of bowl assembly piece lower of 30 C/S discharge pump i/c replacement of bearing sleeve & bearing sleeve.	30 Jobs:	P .Job
3)	Repair & Fixing top shaft 30 mm dia i/c welding cutting, finishing & straightening etc complete.	35 Jobs:	P .Job

	40		
54	Repair & Fixing top shaft 45 mm dia i/c welding cutting, finishing & straightening etc complete.	20 Jobs:	P .Job
55)	Dismantling & refitting of all parts of pumps of 25 & 30 C/S discharge.	45 Jobs:	P .Job
56)	Supplying & Fixing M.S channel size 3"x7" 14 ft: long for foundation of motor		Each
57)	Repair & Refitting of High tension (HT) coil of 630 KVA transformers.	04 Jobs:	P. Job
58)	Repair & Refitting of High tension (IT) coil of 630 KVA transformers.	04 Jobs:	P .Job
59)	Repair & Refitting of High tension (HT) coil of 750 KVA transformers.	04 Jobs:	P. Job
50)	Repair & Refitting of High tension (IT) coil of 750 KVA transformers.	04 Jobs:	P .Job
51)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 200, KVA Transformer.	04 Jobs:	P .Job
52)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 630, KVA Transformer.	04 Jobs:	P .Job
53)	Supplying & Fixing LT insulator including Rod, Nut Bolts etc complete for 750, KVA Transformer.	04 Jobs:	P .Job
64)	Repair & Welding of Transformer with plate form outside including coloring.	05 Jobs:	P .Job
55)	Repair & Fixing of propeller blade i/c welding, grinding and balancing etc complete for the pumps of 25 & 30 C/S Discharge.	05 Jobs:	P .Job
66)	Supplying & Fixing Socket spider for 14" dia pipe for the pumps of 25 & 30 C/S Discharge local.	05 Nos:	Each
57)	Supplying & Fixing Socket spider for 18" dia for the pumps of 25 & 30 C/S Discharge local.	05 Nos:	Each
(8)	Supplying & Fixing Socket spider for 20" dia for the pumps of 25 & 30 C/S Discharge local.	05 Nos:	Each
9)	Supplying of Quality copper wire of specific gauge for the rewinding of Motors of 80 & 100 H.P.	2250 K.G	P. KG
(B	MAINTANANCE OF DRAIN		
59)	Hiring charges for the engaging of Wheel type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	3500 Hours	Р. Н
70)	Hiring charges for the engaging of Chain type Hydraulic excavator with POL for Earth Work, Bed Clarence, De-weeding of Branch-Drains & Sub-Drains.	3000 Hours	P. H
71)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with trolley with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	3000 Hours	Р. Н
72)	Hiring charges for the engaging of Wheel type Hydraulic Tractor with front blade with POL for the supply of Earth for the closing of cuts & breaches along Branch-Drains & Sub-Drains.	1500 Hours	Р. Н
73)	Hiring of Single Cabin Pick-up with POL	280 Days	P. D
4)	Supplying of tyre with tube size 180 / 16 for Toyota Pick-up.	4 Nos:	Each
75)	Supplying of clutch plate genuine for Toyota Pick-up.	1 Nos:	Each
77)	Supplying of Pressure plate genuine for Toyota Pick-up.	1 Nos:	Each
78)	Supplying of Water body Genuine for Toyota Pick-up.	1 Nos:	Each
0.1	A Property of the second secon	1 Set:	P. Set
	Supplying of Shock observer set Rear genuine for Toyota Pick-up.	1 Set.	
79) 80)	Supplying of Shock observer set Rear genuine for Toyota Pick-up. Supplying of Shock observer set Front genuine for Toyota Pick-up. Complete overhauling of engine including Cylinder bore, crank grinding	1 Set:	P. Set

* 49

82)	Supplying & Fixing of Silencer complete local for Toyota Pick-up.	1 Set:	Each
83	Supplying & Fixing of Diesel pump genuine for the for Toyota Pick-up.	1 No:	Each
84)	Complete denting and painting of body for Toyota Pick-up including labor charges.	1 Job:	P. Job
85)	Supplying of tyre with tube size 180 / 16 for Suzuki Jeep.	4 Nos:	Each
86)	Supplying of clutch plate genuine for Suzuki Jeep.	1 No:	Each
87)	Supplying of Pressure plate genuine for Suzuki Jeep.	1 No:	Each
88)	Supplying of Water body Genuine for Suzuki Jeep.	1 No:	Each
89)	Supplying of Shock observer set Rear genuine for Suzuki Jeep.	1 Set	P. Set
90)	Supplying of Shock observer set Front genuine for Suzuki Jeep.	1 Set	P. Set
91)	Complete overhauling of engine including Cylinder bore, crank grinding fixing of sleeve, ring set, Valves including labor charges for Suzuki Jeep.	1 Job:	P. Job
92)	Supplying & Fixing of Silencer complete local for Suzuki Jeep.	1 Job:	Each
93)	Supplying & Fixing of Fuel pump genuine for Suzuki Jeep.	1No:	Each
94)	Complete denting and painting of body for Suzuki Jeep including labor charges.	1 Job:	P. Job

Contractor