

KARACHI WATER & SEWERAGE BOARD

OFFICE OF THE CHIEF ENGINEER (IP&D)

BID EVALUATION REPORT

	me of Procuring Agency	KARACHI WATER & SEWERAGE BOARD
2	Tender Reference No	Serial No 22461 I D No. /2014
3	Tender Description/Name of Work/Item	REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANG TOWN.
d.	Method of Procurement	Single Stage (One Envelop)
5	Tender Published	Through Website
6	Total Bid Documents Sold	02 Nos
7	Total Bid Received	02 Nos
8	Technical Bid Opening Date (if applicable)	N/A
9	No. of Bid Technically Qualified (if applicable)	N/A
10	Bid (s) rejected	Nil
11	Financial Bid Opening Date	06/02/2015 instead of 05/02/2015 due to Kashmir Day
12	Big Evaluation Report	

12 Bid Evaluation Report

5#	NAME OF FIRM OR BIDDER	COST OFFERED BY THE BIDDERS	RANKING IN TERMS OF COST	COMPARISON WITH ESTIMATED COST	REASON FOR ACCEPTANCE/ REJECTION	REMARKS
,	M/s. Unity Associates	Rs 997 982/-	1st Lowest	@ 0.0033% Bekw	Substantially Responsive	P.O # 11654507 Dt:04-02-2015 Rs. 20,000/- HBL Khadija Maraket Br.
2	M/s. S.O.H.Const.Co	Rs. 1,003,142/-	2nd Lowest	@ 0.5137% Above	Substantially Responsive	P.O # AAA 12125855 Dt-04-02-2015 Rs. 21,000/- Allied Bank Paposh Nagar Br.

The all concerned bidder are being informed accordingly.

The E.E. Concerned for compliance of rule 45 of SPPRA 2010 M/s. Unity Associates, declared as the lowest responsive bidder by the Committee and recommended for Sanction from Competent Authority.

(Muhammad Khalid Khan) Accounts Officer (West) Member/Secretary

(Saif-ul-Hadue) Additional Director Internal Audit - KMC Member

(Magsood Ahmed Shaikh) Superintending Engineer (KMC) Member

Chief Engineer (West)

Member

Chief Engineer (IPD).

(Convener)

Method of Procurement:

Single Stage Single Envelope.

Name of Work:

REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN.

MINUTES OF BID OPENING MEETING.

A meeting of the procurement committee of this department was held on 06/02/2015 instead of 05/02/2015 due to Kashmir Day for opening the bids received in respect of subject NIT till deadlines of submission. The meeting was attended by all / following members of the procurement committee and the representative of bidders.

(Attendance sheet is enclosed).

- Two bidders submitted their bids till the deadline of submission.
 - M/s. Unity Associates.
 - ii. M/s. S.O.H Const Co.
- The bids were opened at 02:30 P.M in the presence of the above mentioned participants and the rates quoted by bidders were read aloud and encircled by Chairman of the Procurement Committee.

S. No	Name of Firm	Quoted Price	Amount of Bid Security	Pay Order No. / Date
01	M/s. Unity Associates	Rs. 997,982/-	Rs.20,000/-	P O # 11554507 Dt 04-02-2015 HBL Khadija Maraket Br
02	M/s. S.O.H Const Co.	Rs. 1,003,142/-	Rs.21,000/-	P.O # AAA 12125865 Dt:04-02-2015 Allied Bank Paposh Nagar Br

- The bids do not contain any over-writing or cutting.
- The committee shall examine all the bids as per the qualification / eligibility criteria provided in the bidding document and verify the documents and bid security submitted by the bidders (if required).

The meeting ended with the vote of thanks to and from the chair.

(Muhammad Khalid Khan) Accounts Officer (West)

Member / Secretary

(Saif-ul-Haque) Additional Director Internal Audit – KMC Member (Maqsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

(Abdul Rayeem Khath) Chief Engineer (West)

Member

(Abdal Kahleem Rhatti)

Chief Engineer (IPD)
Convener

Method and procedure of procurement: Open Competitive Bidding(National/International Competitive Bidding) (Single Stage - One Envelope)

Description of work: REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN.

BIDDERS' ELIGIBILITY/ QUALIFICATION REPORT

Eligibility/ Qualification Criteria:

S. No.	Eligibility / Qualification Criteria	M/s. Unity Associates	M/s. S.O.H Const
į,	Registration with PEC (if applicable)	N/A	N/A
2.	NTN	Yes	Yes
3.	Sales Tax Registration	N/A	N/A
4/2	Registration with Sindh Revenue Board (SRB)	Yes	Yes
	Qualification Criteria:		
5.	Minimum three years' experience of relevant field.	Yes	Yes
6.	Turnover of at least last three years	Yes	Yes
7.	Required Bid Security is attached.	Yes	Yes
8.	Bid is signed, named and stamped by the authorized person of the firm along with Authorization letter.	Yes	Yes
9.	Any other factor deemed to be relevant by the procuring agency subject to provision of Rule-44	N/A	N/A
to.	Qualified/ disqualified	Qualified	Qualified

Note: The procuring agency may modify the criteria as per their requirements.

(Muhammad Khalid Khan) Accounts Officer (West)

Member / Secretary

(Saif-ul-Hadue) Additional Director Internal Audit - KMC Member

(Magsood Ahmed Shaikh) Superintending Engineer (KMC)

Member

Chief Engineer (West) Member

Chief Engineer (IPD)

Convener

COMPARATIVE STATEMENT

LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN. NAME OF WORK: REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD &

63	N	1		S.No	
Execution for pipe line in trenches and pits in Soft Rock by hammering and chiseling vic trimming and dressing sides to true alignment and shapes leveling of bed of trenches to correct level and grade cutting joint holes and disposal of surplus earth with in a one chain as directed by engineering lincharge providing fence guard lights flags and temporary crossing for non vehicular traffic where ever required lift up to 5 (1.52m) and lead up to one chain (30.5m)	Execution for pipe line in trenches and pits in all kinds of soils of murum i/c trimming and dressing sides to true alignment and shapes leveling of bed of trenches to correct level and grade cutting joint holes and disposal of surplus earth with in a one chain as directed by engineering incharge providing fence guard, lights flags and temporary crossing for non vehicular traffic where ever required lift up to 5' (1.52m) and lead up to one chain (30.5m).	ocarring the existing road surface etc		Description of Work	
3600 CM	7800 CN	395 Sft	Quantity	1 2000	
10.77a.dp % o cn	4,650.00				
% o ch	% o Cn	% Sft	Unit	Engineer's Estimate	
38,772.00	36,270.00	458 83	Amount		
10 770 00	4.650 00	116.00	Rate	M/s. Unit	
92	36,270.00	458.20	Amount	M/s. Unity Associates	
10,770.00	4.650.00	11600	Rate	Constru	
03	36,270 00	458 20	Amount	M/s. S.O.H Construction & Co	



3

A

NAME OF WORK: REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN.

	on .	o.	(k)		S.No
08 dia	Providing Laying RCC Pipe with (Rubber Ring Joint & Fitting) in trench i/c cutting fitting and jointing with rubber ring i/c testing with water to specific pressure 12" dia	Full hire charges of the pumping set per day inclusive of wages of driver and assistant fuel or electric energy plate forms required for placing pumps etc. at lower depth with suction delivery at pipes for pumping out water found at various depth from trenches or the cost of erection and dismantling after completion of the job.	Execution for pipe line in trenches and pits in Hard Rock by hammering and chiseling voltrimming and shapes leveling of bed of trenches to correct level and grade cutting joint holes and disposal of surplus earth with in a one chain as directed by engineering Inchange providing fence guard lights flags and temporary crossing for non vehicular traffic where ever required lift up to 5' (1.52m) and lead up to one chain (30.5m)		Description of Work
300 Rft	700 Rft	17 Day	2850 C#	Quantity	m
206.00	367.00	1,500.00	24,150.00	Rate	Engineer's Estimate
P/Rit	P/R#	P/Day	% 0 CH	Unit	stimate
61,800.00	256,900,00	25,500 00	68,827.50	Amount	
206.00	367.00	1.500.00	24 150 00	Rate	M/s. Unity
61,800.00	256.900.00	25,500.00	68 827 50	Amount	M/s. Unity Associates
206.00	367.00	1,800,00	24,150.00	Rate	2.6
61,800.00	256,900.00	30,600.00	58 827 50	Amount	M/s. S.O.H Construction & Co



\$

The state of the s

NAME OF WORK: REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN.

:	10	φ	69	7	9	S No
Manufacturing and supplying of RCC Ring Slab of 21" dia inside 36" dia outside 7.5 width and 6" thick i/c 3/8" dia 8 Nos cross linked bars welded and two sunk type hooks coasted in 1.1 ½",3 concrete with embedded 1.5 Kg C.I. frame in perfect position i/c transportation charges for an average lead of 20 Km per trip from casting yard to Town Office (A minimum of 25 slabs per trip will be transported).	Refilling the excavated stuff in trenches 6' thick layer i/c watering removing to full compaction etc.	Sand hero on any other source sand of the same modules of the fineness (Hill Sand)	Making Connection with the existing Manholes i/c the cost of cutting holes in wall making them good in cement concrete 1:2:4 and making the required channel etc complete	Providing Manhole 4ft inside with C.I frame (15Kg) & 5ft clear depth 1:2.4 cost in situ in grithick wall 1:4:8 C.C in 6 ft dia & 6" inch thick in foundation 1:2:4 C.C in benching %" thick C.P. 1:3 motor or inside wall & surface of channel and benching making required no's of main and branches channels %'dia bars M.S foot at 12'dia C/C //C cost of excavation in all kind of soil back filling and disposal of excavated stuff etc. complete as per design & instruction of the Engineer Incharge		Description of Work
20 Nos		5428.3 Cft	70 Nos	19 Nos	Quantity	0
1,906.60	2,760.00	2.425.00	180.00	14 529 29	Rate	Engineer's Estimate
E	% o CI	% Cg	Each	Each	Unit	stimate
38,132.00	21,528.00	131,636 28	12,600.00	276,056.51	Amount	
1,906.00	2,760.00	2,425.00	180.00	14,529.00	Rate	M/s. Unity
38,120.00	21,528,00	131,636.28	12,600.00	276,051,00	Amount	M/s. Unity Associates
1,906.00	2,760.00	2,425.00	180.00	14,529.00	Rate	<u></u>
38,120,00	21,528.00	131,636,28	12,600.00	276,051.00	Amount	M/s. S.O.H Construction & Co

&

.....

)

No.

NAME OF WORK: REPLACEMENT 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06, ORANGI TOWN.

		ü	rà	9	0 20
Par	Total Quoted / Corrected Cost	Manufacturing and supplying of 21" dia RCC manhole cover cost in 1.2.4 concrete ratio 3 inch deep at centre rain forced with ½" dia tor steel bars at 4" C/C welded to 3/10" thick 2" wide MS plate two hook of 3/8" dia tor bar including compacting //c during and transportation within 10 miles.	Shifting to the site & fixing of 36'dia Ring Slab in prefect position on damaged manhole (ic cutting of manhole in damaged portion in proper shape and laying of dement mortar of 2" thickness & disposal of debris.		Description of Work
		20 Nos	20 Nos	Quantity	œ.
		913.63	563.09	Rate	Engineer's Estimate
		E	Each	Unit	stimate
998,016	998,015.52	18 272 60	11,261.80	Unit Amount	
	2	913.00	563 00	Rate	M/s. Unit
997,982	997,982.48	18.260.00	11,260.00	Amount	M/s. Unity Associates
	77	915.00	564.00	Rate	
1,003,142	1,003,141.98	18,300.00	11,280.00	Amount	Construction & Co

(Muhammad Khalid Khan) Accounts Officer (West) Member/Socretary

(Saif-ul-Hitque)
Additional Director Internal
Audit - KMC Member

(Magsood Åhmed Shaikh) Superintending Engineer (KMC) Member

May Mark

(Abdul filenta Khatti)
Chief Engineer (IPD) (Convene

Chief Engineer (Wei

ATTENDANCE OF PARTICIPATE CONTRACTOR

Name of Work : REPLACEMENT OF 8" DIA & 12" DIA DEFECTIVE SUNK DOWN SEWERAGE LINE AT MASTAN BABA MAIN ROAD & LINK ROAD & DIFFERENT LOCATION IN UC-06 ORANGI TOWN.

Date of Opening & Time: 06-01-2015

2:30 PM

Estimated Cost: 9,98,016 1-

s.NO	NAME OF FIRM	NAME OF PERSON & DESIGNATION	SIGNATURE
1	MIS. UNITY ASSOCIATES	Owais	Aut
2	M/s. S.o. H-Conta	M- Nadeen	y Shi
3	M/s.		
4			
5			
6			
7			
8			
9			
10			