

**SCHEDULE "B"**

Name of Work:- **REPAIR/REHABILITATION OF GOVERNMENT BOYS PRIMARY SCHOOL TALUKA TANDO BAGO (2013-14)@GPS HAJI DATO JAT**

S.No.	Description.	Qty.	Rate.	Unit.	Amount.
1	Dismantling Cement Concret reinforcement 1:2:4 & Finshing				
		<u>47.0</u>	5445.00	%Sft	Rs: 2559 /-
					(Rs:Five Thousand four Hundrad Forty Five)
2	Dismantling Packa brick work in cement or lime mortar(S.No.13/P-10)				
		<u>33.0</u>	1285.63	%Cft	Rs: 424 /-
					(Rs: one thousand two hundred eighty five and paisa sixty three only)
3	Dasmantling Cement Concret Plaster1:2:4(SNo 19 PNo10)				
		20.0	3327.50	%Cft	665
					(Rs: Three thousand three hundred twentyseven and paisa fifty only)
4	Removing cement plaster(S No 52 P/No-13)				
		2178	121.00	%Sft	2635
					(Rs: one hundred twenty one and paisa )
5	Pacca brick work in foundation & plinth in cement sand martor . ratio 1:6 ( S.I.NO: 4-ie/P-19 )				
		<u>60.00</u>	11948.36	%Cft	Rs: 7169 /-
					(Rs: eleven thousand nine hundred forty eight and Paisa thirty six only)
6	R.C.C. work I/c all labour and material except the cost of steel reinforcement and its labour for bending and binding which will be paid sperately. This rate also I/c all kinds of moulds lifting shuttering curing rendering and finishing the exposedsurface (I/c screening and washing of shingle)(a) R.C.work in roof slab,beams columns rafts lintels and other structural members laid in situe or precast laid in position complete in all respect(I) Ratio 1:2:4 90 lbs cement 2 Cft sand 4 Cft shingle 1/8" to 1/4" gauge.(S.I.No.6ai/P-15).				
		<u>40.00</u>	337.00	P.Cft	Rs: 13480 /-
					(Rs: three hundred thirty seven only)
7	Fabrication of mild steel reinforcement for cement concrete i/c cutting bending laying in position making joints and fastening i/c cost of binding wire (also i/c removal of rust from bars) (S.I.No:8-a/P-16).				
	a) <u>Tor Steel</u>	<u>1.96</u>	5001.70	P/Cwt	Rs: 9803 /-

S.No.	Description.	Qty.	Rate.	Unit.	Amount.
-------	--------------	------	-------	-------	---------

(Rs: five thousand one and paisa seventy only)

- b) Mild steel 0.17 4820.20 P/Cwt Rs: 819 /-  
(Rs: four thousand eight hundred twenty and paisa twenty only)
- 8 Cement concrete or stone ballast 1-1/2" to 2" gauge ratio 1:5:10.  
(S.I.No:- 4/P-14). 16.00 8694.95 %Cft Rs: 1391 /-  
(Rs: Eight thousand Six hundred Ninty for& Paisa Ninty five only)
- 9 Cement plaster 1:6 upto 12 ft height 1/2" thick. (S.I.No.13-c/P-51) 2354.00 2206.60 % Sft Rs: 51943 /-  
(Rs: two thousand two hundred six and paisa sixty only)
- 10 Cement plaster 1:4 upto 12 ft height 3/8" thick. (S.I.No.11-a/P-51) 2354.00 2197.52 %Sft Rs: 51730 /-  
(Rs: two thousand one hundred ninty seven and paisa fifty two only)
- 11 P/L CC 1:2:4 topping I/c surface finishing and dividing into  
panells (S.I.No.16/P-41) 38.0 4411.82 %Sft Rs: 1676 /-  
(Rs:For thousand For hundred & Paisa eighty five only)
- 12 M/F steel grated door with 1/16" thick sheeting I/c angle iron frame 2"x2"x3/8"&3/4"  
square bars 4" centre to centre with locking arrangement.(S.I.No. 24/P-91). 50.00 726.72 P.Sft. Rs: 36336 /-  
(Rs: seven hundred twenty six and paisa seventy two only)
- 13 Cement pointing struck joints on walls 1:2 (S.I.No.19/P-52) 1181.0 1287.44 % Sft Rs: 15205 /-  
(Rs: one thousand two hundred eighty seven & Paisa forty four only )
- 14 Colour wah two coats.(S.I.No.25/P-53) 1181.00 859.90 %Sft Rs: 10155 /-  
(Rs: eight hundred fifty nine and paisa ninty only )
- 15 White washing three coats.(S.I.No:26/P-53). 68.00 829.95 %Sft Rs: 564 /-  
(Rs: eight hundred twenty nine & Paisa ninty five only )

S.No.	Description.	Qty.	Rate.	Unit.	Amount.
16	Primary coat of chalk under distemper (S.I.No.23/P-53)				
		<u>2354.00</u>	442.75	%Sft	Rs: 10422 /-
					(Rs: four hundred forty two and paisa seventy five only)
17	Distemping three coats (S.I.No.24/P-53)				
		<u>2354.00</u>	1079.65	%Sft	Rs: 25415 /-
					(Rs: one thousand seventy nine and Ps: sixty five only)
18	Painting Old surface painting to doors and windows any type i/c edges two coats ( S.I.No.4-c/P-67)				
		<u>41.00</u>	1160.06	%Sft	Rs: 475 /-
					(Rs:Eleven thousand Fifty Nine And Pasa Fifteen only)
19	Painting new surface painting to doors and windows any type i/c edges 3 coats ( S.I.No.4-c/P-67)				
		<u>120.00</u>	2116.41	%Sft	Rs: 2116 /-
					(Rs: two thousand one hundred sixteen and paisa forty one only)
				<b>Total</b>	<b>244982</b>

**Part B (i)W/S S/fitting**

- P/F squatting type white glazed earthen ware W.C. pan with I/c cost of flushing cistern with internal fitting and flush pipe with bend and making requisite number of holes in walls plinth & floor for pipe connections & making good in cement concrete 1:2:4.  
(a) W.C. pan of not less than 19" clear opening between flushing rims and 3 gallons flushing tank (i) with 4" dia CI Thumble C.I. trape.(S.I.No.1(b-i)/P-1).
- |  |             |         |       |     |  |
|--|-------------|---------|-------|-----|--|
|  | <u>2.00</u> | 4802.60 | Each. | Rs: | 9605 /-  |
|  |             |         |       |     | (Rs: four thousand eight hundred two and paisa sixty only) |
- Providing R.C.C pipes with collars class "B" and digging the trenches to required depth and fixing in position I/c cutting fitting and jointing with maphalt composition & cement mortar 1:1 and testing with water pressure to a head of 4 feet above the top of the highest pipe & refilling with excavted stuff 4" dia R.C.C pipes class "B" (S.I.No.2-b/P-23)
- |  |              |        |       |     |  |
|--|--------------|--------|-------|-----|--|
|  | <u>36.00</u> | 146.57 | P.Rft | Rs: | 5277 /-  |
|  |              |        |       |     | (Rs: one hundred forty six and paisa fifty seven only) |
- S/F Consealed tee-stop cock of superior quality with cp head 1/2" dia (S.I. No.12-b/P-18).
- |  |             |        |      |     |  |
|--|-------------|--------|------|-----|--|
|  | <u>2.00</u> | 889.46 | P.No | Rs. | 1779 /-  |
|  |             |        |      |     | (Rs: eight hundred eighty nine and paisa forty six only) |
- Cancealed C.P fitting or superior quality for tiles Bath room (a) S.F concealed bib cock of superior quality with C.P head 1/2" dia (S.I.No.13-a/ P-19).

